




General information

| | |
|---------------------|-------------------|
| Make | JAGUAR |
| Model | XJ D V6 LUXURY |
| Colour | Grey |
| Year of manufacture | 2010 |
| Top speed | 155 mph |
| 0 - 60 mph | 6.4 seconds |
| Gearbox | 6 speed automatic |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 275 BHP |
| Max. torque | 600 Nm at 2.000 rpm |
| Engine capacity | 2.993 cc |
| Cylinders | 6 |
| Fuel type | Diesel |
| Consumption city | 29.4 mpg |
| Consumption extra urban | 50.4 mpg |
| Consumption combined | 40.4 mpg |
| CO2 emission | 184 g/km |
| CO2 label | I |





Internet history

Entry 2

| | |
|---------------|-----------------------------|
| Date | 2021-07-20 |
| Pictures | 34 |
| Listing price | View report |



source: [autotrader.co.uk](#)

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-01-31 |
| Pictures | 1 |
| Listing price | View report |



source: [autoonline.co.uk](#)



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2024-07-27 |
| MOT pass rate | 72 % |
| MOT passed | 13 |
| Failed MOT tests | 5 |
| Total advice items | 35 |
| Total items failed | 11 |

MOT #18 2023-07-28 13:59

MOT test number 827528905903

Result ✓ Passed

Next expiry date 2024-07-27

- Advice** Brake hose has slight corrosion to ferrule both rear (1.1.12 (f) (i))
- Advice** Suspension component corroded but not seriously weakened rear suspension brace (5.3.3 (b) (i))
- Advice** Brake disc worn, pitted or scored, but not seriously weakened both front (inner faces) (1.1.14 (a) (ii))

MOT #17 2023-07-27 15:23

MOT test number 641592114832

Result ✗ Failed

- Advice** Brake disc worn, pitted or scored, but not seriously weakened both front (inner faces) (1.1.14 (a) (ii))
- Advice** Suspension component corroded but not seriously weakened rear suspension brace (5.3.3 (b) (i))
- Fail** Registration plate lamp inoperative in the case of a single lamp or all lamps both (4.7.1 (b) (ii))
- Fail** Road wheel fixing missing 1 on each wheel (5.2.1 (a) (i))
- Fail** Windscreen washer not working (3.5 (a))
- Advice** Brake hose has slight corrosion to ferrule both rear (1.1.12 (f) (i))

**MOT #16**

2022-07-22 15:34

MOT test number

804660201287

Result

✓ Passed

Advice

Offside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

MOT #15

2021-07-22 13:48

MOT test number

938773630710

Result

✓ Passed

MOT #14

2021-06-25 11:25

MOT test number

140209361718

Result

✓ Passed

Advice

Offside Rear Tyre worn close to legal limit/worn on edge ON LEGAL LIMIT OF 1.6MM (5.2.3 (e))

Minor

Power steering fluid level below minimum (2.1.5 (b) (i))

Advice

Offside Front Tyre worn close to legal limit/worn on edge 2mm worn inner (5.2.3 (e))

Advice

Nearside Front Outer Tyre slightly damaged (5.2.3 (d) (ii))

Advice

Power steering component has slight seepage from a component around power steering bottle (2.1.5 (a))

Advice

Nearside Rear Outer Tyre slightly damaged (5.2.3 (d) (ii))

Minor

Offside Front Windscreen wiper blade defective (3.4 (b) (i))

Advice

Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice

Nearside Front Tyre worn close to legal limit/worn on edge 2mm worn inner edge (5.2.3 (e))

**MOT #13**

2021-06-25 11:25

MOT test number

611559549856

Result**✗ Failed**

- Advice** Nearside Front Outer Tyre slightly damaged (5.2.3 (d) (ii))
- Minor** Power steering fluid level below minimum (2.1.5 (b) (i))
- Advice** Nearside Rear Outer Tyre slightly damaged (5.2.3 (d) (ii))
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Pass with rectification** Windscreen washer not working (3.5 (a))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge 2mm worn inner edge (5.2.3 (e))
- Minor** Offside Front Windscreen wiper blade defective (3.4 (b) (i))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge ON LEGAL LIMIT OF 1.6MM (5.2.3 (e))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge 2mm worn inner (5.2.3 (e))
- Advice** Power steering component has slight seepage from a component around power steering bottle (2.1.5 (a))

MOT #12

2020-02-08 13:23

MOT test number

412347687110

Result**✓ Passed**

- Advice** Rear Brake pad(s) wearing thin close to legal limit 2.0mm (1.1.13 (a) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge worn to 3.0mm,low on inner edge (5.2.3 (e))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge 2.0mm (5.2.3 (e))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge worn to 3.0mm,low on inner edge (5.2.3 (e))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #11** 2018-12-21 12:17**MOT test number** 350517820104**Result** ✓ Passed**MOT #10** 2018-06-01 11:20**MOT test number** 542114532650**Result** ✓ Passed**MOT #9** 2017-05-31 13:18**MOT test number** 639274088788**Result** ✓ Passed**MOT #8** 2016-05-31 15:56**MOT test number** 182728623645**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Advice** Offside Front door damaged**MOT #7** 2016-05-31 12:28**MOT test number** 990603247329**Result** ✗ Failed**Fail** Offside Front Inner Tyre tread depth below requirements of 1.6mm to cord (4.1.E.1)**Advice** Offside Front door damaged**Fail** Nearside Front Inner Tyre tread depth below requirements of 1.6mm under 3/4 tread allowance (4.1.E.1)**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**MOT #6** 2015-05-29 12:32**MOT test number** 137359645120**Result** ✓ Passed

**MOT #5** 2015-05-29 11:21**MOT test number** 969449145168**Result** ✗ Failed

- Fail** Offside Front Headlamp aim too high (1.8)
- Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

MOT #4 2014-05-29 14:56**MOT test number** 129689544134**Result** ✓ Passed**MOT #3** 2014-05-29 11:04**MOT test number** 217039444446**Result** ✗ Failed

- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

MOT #2 2013-06-18 12:02**MOT test number** 156829263127**Result** ✓ Passed**MOT #1** 2013-03-12 12:49**MOT test number** 407541873045**Result** ✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 August 2024

✓
MOT

Expires:
27 July 2024

| | |
|------------------|---------------------------------|
| Tax status | Valid until 1 August |
| Days left | 95 |
| MOT expiry date | 27 July 2024 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|---|------------|
| Vehicle class | 49 |
| Band | I |
| Single payment (12 months) | £ 320,00,- |
| Single six month payment | £ 176,00,- |
| Total payable by 12 monthly instalments | £ 336,00,- |



Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report [here](#) for the results.

| | |
|----------|--|
| Damage 1 | |
| Date | |
| Category | |
| Type | |
| Damage 2 | |
| Date | |
| Category | |
| Type | |



Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 10,000 |
| Auction value | £ 10,000 |
| Average private trade value | £ 10,000 |

More info >



Owner history

For how long did the current and previous owner(s) have this JAGUAR? How many owners did this JAGUAR have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | | |
|-------|------|----|
| Owner | From | To |
| Owner | From | To |
| Owner | From | To |
| Owner | From | To |
| Owner | From | To |
| Owner | From | To |
| Owner | From | To |

More info >

Plate changes

See in this check if this JAGUAR had different number plates.

| | |
|----------------------|---------------|
| Number of plates | 1 |
| Current registration | XXXXXX |
| Plate since | 2024-03-28 |
| Current registration | XXXXXX |
| Plate since | 2024-03-28 |

More info >



Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled.

If not, and you buy this JAGUAR then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this JAGUAR is financed.

| | | |
|-------------------|------------|------|
| Finance company | XXXXXXXXXX | XXXX |
| Date of agreement | XXXXXXXXXX | XXXX |
| Agreement type | XXXXXXXXXX | XXXX |
| Agreement term | XXXXXXXXXX | XXXX |
| Agreement number | XXXXXXXXXX | XXXX |
| Contact info | XXXXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 21 |
| First mileage registration | 2010-06-21 |
| Last registration | 2023-07-28 |
| Complete history | See info |



| | | |
|------------------|------------|------------|
| Registration #1 | 2010-06-21 | 14 mi |
| Registration #2 | 2013-03-12 | 11.967 mi |
| Registration #3 | 2013-06-18 | 15.510 mi |
| Registration #4 | 2014-05-29 | 26.775 mi |
| Registration #5 | 2014-05-29 | 26.775 mi |
| Registration #6 | 2015-05-29 | 39.557 mi |
| Registration #7 | 2015-05-29 | 39.558 mi |
| Registration #8 | 2016-05-31 | 51.397 mi |
| Registration #9 | 2016-05-31 | 51.400 mi |
| Registration #10 | 2017-05-31 | 61.865 mi |
| Registration #11 | 2018-06-01 | 71.292 mi |
| Registration #12 | 2019-06-01 | 81.719 mi |
| Registration #13 | 2020-06-01 | 92.146 mi |
| Registration #14 | 2021-06-01 | 102.573 mi |
| Registration #15 | 2022-06-01 | 112.999 mi |
| Registration #16 | 2023-06-01 | 123.426 mi |
| Registration #17 | 2024-06-01 | 133.853 mi |
| Registration #18 | 2025-06-01 | 144.280 mi |
| Registration #19 | 2026-06-01 | 154.707 mi |
| Registration #20 | 2027-06-01 | 165.134 mi |
| Registration #21 | 2028-06-01 | 175.561 mi |

More info >



Dimensions & weight

| | |
|---------------------|---------|
| Width | 2110 mm |
| Height | 1448 mm |
| Length | 5122 mm |
| Wheel base | 3157 mm |
| Kerb weight | 1796 kg |
| Max. allowed weight | 2365 kg |

Additional information

| | |
|--------------------|------------------|
| Fuel tank capacity | 83 l |
| Fuel delivery | Direct Injection |
| Number of doors | 4 |
| Number of seats | 5 |
| Number of axles | 2 |
| Engine number | 0502641306DT |