





report date: 2024-03-29

General information

| Make | RENAULT |
|---------------------|-------------------|
| ויומגכ | NLIMOLI |
| Model | ZOE DYNAMIQUE ZEN |
| Colour | Blue |
| Year of manufacture | 2013 |
| Top speed | 84 mph |
| 0 - 60 mph | 13.5 seconds |
| Gearbox | 1 speed automatic |

Engine & fuel consumption

| Power | 87 BHP |
|-------------|---------------------|
| Max. torque | 220 Nm at 2.500 rpm |
| Fuel type | Electricity |



CarCheck.co.uk page 1/13



report date: 2024-03-29

Internet history

Entry 1

Date 2021-06-03

Pictures 33

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-29

MOT history

| MOT expiry date | 2024-06-21 |
|--------------------|------------|
| MOT pass rate | 69 % |
| MOT passed | 9 |
| Failed MOT tests | 4 |
| Total advice items | 23 |
| Total items failed | 0 |

| MOT #13 | 2023-06-14 11:01 |
|--|------------------|
| MOT test number | 215540712243 |
| Result | ✓ Passed |
| Next expiry date | 2024-06-21 |
| Advice Nearside Front Inner Tyre worn close to legal limit/worn on edge worn on edge (5.2.3 (e)) | |

| MOT #12 | 2023-06-12 08:11 | |
|--|------------------|--|
| MOT test number | 304683545110 | |
| Result | X Failed | |
| Advice Nearside Front Inner Tyre worn close to legal limit/worn on edge worn on edge (5.2.3 (e)) | | |
| Minor Front Tyre obviously under inflated (5.2.3 (I)) | | |
| DANGEROUS Offside Front Inner Tyre has ply or cords exposed (5.2.3 (d) (ii)) | | |

| MOT #11 | 2022-06-14 15:05 |
|--|------------------|
| MOT test number | 906765151985 |
| Result | ✓ Passed |
| Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt Advice Offside Front Inner Tyre worn close to legal limit/worn on edge worn on edge | e (5.2.3 (e)) |

CarCheck.co.uk page 3/13



report date: 2024-03-29

MOT test number

Result

MAJOR

Windscreen washer not working unable to check wiper blades (3.5 (a))

Advice

Nearside Rear Child Seat fitted not allowing full inspection of adult belt

Advice

Offside Front Inner Tyre worn close to legal limit/worn on edge worn on edge (5.2.3 (e))

MOT #9

MOT test number

537384354101

Result

✓ Passed

MOT test number

Result

Advice Nearside Front tyre has slightly worn on outer edge

Advice Front Shock absorbers Slight external corroded to both casing

MOT #7

MOT test number

137922347752

Result

✓ Passed

MOT #6 2018-12-18 12:58

MOT test number 898784353713

Result ✓ Passed

CarCheck.co.uk page 4/13



report date: 2024-03-29

MOT #5

MOT test number

Result

Advice Nearside front tyre wearing low on tread

Advice Nearside rear tyre bold on outer edge

MAJOR Reversing lamp inoperative (4.6.1 (a))

MOT #4

MOT test number

Result

Advice

Under trays preventing a full inspection

2018-09-11 13:19

426625591699

✓ Passed

MOT #3 2018-09-11 09:50
MOT test number 203247352772

Result × Failed

Advice Under trays preventing a full inspection

MAJOR Offside Front Service brake excessively fluctuating (1.2.1 (e))

DANGEROUS Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MAJOR Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

MAJOR Nearside Front Service brake excessively fluctuating (1.2.1 (e))

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MAJOR Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))

MOT #2 2017-09-19 14:45

MOT test number 990662945064

Result \(\sqrt{Passed} \)

Advice Nearside Front Tyre worn close to the legal limit Worn on outer edge (4.1.E.1)

CarCheck.co.uk page 5/13



MOT #1

SP63MLN

report date: 2024-03-29

2016-09-16 10:55

MOT test number 152819246008

Result ✓ Passed

CarCheck.co.uk page 6/13



report date: 2024-03-29

Tax & MOT check



MOT expiry date 21 June 2024

Full MOT history See MOT history

CarCheck.co.uk page 7/13



report date: 2024-03-29

Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-29

Owner history

| • | |
|--|-------------|
| For how long did the current and previous owner(s) have this RENAULT? How many owner have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations. | |
| | |
| HARMAN CO. C. | |
| | |
| *************************************** | |
| | |
| THE PARTY OF THE P | |
| *************************************** | |
| *************************************** | |
| | |
| | More info > |
| | |
| Plate changes | |
| | |
| See in this check if this RENAULT had different number plates. | |
| | |
| Number of plates | , |
| | |
| Current registration | UK UK |
| Plate since | |
| | |
| Current registration | UK NE |
| Finds since | |
| | |
| | More info > |
| | , , , |

CarCheck.co.uk page 10/13



report date: 2024-03-29

Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this RENAULT is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| | |

Contact info

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-29

Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 15 |
| First mileage registration | 2013-10-17 |
| Last registration | 2023-06-14 |
| Complete history | See info |



| Registration #1 | 2013-10-17 | 11 mi |
|------------------|------------|-----------|
| Registration #2 | 2016-09-16 | 19.290 mi |
| Registration #3 | 2017-09-19 | 31.301 mi |
| Registration #4 | 2018-09-11 | 38.743 mi |
| Registration #5 | 2018-09-11 | 38.744 mi |
| Registration #6 | 2018-12-12 | 39.662 mi |
| Registration #7 | 2018-12-18 | 39.664 mi |
| Registration #8 | 2019-12-19 | 45.495 mi |
| Registration #9 | | 11.777 es |
| Registration #10 | | 11.777 es |
| Registration #11 | | 91.777 es |
| Registration #12 | | 11.777 es |
| Registration #13 | | 91.777 es |
| Registration #14 | | 11.777 es |
| Registration #15 | | |

More info >

CarCheck.co.uk page 12/13



report date: 2024-03-29

Car features

| S0225 | Air conditionin |
|-------|-----------------|
| 50295 | |
| 50482 | |
| 50501 | |
| 50566 | |
| 60567 | |
| 50569 | |

Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 89% |
| Children | 80% |
| Pedestrian | 66% |
| Safety systems | 85% |
| Overall rating | 82% |
| Video | see crash video |



Dimensions & weight

| Width | 1730 mm |
|---------------------|---------|
| Height | 1562 mm |
| Length | 4084 mm |
| Wheel base | 2588 mm |
| Kerb weight | 1468 kg |
| Max. allowed weight | 1943 kg |

Additional information

| Fuel delivery | Not Applicable |
|-----------------------------------|----------------|
| Number of doors | 5 |
| Number of seats | 5 |
| Number of axles Carcheck.co.uk | 2 page 13/13 |