



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	BEETLE LUNA 16V
Colour	Silver
Year of manufacture	2006
Top speed	100 mph
0 - 60 mph	14.6 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	75 BHP
Max. torque	126 Nm at 3.300 rpm
Engine capacity	1.390 cc
Cylinders	4
Fuel type	Petrol
Consumption city	30.1 mpg
Consumption extra urban	48.7 mpg
Consumption combined	39.8 mpg
CO2 emission	170 g/km
CO2 label	H





Internet history

Entry 1

Date	2021-07-09
Pictures	33
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2022-10-12
MOT pass rate	87 %
MOT passed	13
Failed MOT tests	2
Total advice items	23
Total items failed	5

MOT #15	2021-10-13 15:44
MOT test number	727498324152
Result	✓ Passed
Next expiry date	2022-10-12

MOT #14	2020-09-30 13:30
MOT test number	216340994570
Result	✓ Passed
Advice	Front Inner Brake disc worn, pitted or scored, but not seriously weakened x 2 brake discs (1.1.14 (a) (ii))

MOT #13	2019-03-23 09:17
MOT test number	289126754820
Result	✓ Passed
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened Both sides (1.1.14 (a) (ii))
Advice	Rear Brake pad(s) wearing thin Both sides (1.1.13 (a) (ii))
Minor	Nearside Windscreen wiper blade defective (3.4 (b) (i))
Advice	Front Brake pad(s) wearing thin Both sides (1.1.13 (a) (ii))

MOT #12	2018-04-05 08:34
MOT test number	484070657966
Result	✓ Passed

**MOT #11**

2018-04-03 09:05

MOT test number

685686302576

Result**✗ Failed****Advice** Washer bottle leaking**Fail** Offside Front suspension has excessive movement at a wishbone pin or bush wishbone rear bush (2.5.A.1c)**Fail** Nearside Front passenger door cannot be opened from inside the vehicle (6.2.B.1b)**Fail** Offside Track rod end ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.2.C.1c)**MOT #10**

2017-04-05 15:58

MOT test number

676734022090

Result**✓ Passed****Advice** Offside Front suspension has slight movement at a wishbone pin or bush (2.5.A.1c)**Advice** High level brake light not working**MOT #9**

2016-03-05 09:51

MOT test number

225329678572

Result**✓ Passed****Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Front suspension has slight movement at a wishbone pin or bush (2.5.A.1c)**Advice** Nearside Front Upper Macpherson strut has slight movement at the upper attachment (2.5.A.1c)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Front suspension has slight movement at a wishbone pin or bush (2.5.A.1c)

**MOT #8** 2015-03-07 10:11**MOT test number** 799806165023**Result** ✓ Passed

- Advice** Offside Front Obligatory mirror damaged, but not seriously affecting the rear view (8.1.2a)
- Advice** Offside Front Lower Ball joint dust cover damaged, but preventing the ingress of dirt (2.2.C.1c)
- Advice** Rear Exhaust has a minor leak of exhaust gases (7.1.2)

MOT #7 2014-03-08 13:03**MOT test number** 177967164455**Result** ✓ Passed

- Advice** Nearside Rear Front suspension has slight movement at a wishbone pin or bush (2.5.A.1c)
- Advice** Nearside Rear coil spring corroded (2.4.C.1b)
- Advice** Offside Rear Front suspension has slight movement at a wishbone pin or bush (2.5.A.1c)
- Advice** Rear Exhaust has a minor leak of exhaust gases (7.1.2)

MOT #6 2013-03-09 09:26**MOT test number** 727828263078**Result** ✓ Passed**MOT #5** 2013-03-09 09:26**MOT test number** 126968163462**Result** ✗ Failed

- Pass with rectification** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Pass with rectification** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)



MOT #4	2012-04-16 14:09
---------------	------------------

MOT test number	819197702178
------------------------	--------------

Result	✓ Passed
---------------	----------

Advice	Nearside Rear Suspension arm has slight play in a pin/bush (2.4.G.2)
---------------	--

Advice	Exhaust has a minor leak of exhaust gases (7.1.2)
---------------	---

MOT #3	2011-04-07 12:49
---------------	------------------

MOT test number	569527591074
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #2	2010-03-27 11:23
---------------	------------------

MOT test number	920166780003
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #1	2009-03-19 15:43
---------------	------------------

MOT test number	281288679010
------------------------	--------------

Result	✓ Passed
---------------	----------



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 ML06HJC
Plate since	2024-03-29
Current registration	 ML06HJC
Plate since	2024-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2006-03-31
Last registration	2021-10-13
Complete history	See info



Registration #1	2006-03-31	26 mi
Registration #2	2009-03-19	22.015 mi
Registration #3	2010-03-27	28.597 mi
Registration #4	2011-04-07	36.244 mi
Registration #5	2012-04-16	43.945 mi
Registration #6	2013-03-09	49.426 mi
Registration #7	2014-03-08	55.259 mi
Registration #8	2015-03-07	61.697 mi
Registration #9	2016-03-07	68.135 mi
Registration #10	2017-03-07	74.573 mi
Registration #11	2018-03-07	81.011 mi
Registration #12	2019-03-07	87.449 mi
Registration #13	2020-03-07	93.887 mi
Registration #14	2021-03-07	100.325 mi
Registration #15	2022-03-07	106.763 mi
Registration #16	2023-03-07	113.201 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1724 mm
Height	1502 mm
Length	4081 mm
Wheel base	2515 mm
Kerb weight	1285 kg
Max. allowed weight	1650 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	3

Number of seats	4
Number of axles	2
Engine number	BCA 463754