



report date: 2024-03-29

General information

Make	VOLVO
Model	S60 D3 SE LUX
Colour	Blue
Year of manufacture	2011
Top speed	127 mph
0 - 60 mph	9.1 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	148 BHP
Max. torque	350 Nm at 2.750 rpm
Engine capacity	1.984 cc
Cylinders	5
Fuel type	Diesel
Consumption city	35.8 mpg
Consumption extra urban	61.4 mpg
Consumption combined	48.7 mpg
CO2 emission	154 g/km
CO2 label	G






Internet history

Entry 1

Date	2021-02-06
Pictures	10
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2024-06-08
MOT pass rate	91 %
MOT passed	10
Failed MOT tests	1
Total advice items	13
Total items failed	1

MOT #11	2023-06-09 13:04
MOT test number	952569342195
Result	✓ Passed
Next expiry date	2024-06-08

MOT #10	2023-06-08 08:19
MOT test number	783361236957
Result	✗ Failed
Fail	Offside Front Tyre has ply or cords exposed 215/50/17 (5.2.3 (d) (ii))
Advice	Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Offside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #9	2022-06-09 14:15
MOT test number	847390597417
Result	✓ Passed

**MOT #8** 2021-06-09 08:38**MOT test number** 675768510296**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #7** 2020-09-18 14:19**MOT test number** 555012684127**Result** ✓ Passed**MOT #6** 2019-10-15 15:34**MOT test number** 925020691004**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Under-body panels fitted**MOT #5** 2018-06-21 11:24**MOT test number** 198765702164**Result** ✓ Passed**Advice** Nearside Front Brake pad(s) wearing thin very low (1.1.13 (a) (ii))**Advice** Nearside Front tyre outer sidewall has a cut.not exposing cords**Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #4** 2017-06-28 10:38**MOT test number** 851363442767**Result** ✓ Passed**Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)



MOT #3	2016-06-27 10:27
MOT test number	340350957956
Result	✓ Passed
Advice	Front registration plate deteriorated but not likely to be misread (6.3.1d)

MOT #2	2015-06-25 14:16
MOT test number	378436775189
Result	✓ Passed

MOT #1	2014-06-27 10:42
MOT test number	105218374155
Result	✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 June 2024

✓
MOT

Expires:
8 June 2024

Tax status	Valid until 1 June
Days left	32
MOT expiry date	8 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2011-06-30
Last registration	2023-06-09
Complete history	See info



Registration #1	2011-06-30	7 mi
Registration #2	2014-06-27	19.903 mi
Registration #3	2015-06-25	25.793 mi
Registration #4	2016-06-27	32.100 mi
Registration #5	2017-06-28	38.192 mi
Registration #6	2018-06-21	43.688 mi
Registration #7	2019-10-15	45.852 mi
Registration #8	2020-06-22	46.277 mi
Registration #9	2021-06-22	46.277 mi
Registration #10	2022-06-22	46.277 mi
Registration #11	2023-06-09	46.277 mi
Registration #12	2023-06-09	46.277 mi
Registration #13	2023-06-09	46.277 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1457 mm
Length	4522 mm
Wheel base	2640 mm
Kerb weight	1561 kg
Max. allowed weight	2020 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Engine number	1026084
---------------	---------