



report date: 2024-03-29

General information

Make	VAUXHALL
Model	ASTRA SRI
Colour	Black
Year of manufacture	2018
Top speed	134 mph
0 - 60 mph	7.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	148 BHP
Max. torque	245 Nm at 2.000 rpm
Engine capacity	1.399 cc
Cylinders	4
Fuel type	Petrol
Consumption city	38.7 mpg
Consumption extra urban	62.8 mpg
Consumption combined	51.4 mpg
CO2 emission	128 g/km
CO2 label	D





Internet history

Entry 2

Date	2021-07-03
Pictures	34
Listing price	View report



source: [heycar.co.uk](#)

Entry 1

Date	2021-06-17
Pictures	10
Listing price	View report



source: [autoonline.co.uk](#)



MOT history

MOT expiry date	2025-05-10
MOT pass rate	80 %
MOT passed	4
Failed MOT tests	1
Total advice items	18
Total items failed	1

MOT #5	2024-04-27 12:09
MOT test number	765306256671
Result	✓ Passed
Next expiry date	2025-05-10
Advice	Front Brake disc worn, but not excessively (1.1.14 (a) (i))
Advice	Nearside Rear Nail in tyre

MOT #4	2023-05-05 09:20
MOT test number	434860856857
Result	✓ Passed
Advice	Offside Rear shock absorber dust cover damaged
Advice	Offside Front Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e))
Minor	Front Obligatory mirror slightly loose interior mirror (3.3 (b) (i))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing 225/4517 (5.2.3 (d) (ii))
Advice	Front Items removed from driver's view prior to test air freshener on interior mirror

**MOT #3**

2023-05-04 09:57

MOT test number

786911411222

Result**✗ Failed****Advice** Front Items removed from driver's view prior to test air freshener on interior mirror**Fail** Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))**Advice** Offside Rear shock absorber dust cover damaged**Minor** Front Obligatory mirror slightly loose interior mirror (3.3 (b) (i))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing 225/4517 (5.2.3 (d) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e))**MOT #2**

2022-04-30 09:48

MOT test number

834505059832

Result**✓ Passed****Advice** Offside Front Tyre slightly damaged/cracking or perishing cracking and perishing 225 45 17 (5.2.3 (d) (ii))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing cracking and perishing 225 45 17 (5.2.3 (d) (ii))**Advice** Offside Rear Tyre slightly damaged out of shape 225 45 17 (5.2.3 (d) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge 2mm wearing on edges 225 45 17 (5.2.3 (e))**Advice** Nearside Front Inner Tyre has a cut but not deep enough to reach the ply or cords sidewall 225 45 17 (5.2.3 (d) (i))**Advice** Nearside Rear Tyre slightly damaged out of shape 225 45 17 (5.2.3 (d) (ii))**MOT #1**

2021-04-12 10:50

MOT test number

909294657021

Result**✓ Passed**



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
10 May 2025

Tax status	Valid until 1 July
Days left	62
MOT expiry date	10 May 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
First licence fee (12 months)	£ 210,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 AK18MEV
Plate since	2019-03-29
Current registration	 AK18MEV
Plate since	2019-03-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2018-05-11
Last registration	2024-04-27
Complete history	See info



Registration #1	2018-05-11	21 mi
Registration #2	2021-04-12	14.281 mi
Registration #3	2022-05-20	25.277 mi
Registration #4	2023-05-20	25.277 mi
Registration #5	2023-05-20	25.277 mi
Registration #6	2023-05-20	25.277 mi
Registration #7	2023-05-20	25.277 mi
Registration #8	2024-04-27	25.277 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	86%
Children	84%
Pedestrian	83%
Safety systems	75%
Overall rating	83%
Video	see crash video



Dimensions & weight

Width	2042 mm
Height	1485 mm
Length	4370 mm
Wheel base	2662 mm
Kerb weight	1203 kg
Max. allowed weight	1820 kg

Additional information

Fuel tank capacity	48 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	B1180098HA5X0280LE2