



RENAULT

RV54HF0

report date: 2024-03-29

General information

Make	RENAULT
Model	SCENIC EXPRESSION VVT 111 SCENIC EU4
Colour	Green
Year of manufacture	2004
Top speed	107 mph
0 - 60 mph	12.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	110 BHP
Max. torque	150 Nm at 4.250 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	30.4 mpg
Consumption extra urban	47.1 mpg
Consumption combined	39.2 mpg
CO2 emission	172 g/km
CO2 label	H






Internet history

Entry 1

Date	2021-06-26
Pictures	22
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-07-19
MOT pass rate	81 %
MOT passed	17
Failed MOT tests	4
Total advice items	38
Total items failed	5

MOT #21	2023-07-17 08:39
MOT test number	874285513300
Result	✓ Passed
Next expiry date	2024-07-19
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Exhaust has a minor leak of exhaust gases (6.1.2 (a))

MOT #20	2022-07-06 10:17
MOT test number	428068601733
Result	✓ Passed

MOT #19	2021-06-21 11:37
MOT test number	237752058799
Result	✓ Passed

MOT #18	2020-07-20 08:18
MOT test number	404309040707
Result	✓ Passed
Advice	O/s headlight fading
Advice	Surfacecorrosion rear axle
Advice	Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**MOT #17** 2019-07-09 11:46**MOT test number** 705647972199**Result** ✓ Passed**MOT #16** 2019-07-08 11:18**MOT test number** 675203565188**Result** ✗ Failed**Fail** Offside Headlamp levelling device inoperative (4.1.5 (a))**MOT #15** 2018-07-18 13:36**MOT test number** 790080270805**Result** ✓ Passed**MOT #14** 2018-07-17 10:48**MOT test number** 813493349365**Result** ✗ Failed**Fail** Offside Stop lamp(s) all not working (4.3.1 (a) (iii))**Fail** Offside Front Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**MOT #13** 2017-07-04 11:04**MOT test number** 228919189939**Result** ✓ Passed**Advice** Offside Front Brake pipe slightly corroded (3.6.B.2c)**Advice** Offside Rear Tyre worn close to the legal limit and slightly perished (4.1.E.1)**Advice** Rear Shock absorber has slight corrosion to the casing both (2.7.2a)**Advice** Offside Headlamp deteriorated but light output not reduced (1.7.5a)**Advice** Offside Rear slight bind to brake

**MOT #12**

2016-07-22 10:16

MOT test number

686935622508

Result

✓ Passed

- Advice** Nearside Front Shock absorber has slight corrosion to the casing (2.7.2a)
- Advice** Exhaust tailpipe slightly corroded
- Advice** Offside Rear Shock absorber has slight corrosion to the casing (2.7.2a)
- Advice** Offside Rear coil spring corroded (2.4.C.1b)
- Advice** Engine covers and under trays fitted, obscuring view of some components
- Advice** Offside Front Shock absorber has slight corrosion to the casing (2.7.2a)
- Advice** Nearside Rear Shock absorber has slight corrosion to the casing (2.7.2a)

MOT #11

2016-07-18 11:04

MOT test number

147902684021

Result

✗ Failed

- Advice** Nearside Rear Shock absorber has slight corrosion to the casing (2.7.2a)
- Advice** Exhaust tailpipe slightly corroded
- Fail** Nearside Rear coil spring broken (2.4.C.1a)
- Advice** Nearside Front Shock absorber has slight corrosion to the casing (2.7.2a)
- Advice** Offside Rear Shock absorber has slight corrosion to the casing (2.7.2a)
- Advice** Engine covers and under trays fitted, obscuring view of some components
- Advice** Offside Rear coil spring corroded (2.4.C.1b)
- Advice** Offside Front Shock absorber has slight corrosion to the casing (2.7.2a)

**MOT #10** 2015-07-03 10:58**MOT test number** 207974885156**Result** ✓ Passed**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)**MOT #9** 2014-07-04 14:50**MOT test number** 347355784192**Result** ✓ Passed**MOT #8** 2013-07-19 12:20**MOT test number** 995970303281**Result** ✓ Passed**Notice** Wipers poor condition**MOT #7** 2012-07-20 09:24**MOT test number** 245372902246**Result** ✓ Passed**MOT #6** 2011-07-26 13:06**MOT test number** 706327301250**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2010-02-16 09:13**MOT test number** 881327240085**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #4** 2009-02-19 09:08**MOT test number** 483880759066**Result** ✓ Passed**MOT #3** 2008-02-15 12:21**MOT test number** 180316348455**Result** ✓ Passed**Advice** Ball joint has slight play (2.2.B.1f)**MOT #2** 2007-02-21 14:19**MOT test number** 791972657023**Result** ✓ Passed**MOT #1** 2007-02-19 13:17**MOT test number** 774000257068**Result** ✗ Failed**Notice** Rubber sheafing on susp springs coming adrift**Advice** Offside Rear brake disc slightly pitted (3.5.1h)**Fail** Rear brake binding (3.7.B.1)**Advice** Offside Inner Ball joint has slight play (2.2.B.1f)**Notice** N/S/F seat belt mouldy**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Inner Ball joint has slight play (2.2.B.1f)**Notice** N/S/R seat belt slow to retract



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
19 July 2024

Tax status	Valid until 1 July
Days left	64
MOT expiry date	19 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	0
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	RENAULT FINANCE
Date of agreement	01/01/2024
Agreement type	FINANCE
Agreement term	36 months
Agreement number	123456789
Contact info	0123 456789

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2004-09-14
Last registration	2023-07-17
Complete history	See info



Registration #1	2004-09-14	18 mi
Registration #2	2007-02-19	35.476 mi
Registration #3	2007-02-21	35.476 mi
Registration #4	2008-02-15	41.717 mi
Registration #5	2009-02-19	48.487 mi
Registration #6	2010-02-16	54.276 mi
Registration #7	2011-07-26	6.303 mi
Registration #8	2012-07-20	12.798 mi
Registration #9	2013-07-19	19.088 mi
Registration #10	2014-07-04	25.377 mi
Registration #11	2015-07-03	30.852 mi
Registration #12	2016-07-18	34.491 mi
Registration #13	2016-07-18	34.491 mi
Registration #14	2016-07-18	34.491 mi
Registration #15	2016-07-18	34.491 mi
Registration #16	2016-07-18	34.491 mi
Registration #17	2016-07-18	34.491 mi
Registration #18	2016-07-18	34.491 mi
Registration #19	2016-07-18	34.491 mi
Registration #20	2016-07-18	34.491 mi
Registration #21	2016-07-18	34.491 mi
Registration #22	2016-07-18	34.491 mi
Registration #23	2016-07-18	34.491 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1810 mm
Height	1620 mm
Length	4259 mm
Wheel base	2685 mm
Kerb weight	1320 kg
Max. allowed weight	1915 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	D089071