



report date: 2024-03-28

General information

| | |
|---------------------|--------------------------|
| Make | NISSAN |
| Model | PRIMASTAR DCI SE SHR P/V |
| Colour | White |
| Year of manufacture | 2007 |
| Top speed | 99 mph |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 113 BHP |
| Max. torque | 300 Nm at 1.500 rpm |
| Engine capacity | 1.995 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 31.0 mpg |
| Consumption extra urban | 43.5 mpg |
| Consumption combined | 37.7 mpg |



LABEL UNKNOWN



Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-02-03 |
| Pictures | 1 |
| Listing price | View report |



source: [autoonline.co.uk](#)



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2024-07-03 |
| MOT pass rate | 68 % |
| MOT passed | 13 |
| Failed MOT tests | 6 |
| Total advice items | 73 |
| Total items failed | 8 |

| | |
|---------|------------------|
| MOT #19 | 2023-07-04 13:02 |
|---------|------------------|

| | |
|-----------------|--------------|
| MOT test number | 972691938783 |
|-----------------|--------------|

| | |
|--------|----------|
| Result | ✓ Passed |
|--------|----------|

| | |
|------------------|------------|
| Next expiry date | 2024-07-03 |
|------------------|------------|

- Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Coil spring corroded (ALL) (5.3.1 (b) (i))
- Advice** Nearside Front Vehicle structure or chassis corroded within 30cm of a mounting, but not seriously affecting overall security (6.2.2 (d) (i))
- Advice** Offside Front Outer Tyre has a cut but not deep enough to reach the ply or cords side wall (5.2.3 (d) (i))
- Advice** Brake pipe corroded, covered in grease or other material (ALL) (1.1.11 (c))

**MOT #18**

2023-06-27 10:40

MOT test number

231925224381

Result**✗ Failed**

- Advice** Coil spring corroded (ALL) (5.3.1 (b) (i))
- Advice** Nearside Front Vehicle structure or chassis corroded within 30cm of a mounting, but not seriously affecting overall security (6.2.2 (d) (i))
- MAJOR** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- MAJOR** Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))
- Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Outer Tyre has a cut but not deep enough to reach the ply or cords side wall (5.2.3 (d) (i))
- Advice** Brake pipe corroded, covered in grease or other material (ALL) (1.1.11 (c))
- MAJOR** Horn not working (7.7 (a))
- MAJOR** Offside Rear Position lamp not working (4.2.1 (a) (ii))
- MAJOR** Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))

MOT #17

2022-06-22 08:28

MOT test number

793447556378

Result**✓ Passed****MOT #16**

2022-06-14 15:24

MOT test number

161404128760

Result**✗ Failed**

- MAJOR** Nearside Front Wheel bearing rough when rotated (5.1.3 (b) (i))
- MAJOR** Nearside Rear Service brake excessively binding (1.2.1 (f))
- DANGEROUS** Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))

**MOT #15**

2022-06-06 07:45

MOT test number

515862876653

Result**✗ Failed****Advice**

Offside Front Anti-roll bar pin or bush worn but not resulting in excessive movement "D" bush (5.3.4 (a) (i))

MAJOR

Nearside Rear Service brake excessively binding (1.2.1 (f))

Advice

Nearside Front Anti-roll bar pin or bush worn but not resulting in excessive movement "D" bush (5.3.4 (a) (i))

MAJOR

Nearside Rear Suspension arm pin or bush excessively worn trailing arm front bush (5.3.4 (a) (i))

MAJOR

Nearside Front Wheel bearing rough when rotated (5.1.3 (b) (i))

MOT #14

2021-06-08 10:14

MOT test number

298621870038

Result**✓ Passed****Advice**

Oil leak

**MOT #13**

2021-06-04 12:35

MOT test number

620758864206

Result**✗ Failed**

- MAJOR** Nearside Front Brake pipe excessively corroded to rear (1.1.11 (c))
- MAJOR** Nearside Front Lower Anti-roll bar ball joint excessively worn (5.3.4 (a) (i))
- MAJOR** Offside Parking brake inoperative on one side (1.4.1 (a))
- MAJOR** Offside Front Integral body structure or chassis has excessive corrosion, seriously affecting its strength within 30cm of a body mounting out rigger (6.2.2 (d) (i))
- MAJOR** Hazard warning switch inoperative (4.4.2 (a) (ii))
- Advice** Oil leak
- DANGEROUS** Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))
- MAJOR** Nearside Headlamp aim too low (4.1.2 (a))
- MAJOR** Nearside Indicator switch inoperative (4.4.2 (a) (ii))
- MAJOR** Nearside Parking brake inoperative on one side (1.4.1 (a))
- MAJOR** Nearside Front Integral body structure or chassis has excessive corrosion, seriously affecting its strength within 30cm of a body mounting out rigger (6.2.2 (d) (i))
- Minor** Nearside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- MAJOR** Nearside All direction indicators not working all (4.4.1 (a) (ii))
- MAJOR** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))
- MAJOR** Offside Headlamp aim too low (4.1.2 (a))

**MOT #12**

2019-07-05 13:12

MOT test number

601411465880

Result

✓ Passed

- Advice** Nearside Front out rigger corroded
- Advice** Hazard switch damaged but still functional
- Advice** Nearside Front Wheel bearing has slight play (5.1.3 (a) (i))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Offside Front out rigger corroded
- Advice** Brake pipe corroded, covered in grease or other material all of them (1.1.11 (c))
- Advice** General unerbody corrosion
- Advice** Offside Front Wheel bearing has slight play (5.1.3 (a) (i))

MOT #11

2018-06-29 14:39

MOT test number

526421834542

Result

✓ Passed

- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Brake pipe corroded, covered in grease or other material all (1.1.11 (c))

**MOT #10**

2017-06-16 13:36

MOT test number

399929760598

Result

✓ Passed

- Advice** Offside Front Front wheel bearing has slight play (2.5.A.3c)
- Advice** Nearside Rear Brake pipe slightly corroded (3.6.B.2c)
- Advice** Nearside Front Front wheel bearing has slight play (2.5.A.3c)
- Advice** Oil leak
- Advice** Offside Rear Brake pipe slightly corroded (3.6.B.2c)
- Advice** Brake pipe slightly corroded front to rear (3.6.B.2c)

MOT #9

2016-07-05 09:14

MOT test number

473601138760

Result

✓ Passed

- Advice** Front Anti-roll bar rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Front wiper blades smear screen
- Advice** Offside Front wheel bearing has slight play (2.5.A.3c)
- Advice** High level brake light inop
- Advice** Nearside Front wheel bearing has slight play (2.5.A.3c)

MOT #8

2015-06-17 09:15

MOT test number

636688865181

Result

✓ Passed

- Advice** Offside Front wheel bearing has slight play (2.5.A.3c)
- Advice** Nearside Front wheel bearing has slight play (2.5.A.3c)

**MOT #7**

2014-06-20 09:15

MOT test number

276391274193

Result

✓ Passed

- Advice** Offside Front coil spring corroded (2.4.C.1b)
- Notice** Oil leak
- Notice** Play in steering rack inner joint(s)
- Advice** Front Lower engine mounting deteriorated, but not resulting in excessive movement (6.1.D.1a)
- Notice** Nail in offside rear tyre

MOT #6

2013-07-05 10:09

MOT test number

299006683102

Result

✓ Passed

MOT #5

2013-05-15 15:54

MOT test number

867325533136

Result

✗ Failed

- Fail** Parking brake: efficiency below requirements (3.7.B.7)
- Fail** Supplementary Restraint System warning lamp indicates a fault (5.4.2)
- Fail** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)
- Fail** Emissions not tested (7.0)
- Fail** Horn not working (1.6.2a)
- Fail** Offside Front Anti-roll bar linkage ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)
- Fail** Nearside rear parking brake recording little or no effort (3.7.B.6a)

**MOT #4** 2012-04-20 18:02**MOT test number** 635951812174**Result** ✓ Passed**Notice** Some wear to discs**Notice** Some corrosion to brake pipes**MOT #3** 2012-04-20 14:35**MOT test number** 847141212185**Result** ✗ Failed**Notice** Some wear to discs**Fail** Offside Front suspension has excessive play in a lower suspension ball joint (2.5.B.1a)**Notice** Some corrosion to brake pipes**MOT #2** 2011-04-28 12:54**MOT test number** 227598311497**Result** ✓ Passed**Advice** Offside Front Track rod end ball joint has slight play (2.2.B.1f)**MOT #1** 2010-04-28 15:50**MOT test number** 420338910105**Result** ✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 November 2024

✓
MOT

Expires:
3 July 2024

| | | |
|------------------|--|---------------------------------|
| Tax status | | Valid until 1 November |
| Days left | | 186 |
| MOT expiry date | | 3 July 2024 |
| Full MOT history | | See MOT history |



Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|-------|
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |

More info >

Plate changes

See in this check if this NISSAN had different number plates.

| | |
|----------------------|------------|
| Number of plates | 1 |
| Current registration | ***** |
| Plate since | 2019-06-29 |
| Current registration | ***** |
| Plate since | 2019-06-29 |

More info >



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.


| | | |
|-------------------|------------|------|
| Finance company | XXXXXXXXXX | XXXX |
| Date of agreement | XXXXXXXXXX | XXXX |
| Agreement type | XXXXXXXXXX | XXXX |
| Agreement term | XXXXXXXXXX | XXXX |
| Agreement number | XXXXXXXXXX | XXXX |
| Contact info | XXXXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 21 |
| First mileage registration | 2007-05-01 |
| Last registration | 2023-07-04 |
| Complete history | See info |



| | | |
|------------------|------------|------------|
| Registration #1 | 2007-05-01 | 8 mi |
| Registration #2 | 2010-04-28 | 116.387 mi |
| Registration #3 | 2011-04-28 | 149.799 mi |
| Registration #4 | 2012-04-20 | 163.756 mi |
| Registration #5 | 2012-04-20 | 163.762 mi |
| Registration #6 | 2013-05-15 | 167.551 mi |
| Registration #7 | 2013-07-05 | 167.593 mi |
| Registration #8 | 2014-06-20 | 176.265 mi |
| Registration #9 | 2015-06-17 | 185.779 mi |
| Registration #10 | 2016-07-05 | 192.914 mi |
| Registration #11 | 2017-06-16 | 198.562 mi |
| Registration #12 | 2018-06-16 | 205.210 mi |
| Registration #13 | 2019-06-16 | 211.858 mi |
| Registration #14 | 2020-06-16 | 218.506 mi |
| Registration #15 | 2021-06-16 | 225.154 mi |
| Registration #16 | 2022-06-16 | 231.802 mi |
| Registration #17 | 2023-06-16 | 238.450 mi |
| Registration #18 | 2023-07-04 | 245.098 mi |
| Registration #19 | 2023-07-04 | 245.098 mi |
| Registration #20 | 2023-07-04 | 245.098 mi |
| Registration #21 | 2023-07-04 | 245.098 mi |

More info >



Car features

The NISSAN factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Additional information

| | |
|-----------------|------------------|
| Fuel delivery | Direct Injection |
| Number of doors | 4 |
| Number of seats | 3 |
| Engine number | 136904 |