



PEUGEOT



report date: 2024-03-29

General information

Make	PEUGEOT
Model	307 S
Colour	Blue
Year of manufacture	-
Top speed	118 mph
0 - 60 mph	10.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	107 BHP
Max. torque	147 Nm at 4.000 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	29.7 mpg
Consumption extra urban	48.7 mpg
Consumption combined	39.2 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-07-15
Pictures	14
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)

**MOT history**

<b>MOT #20</b>	2022-07-27 14:26
<b>MOT test number</b>	495536529677
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2023-07-29
<b>Advice</b>	Front Play in steering rack inner joint(s)
<b>Advice</b>	Front Upper Macpherson strut pin or bush worn but not resulting in excessive movement offside and nearside top mount bush and bearing worn (5.3.4 (a) (i))
<b>Advice</b>	Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i))
<b>Advice</b>	Rear Shock absorbers has a slightly worn bush (5.3.2 (c))
<b>Advice</b>	Front Lower Suspension arm pin or bush worn but not resulting in excessive movement offside and nearside arm bushes perished (5.3.4 (a) (i))
<b>Advice</b>	Coil spring corroded all 4 springs (5.3.1 (b) (i))
<b>Advice</b>	Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))

<b>MOT #19</b>	2021-07-02 15:17
<b>MOT test number</b>	191663429911
<b>Result</b>	✓ Passed
<b>Advice</b>	Front Exhaust has a minor leak of exhaust gases flange (6.1.2 (a))
<b>Advice</b>	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
<b>Advice</b>	Rear Coil spring corroded (5.3.1 (b) (i))
<b>Advice</b>	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #18** 2021-07-02 13:16**MOT test number** 645824489055**Result** ✗ Failed**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Front Exhaust has a minor leak of exhaust gases flange (6.1.2 (a))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Rear Coil spring corroded (5.3.1 (b) (i))**Fail** Nearside Front Lower Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**MOT #17** 2020-07-30 14:34**MOT test number** 979249632665**Result** ✓ Passed**MOT #16** 2019-05-28 12:49**MOT test number** 952625030705**Result** ✓ Passed**MOT #15** 2018-05-22 13:40**MOT test number** 588733487030**Result** ✓ Passed**MOT #14** 2017-05-16 15:48**MOT test number** 773195808165**Result** ✓ Passed**Advice** Rear exhaust bracket broken

**MOT #13**

2017-05-16 09:02

**MOT test number**

620332294009

**Result**

✗ Failed

**Advice** Rear exhaust bracket broken**Fail** Offside Front Upper Anti-roll bar linkage ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)**Fail** Offside Rear position lamp(s) not working (1.1.A.3b)**MOT #12**

2016-05-24 09:11

**MOT test number**

791609306070

**Result**

✓ Passed

**Advice** Nearside Front Tyre worn close to the legal limit 3mm (4.1.E.1)**Advice** Nearside Front Ball joint has slight play inner tie rod (2.2.B.1f)**Advice** Offside Rear coil spring corroded (2.4.C.1b)**Advice** Exhaust bracket broken**Advice** Offside Front Tyre worn close to the legal limit 2mm worn on inner edge (4.1.E.1)**MOT #11**

2015-05-20 16:17

**MOT test number**

975240745124

**Result**

✓ Passed

**MOT #10**

2015-05-20 10:11

**MOT test number**

548450045157

**Result**

✗ Failed

**Advice** Offside Front Ball joint has slight play (2.2.B.1f)**Notice** Nearside front track rod end gaiter not fully secure**Fail** Offside Front Track rod end ball joint dust cover insecure so that it no longer prevents the ingress of dirt (2.2.C.1c)**Fail** Rear position lamp(s) adversely affected by the operation of another lamp (1.1.A.3f)

**MOT #9** 2014-05-28 16:02**MOT test number** 796388444177**Result** ✓ Passed**Notice** Play in steering rack inner joint(s)**MOT #8** 2014-05-28 10:26**MOT test number** 717178644168**Result** ✗ Failed**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Notice** Play in steering rack inner joint(s)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #7** 2013-05-23 15:41**MOT test number** 279153643491**Result** ✓ Passed**Notice** Rear discs lipped and pitted**Notice** Offside rear light lens damaged**MOT #6** 2013-05-23 12:06**MOT test number** 867303543128**Result** ✗ Failed**Fail** Nearside Front Headlamp aim too high (1.8)**Notice** Offside rear brake slightly binding**Notice** Offside rear light lens damaged**Fail** Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Notice** Rear discs lipped and pitted

**MOT #5** 2012-05-28 14:52**MOT test number** 958119342107**Result** ✓ Passed**MOT #4** 2011-05-27 14:29**MOT test number** 105547141158**Result** ✓ Passed**MOT #3** 2011-05-19 15:30**MOT test number** 396519531174**Result** ✗ Failed**Notice** Front discs worn**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Fail** Horn not working (1.6.2a)**MOT #2** 2010-05-21 11:23**MOT test number** 571771540186**Result** ✓ Passed**Advice** Front brake disc slightly scored (3.5.1h)**MOT #1** 2010-05-20 09:30**MOT test number** 291070840412**Result** ✗ Failed**Fail** Offside Rear brake disc excessively scored (3.5.1h)**Advice** Front brake disc slightly scored (3.5.1h)**Fail** Windscreen washer provides insufficient washer liquid (8.2.3)



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	<b>KS07EZG</b>
Plate since	2024-03-29
Current registration	<b>KS07EZG</b>
Plate since	2024-03-29

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2007-05-21
Last registration	2022-07-27
Complete history	<a href="#">See info</a>



Registration #1	2007-05-21	23 mi
Registration #2	2010-05-20	25.151 mi
Registration #3	2010-05-21	25.177 mi
Registration #4	2011-05-19	30.998 mi
Registration #5	2011-05-27	31.017 mi
Registration #6	2012-05-28	36.522 mi
Registration #7	2013-05-23	42.497 mi
Registration #8	2013-05-23	42.497 mi
Registration #9	2014-05-28	49.852 mi
Registration #10	2014-05-28	49.852 mi
Registration #11	2015-05-20	56.905 mi
Registration #12	2015-05-20	56.905 mi
Registration #13	2015-05-20	56.905 mi
Registration #14	2015-05-20	56.905 mi
Registration #15	2015-05-20	56.905 mi
Registration #16	2015-05-20	56.905 mi
Registration #17	2015-05-20	56.905 mi
Registration #18	2015-05-20	56.905 mi
Registration #19	2015-05-20	56.905 mi
Registration #20	2015-05-20	56.905 mi
Registration #21	2015-05-20	56.905 mi
Registration #22	2015-05-20	56.905 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video [see crash video](#)



Dimensions & weight

Width	1746 mm
Height	1512 mm
Length	4202 mm
Wheel base	2608 mm
Kerb weight	1275 kg
Max. allowed weight	1700 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	FX6N3093351