



report date: 2024-03-29

General information

Make	FORD
Model	FUSION FUSION +
Colour	Blue
Year of manufacture	2009
Top speed	109 mph
0 - 60 mph	12.7 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	100 BHP
Max. torque	145 Nm at 4.000 rpm
Engine capacity	1.596 cc
Cylinders	4
Fuel type	Petrol
Consumption city	27.4 mpg
Consumption extra urban	46.3 mpg
Consumption combined	37.2 mpg
CO2 emission	179 g/km
CO2 label	I





Internet history

Entry 1

Date	2022-01-22
Pictures	20
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



## MOT history

MOT expiry date	2024-09-07
MOT pass rate	67 %
MOT passed	12
Failed MOT tests	6
Total advice items	19
Total items failed	12

MOT #18	2023-09-01 15:48
MOT test number	407044502031
Result	✓ Passed
Next expiry date	2024-09-07
Advice	Exhaust has a minor leak of exhaust gases (6.1.2 (a))

MOT #17	2023-09-01 11:29
MOT test number	654241684934
Result	✗ Failed
Minor	Offside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))
Fail	Nearside Rear Rear fog lamp not working (4.5.1 (a) (ii))
Fail	Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
Minor	Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Fail	Nearside Rear Reversing lamp inoperative (4.6.1 (a))
Advice	Exhaust has a minor leak of exhaust gases (6.1.2 (a))

**MOT #16**

2022-09-03 13:20

**MOT test number**

181551032684

**Result**

✓ Passed

**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Rear Tyre slightly damaged/cracking or perishing Offside - Nearside (5.2.3 (d) (ii))**MOT #15**

2022-09-03 13:20

**MOT test number**

367644347781

**Result**

✗ Failed

**Pass with rectification** Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Pass with rectification** Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Rear Tyre slightly damaged/cracking or perishing Offside - Nearside (5.2.3 (d) (ii))**MOT #14**

2021-09-08 10:30

**MOT test number**

648393462076

**Result**

✓ Passed

**Advice** Offside Brake pipe corroded, covered in grease or other material Front to rear (1.1.11 (c))**MOT #13**

2020-08-13 13:33

**MOT test number**

127431020244

**Result**

✓ Passed

**MOT #12** 2020-08-13 08:10**MOT test number** 649161821572**Result** ✗ Failed**Fail** Offside Rear Wheel bearing has excessive play (5.1.3 (a) (i))**Fail** Offside Rear Wheel bearing rough when rotated (5.1.3 (b) (i))**MOT #11** 2019-05-01 14:43**MOT test number** 976227172179**Result** ✓ Passed**MOT #10** 2019-05-01 08:17**MOT test number** 996057451271**Result** ✗ Failed**Fail** Nearside Rear Wheel bearing rough when rotated (5.1.3 (b) (i))**Fail** Nearside Rear Coil spring fractured or broken at base (5.3.1 (b) (i))**MOT #9** 2018-11-16 16:56**MOT test number** 964417072181**Result** ✓ Passed**Advice** Nearside Rear Wheel bearing slightly noisy (5.1.3 (b) (i))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Nearside bumper to wing fixing damaged**MOT #8** 2017-08-25 11:24**MOT test number** 766137052502**Result** ✓ Passed**Advice** Front brake pads wearing low**Advice** All tyres wearing low and perished

**MOT #7** 2016-09-27 08:19**MOT test number** 522819803130**Result** ✓ Passed**Advice** All tyres perishing**MOT #6** 2015-10-01 13:17**MOT test number** 736330930770**Result** ✓ Passed**MOT #5** 2014-09-16 10:47**MOT test number** 469079754207**Result** ✓ Passed**MOT #4** 2013-10-01 14:56**MOT test number** 349194073253**Result** ✓ Passed**MOT #3** 2013-10-01 14:56**MOT test number** 119814573289**Result** ✗ Failed**Pass with rectification** Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Pass with rectification** Front registration plate insecure (6.3.1b)**MOT #2** 2012-08-06 16:34**MOT test number** 879649212228**Result** ✓ Passed



MOT #1	2012-08-06 12:11
MOT test number	325019512295
Result	✗ Failed
Fail	Fuel cap/sealing device missing (7.2.4a)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 February 2025

✓  
**MOT**  
**Expires:**  
7 September 2024

<b>Tax status</b>	Valid until 1 February
<b>Days left</b>	278
<b>MOT expiry date</b>	7 September 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	I
<b>Single payment (12 months)</b>	£ 320,00,-
<b>Single six month payment</b>	£ 176,00,-
<b>Total payable by 12 monthly instalments</b>	£ 336,00,-





Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2009-09-30
Last registration	2023-09-01
Complete history	<a href="#">See info</a>



Registration #1	2009-09-30	25 mi
Registration #2	2012-08-06	6.735 mi
Registration #3	2012-08-06	6.735 mi
Registration #4	2013-10-01	7.350 mi
Registration #5	2014-09-16	7.469 mi
Registration #6	2015-10-01	15.458 mi
Registration #7	2016-09-27	23.196 mi
Registration #8	2017-08-25	30.699 mi
Registration #9	2018-11-16	40.527 mi
Registration #10	2019-05-01	46.121 mi
Registration #11	2019-05-01	46.121 mi
Registration #12	2019-05-01	46.121 mi
Registration #13	2019-05-01	46.121 mi
Registration #14	2019-05-01	46.121 mi
Registration #15	2019-05-01	46.121 mi
Registration #16	2019-05-01	46.121 mi
Registration #17	2019-05-01	46.121 mi
Registration #18	2019-05-01	46.121 mi
Registration #19	2019-05-01	46.121 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1963 mm
Height	1543 mm
Length	4013 mm
Wheel base	2485 mm
Kerb weight	1110 kg
Max. allowed weight	1630 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	9P21532