



report date: 2024-03-29

General information

Make	VAUXHALL
Model	VIVARO L1H1 2700 CDTi
Colour	Black
Year of manufacture	2017
Gearbox	6 speed Manual

Engine & fuel consumption

Power	118 BHP
Max. torque	300 Nm at 1.750 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	36.2 mpg
Consumption extra urban	48.7 mpg
Consumption combined	43.5 mpg
CO2 emission	170 g/km
CO2 label	H





Internet history

Entry 3


Date	2021-12-18
Pictures	35
Listing price	View report



source: yesauto.com

Entry 2

Date	2021-11-21
Pictures	36
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2021-11-21
Pictures	0
Listing price	View report

source: heycar.co.uk



MOT history

MOT expiry date	2025-02-09
MOT pass rate	67 %
MOT passed	4
Failed MOT tests	2
Total advice items	14
Total items failed	3

MOT #6	2024-01-17 17:03
MOT test number	112864502292
Result	✓ Passed
Next expiry date	2025-02-09
Minor	Offside Front Windscreen wiper blade defective (3.4 (b) (i))

MOT #5	2023-02-07 09:16
MOT test number	367052229828
Result	✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Front Service brake fluctuating, but not excessively (1.2.1 (e))
Advice	Front Brake disc worn, but not excessively lipped (1.1.14 (a) (i))

**MOT #4** 2023-02-03 09:44**MOT test number** 658640786523**Result** ✗ Failed**Fail** Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Front Service brake fluctuating, but not excessively (1.2.1 (e))**Advice** Front Brake disc worn, but not excessively lipped (1.1.14 (a) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #3** 2022-02-10 16:00**MOT test number** 944379516516**Result** ✓ Passed**Advice** Covers / trays fitted**MOT #2** 2022-02-10 15:06**MOT test number** 500454518808**Result** ✗ Failed**Fail** Nearside Front Brake hose excessively twisted (1.1.12 (b) (ii))**Fail** Offside Stop lamp(s) not working (4.3.1 (a) (ii))**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Engine cover fitted under tray missing**MOT #1** 2021-04-27 13:39**MOT test number** 418749031469**Result** ✓ Passed**Minor** Nearside Obligatory mirror slightly damaged (3.3 (b) (i))



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
9 February 2025

Tax status	Valid until 1 March
Days left	306
MOT expiry date	9 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 320,00,-
Standard rate (6 months)	£ 176,00,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	DU67WND
Plate since	2019-06-29
Current registration	DU67WND
Plate since	2019-06-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2017-09-30
Last registration	2024-01-17
Complete history	See info



Registration #1	2017-09-30	13 mi
Registration #2	2021-04-27	48.916 mi
Registration #3	2022-05-20	55.277 mi
Registration #4	2023-05-20	55.277 mi
Registration #5	2023-05-20	55.277 mi
Registration #6	2023-05-20	55.277 mi
Registration #7	2023-05-20	55.277 mi
Registration #8	2023-05-20	55.277 mi
Registration #9	2023-05-20	55.277 mi
Registration #10	2024-01-17	55.277 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Adult	52%
Children	91%
Pedestrian	53%
Safety systems	57%
Overall rating	61%
Video	see crash video



Dimensions & weight

Width	2283 mm
Height	1971 mm
Length	4998 mm
Kerb weight	1725 kg
Max. allowed weight	2800 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	3
Engine number	R9M MK - C048048LWZ