






General information

Make	VOLKSWAGEN
Model	BEETLE LUNA 8V
Colour	White
Year of manufacture	2011
Top speed	111 mph
0 - 100 km/h	11.6 seconds
0 - 60 mph	11.6 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	75 kW / 102 HP / 102 BHP
Max. torque	148 Nm at 3.800 rpm
Engine capacity	1.595 cc
Cylinders	4
Fuel type	Petrol
Consumption city	27.4 mpg
Consumption extra urban	47.9 mpg
Consumption combined	37.7 mpg
CO2 emission	180 g/km
CO2 label	I








Internet history

Entry 1	
Date	2021-07-31
Pictures	26

Listing price

View report



source: yesauto.com



MOT history

MOT expiry date	2024-09-18
MOT pass rate	79 %
MOT passed	11
Failed MOT tests	3
Total advice items	32
Total items failed	2

MOT #14		2023-09-19 09:06
MOT test	number	323590401610
Result		✓ Passed
Next expi	ry date	2024-09-18
Advice	Nearside Front Outer Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Offside Rear Service brake binding but not excessively (1.2.1 (f))	

MOT #13	2023-09-13 12:1
MOT test	number 477741394103
Result	× Failed
Advice bush (5.3.4	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear 4 (a) (i))
Advice	Central exhaust centre sleeve corroded
Advice	Offside Rear Service brake binding but not excessively (1.2.1 (f))
MAJOR	Offside Front Suspension arm pin or bush excessively worn rear bush (5.3.4 (a) (i))
MAJOR	Nearside Rear Outer Brake disc significantly and obviously worn (1.1.14 (a) (i))
Advice	Nearside Front Outer Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
MAJOR	Nearside Rear Service brake excessively fluctuating (1.2.1 (e))





MOT #12	2022-09-12 15:06	
MOT test number	598168643059	
Result	✓ Passed	
MOT #11	2022-01-04 15:21	
MOT test number	769703398118	
Result	✓ Passed	
MOT #10	2021-05-14 09:36	
MOT test number	938899157319	
Result	✓ Passed	
Advice Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))		
Advice Rear Brake disc worn, pitted or scored, but not seriously weakene	d (1.1.14 (a) (ii))	
Advice Exhaust has a minor leak of exhaust gases Connecting sleeve clar	mp (6.1.2 (a))	

Advice	Front Brake disc worn,	pitted or scored,	but not seriously	v weakened (1.1.14 (a) (ii))
--------	------------------------	-------------------	-------------------	------------------------------

МОТ #9	2020-12-16 15:46
MOT test number	279068549903
Result	✓ Passed
Advice Brake pad wear sensor illuminated	

MOT #8		2020-12-15 14:16
MOT test	number	647348734956
Result		🗙 Failed
MAJOR	Rear Rear fog lamp not working (4.5.1 (a) (ii))	
MAJOR	Offside Front Shock absorbers has a serious fluid leak (5.3.2 (b))	
Advice	Brake pad wear sensor illuminated	





MOT #7		2019-12-14 10:20
MOT test	number	727150883506
Result		✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge slight wear to inner e	dges (5.2.3 (e))
Advice	Front Registration plate deteriorated but not likely to be misread (0.1 (b))	
Advice	Brake pedal has little reserve travel	
Advice	Service brake fluctuating, but not excessively all (1.2.1 (e))	

МОТ #6	2019-12-13 15:06	
MOT test number	221094037222	
Result	🗙 Failed	
DANGEROUS Nearside Front Tyre has ply or cords exposed outer edge (5.2.3 (d) (ii))		
Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b))		
Pass with rectification Headlamp aim too low both (4.1.2 (a))		
Advice Offside Front Tyre worn close to legal limit/worn on edge slight wear to inner	edges (5.2.3 (e))	
Advice Service brake fluctuating, but not excessively all (1.2.1 (e))		
Advice Brake pedal has little reserve travel		
Pass with rectification Windscreen wiper does not clear the windscreen effectively	both (3.4 (b) (ii))	

MOT #5	2018-05-26 10:40
MOT test number	593185780794
Result	✓ Passed
Advice Nearside Front Tyre	e worn close to legal limit/worn on edge also cracked and perished. (5.2.3 (e))

MOT #4	2017-03-04 15:01
MOT test number	974321565529
Result	✓ Passed



MOT #3		2016-03-24 11:22
MOT test	number	209077848959
Result		✓ Passed
Advice	Rear Brake pad(s) wearing thin (3.5.1g)	
Advice	Front Brake pad(s) wearing thin (3.5.1g)	

MOT #2 2015-03-27 14:03 475256885059 **MOT test number** Result ✓ Passed Notice Both rear tyres have minor cracks on the outter edge Notice Engine covers fitted obscuring some components in the engine bay Notice Child seat fitted not allowing full inspection of adult belt

MOT #1	2014-01-11 08:46
MOT test number	658311714080
Result	✓ Passed

YY60URT report date: 2024-03-29



Tax & MOT check

✓ Taxed Tax due: 1 October 2024	✓ MOT Expires: 18 September 2024
Tax status	Valid until 1 October
Days left	155
MOT expiry date	18 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-





Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FERRE
Category	Lamp
Туре	
Demons 2	AMPLE
Damage 2	6 6 at - a
Date	
Category	AMPT
Туре	

Extra VOLKSWAGEN salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4.11.111
Auction value	4 10.000
Average private trade value	4 =





Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

ANALY AND A ANALY ANY ANY ANY ANY ANY ANY ANY ANY ANY AN	
	More info >
Plate changes	
See in this check if this VOLKSWAGEN had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate sites	





Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2011-01-31
Last registration	2023-09-19
Complete history	<u>See info</u>



Registration #1	2011-01-31	24 mi
Registration #2	2014-01-11	21.547 mi
Registration #3	2015-03-27	28.842 mi
Registration #4	2016-03-24	34.194 mi
Registration #5	2017-03-04	39.211 mi
Registration #6	2018-05-26	44.163 mi
Registration #7	2019-12-13	50.131 mi
Registration #8	2019-12-14	50.140 mi
Registration #9		11.777 mi
Registration #9 Registration #10		10.000 est
-		00.000 est 0.000 est 00.000 est
Registration #10		00.000 est 0.000 est 00.000 est 00.000 est
Registration #10 Registration #11		00.000 est 0.000 est 00.000 est 0.000 est 00.000 est
Registration #10 Registration #11 Registration #12		00.000 est 0.000 est 0.000 est 0.000 est 0.000 est 0.000 est
Registration #10 Registration #11 Registration #12 Registration #13		00.000 est 0.000 est 0.000 est 0.000 est 0.000 est 0.000 est 0.000 est





Car features

S0225	Air conditioning
S0295	
50482	
\$0501	
\$0566	
\$0567	
S0569	

Safety ratings

NCAP rating

Video

see crash video



Dimensions & weight	
Width	1721 mm
Height	1502 mm
Length	4129 mm
Wheel base	2516 mm
Kerb weight	1177 kg
Max. allowed weight	1680 kg
Additional information	
Fuel tank capacity	55 I
Fuel delivery	Multi-Point Injection
Number of doors	3

Number of seats	4
Number of axles	2
Engine number	BFS 085648