



GF57TWU

report date: 2024-03-29

General information

Make	AUDI
Model	Q7 TDI QUATTRO S LINE
Colour	Black
Year of manufacture	2007
Top speed	134 mph
0 - 60 mph	9.1 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	229 BHP
Max. torque	500 Nm at 1.750 rpm
Engine capacity	2.967 cc
Cylinders	6
Fuel type	Diesel
Consumption city	19.3 mpg
Consumption extra urban	34.0 mpg
Consumption combined	26.9 mpg
CO2 emission	279 g/km
CO2 label	M





Internet history

Entry 1

Date	2021-07-06
Pictures	15
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-12-19
MOT pass rate	80 %
MOT passed	12
Failed MOT tests	3
Total advice items	20
Total items failed	4

MOT #15	2023-12-20 14:54
MOT test number	535808545685
Result	✓ Passed
Next expiry date	2024-12-19

MOT #14	2022-09-10 13:07
MOT test number	590748468753
Result	✓ Passed
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Nearside Front Upper Suspension arm ball joint has slight play (5.3.4 (a) (i))

MOT #13	2021-07-06 10:00
MOT test number	214981925191
Result	✓ Passed
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Nearside Front Upper Suspension arm ball joint has slight play (5.3.4 (a) (i))
Advice	Front Brake disc worn, but not excessively (1.1.14 (a) (i))

**MOT #12** 2020-06-26 10:52**MOT test number** 627098427704**Result** ✓ Passed**Advice** Front Anti-roll bar corroded but not seriously weakened (5.3.3 (b) (i))**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Rear Anti-roll bar corroded but not seriously weakened (5.3.3 (b) (i))**MOT #11** 2020-06-26 10:52**MOT test number** 468557154409**Result** ✗ Failed**Advice** Front Anti-roll bar corroded but not seriously weakened (5.3.3 (b) (i))**Pass with rectification** Rear fog lamp not working (4.5.1 (a) (ii))**Advice** Rear Anti-roll bar corroded but not seriously weakened (5.3.3 (b) (i))**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #10** 2019-06-29 07:29**MOT test number** 636959827531**Result** ✓ Passed**MOT #9** 2018-06-29 09:16**MOT test number** 642212858477**Result** ✓ Passed**Advice** Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))**MOT #8** 2017-07-09 14:06**MOT test number** 447939262336**Result** ✓ Passed

**MOT #7** 2015-04-29 11:06**MOT test number** 186419515194**Result** ✓ Passed**MOT #6** 2015-04-27 12:52**MOT test number** 625557915195**Result** ✗ Failed**Advice** Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.C.1b)**Fail** Nearside Front Tyre has ply or cords exposed (4.1.D.1b)**MOT #5** 2014-05-01 10:46**MOT test number** 286001424184**Result** ✓ Passed**MOT #4** 2012-11-21 09:27**MOT test number** 419626922335**Result** ✓ Passed**Advice** Nearside Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)**MOT #3** 2011-11-16 11:53**MOT test number** 296060421330**Result** ✓ Passed**Notice** Nearside front tyre is wearing on the outer edge**Notice** Offside front tyre wearing low on the outer edge



MOT #2 2011-11-14 16:30

MOT test number 608028511304

Result ✗ Failed

- Notice** Nearside front tyre is wearing on the outer edge
- Fail** Nearside Rear reflector excessively damaged so that its function is impaired (1.5.1c)
- Notice** Offside front tyre wearing low on the outer edge
- Fail** Rear fog lamp switch faulty (1.3.1a)
- Notice** Nail in nearside rear tyre

MOT #1 2010-10-27 16:51

MOT test number 453140600395

Result ✓ Passed

- Notice** Nearside rear reflector and bumper is damaged



Tax & MOT check

X

Untaxed

Tax expired:
8 July 2021

✓

MOT

Expires:
19 December 2024

Tax status	Expired at 8 July 2021
Days left	1027 days too late
MOT expiry date	19 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	M
Single payment (12 months)	£ 695,00,-
Single six month payment	£ 382,25,-
Total payable by 12 monthly instalments	£ 729,75,-



Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra AUDI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this AUDI? How many owners did this AUDI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this AUDI had different number plates.

Number of plates	1
Current registration	
Plate since	2019-03-29
Current registration	
Plate since	2019-03-29

More info >



Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this AUDI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2007-10-31
Last registration	2023-12-20
Complete history	See info



Registration #1	2007-10-31	27 mi
Registration #2	2010-10-27	59.540 mi
Registration #3	2011-11-14	81.084 mi
Registration #4	2011-11-16	81.253 mi
Registration #5	2012-11-21	100.268 mi
Registration #6	2014-05-01	111.938 mi
Registration #7	2015-04-27	119.588 mi
Registration #8	2015-04-29	119.608 mi
Registration #9	2017-07-09	127.239 mi
Registration #10	2019-05-20	151.377 mi
Registration #11	2019-05-20	151.377 mi
Registration #12	2019-05-20	151.377 mi
Registration #13	2019-05-20	151.377 mi
Registration #14	2019-05-20	151.377 mi
Registration #15	2019-05-20	151.377 mi
Registration #16	2019-05-20	151.377 mi
Registration #17	2019-05-20	151.377 mi

More info >



Car features

The AUDI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete AUDI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1983 mm
Height	1737 mm
Length	5086 mm
Wheel base	3002 mm
Kerb weight	2325 kg
Max. allowed weight	3120 kg

Additional information

Fuel tank capacity	100 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

