



report date: 2024-03-28

## General information

Make	VAUXHALL
Model	ANTARA SE NAV CDTI S/S
Colour	Grey
Year of manufacture	2013
Top speed	117 mph
0 - 60 mph	9.6 seconds
Gearbox	6 speed Manual

## Engine & fuel consumption

Power	161 BHP
Max. torque	350 Nm at 2.000 rpm
Engine capacity	2.231 cc
Cylinders	4
Fuel type	Diesel
Consumption city	35.8 mpg
Consumption extra urban	50.4 mpg
Consumption combined	44.1 mpg
CO2 emission	170 g/km
CO2 label	H





Internet history

Entry 1

Date	2022-07-01
Pictures	0
Listing price	<a href="#">View report</a>

source: cargurus.co.uk



## MOT history

MOT expiry date	2024-07-11
MOT pass rate	71 %
MOT passed	10
Failed MOT tests	4
Total advice items	24
Total items failed	6

MOT #14	2023-06-28 15:31
MOT test number	280860263137
Result	✓ Passed
Next expiry date	2024-07-11

MOT #13	2022-07-12 08:18
MOT test number	221811819184
Result	✓ Passed

MOT #12	2022-02-15 14:24
MOT test number	134975606137
Result	✓ Passed

- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Rear Suspension arm pin or bush worn but not resulting in excessive movement Both trailing arm bush (5.3.4 (a) (i))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #11**

2022-02-15 10:35

**MOT test number**

835162707340

**Result**

✗ Failed

- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Rear Suspension arm pin or bush worn but not resulting in excessive movement Both trailing arm bush (5.3.4 (a) (i))
- Fail** Reversing lamp inoperative (4.6.1 (a))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))

**MOT #10**

2021-01-28 09:44

**MOT test number**

601772420304

**Result**

✓ Passed

- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**MOT #9**

2020-02-17 09:57

**MOT test number**

891083436422

**Result**

✓ Passed

- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt

**MOT #8** 2020-02-17 09:57**MOT test number** 671010134315**Result** ✗ Failed**Pass with rectification** Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**MOT #7** 2019-01-16 09:44**MOT test number** 655990768658**Result** ✓ Passed**Minor** Offside Rear Tyre obviously under inflated (5.2.3 (h) (i))**MOT #6** 2018-02-16 08:41**MOT test number** 106407655826**Result** ✓ Passed**MOT #5** 2018-02-16 08:41**MOT test number** 371267525811**Result** ✗ Failed**Pass with rectification** Offside Headlamp not working on dipped beam (1.7.5a)**MOT #4** 2017-09-21 16:09**MOT test number** 920594727577**Result** ✓ Passed**Advice** Engine under tray fitted

**MOT #3** 2017-09-15 15:58**MOT test number** 498367557851**Result** ✗ Failed

- Advice** Nearside Rear tyre worn on edge
- Advice** Front brakes slightly binding on
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Fail** Nearside Stop lamp not working (1.2.1b)
- Advice** Offside Rear tyre worn on edge
- Advice** Engine under tray fitted
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Fail** Offside Front Shock absorber has a serious fluid leak (2.7.3)

**MOT #2** 2016-10-17 10:29**MOT test number** 796701861412**Result** ✓ Passed**MOT #1** 2015-10-22 13:04**MOT test number** 151950949478**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 July 2024

✓  
**MOT**  
**Expires:**  
11 July 2024

<b>Tax status</b>	Valid until 1 July
<b>Days left</b>	63
<b>MOT expiry date</b>	11 July 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	H
<b>Single payment (12 months)</b>	£ 290,00,-
<b>Single six month payment</b>	£ 159,50,-
<b>Total payable by 12 monthly instalments</b>	£ 304,50,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	<b>AO62TVF</b>
Plate since	2019-03-28
Current registration	<b>AO62TVF</b>
Plate since	2019-03-28

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2013-01-16
Last registration	2023-06-28
Complete history	<a href="#">See info</a>



Registration #1	2013-01-16	10 mi
Registration #2	2015-10-22	14.434 mi
Registration #3	2016-10-17	27.466 mi
Registration #4	2017-09-15	34.307 mi
Registration #5	2017-09-21	34.307 mi
Registration #6	2018-02-16	37.591 mi
Registration #7	2018-02-16	37.591 mi
Registration #8	2019-01-16	43.538 mi
Registration #9	2019-01-16	43.538 mi
Registration #10	2019-01-16	43.538 mi
Registration #11	2019-01-16	43.538 mi
Registration #12	2019-01-16	43.538 mi
Registration #13	2019-01-16	43.538 mi
Registration #14	2019-01-16	43.538 mi
Registration #15	2019-01-16	43.538 mi
Registration #16	2019-01-16	43.538 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	95%
Children	84%
Pedestrian	46%
Safety systems	71%
Overall rating	81%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	2085 mm
Height	1717 mm
Length	4596 mm
Wheel base	2707 mm
Kerb weight	1896 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	65 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	Z22D1 291601K LNQ