





report date: 2024-03-28

## General information

Make	MINI
Model	MINI COOPER D CLUBMAN
Colour	Grey
Year of manufacture	2014
Top speed	122 mph
0 - 60 mph	10.2 seconds
Gearbox	6 speed Manual

# Engine & fuel consumption

Power	112 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.598 сс
Cylinders	4
Fuel type	Diesel
Consumption city	64.2 mpg
Consumption extra urban	78.5 mpg
Consumption combined	72.4 mpg
CO2 emission	103 g/km
CO2 label	В



CarCheck.co.uk page 1/12



report date: 2024-03-28

# Internet history

### Entry 2

Date 2021-08-28

Pictures 20

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1

Date 2021-08-28

Pictures 20

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-28

	_			
MO	1	hic	to	r\/
				ıv.
				. ,

MOT expiry date	2025-03-21
MOT pass rate	90 %
MOT passed	9
Failed MOT tests	1
Total advice items	20
Total items failed	0

MOT #10	2024-03-22 12:18
MOT test number	132972688934
Result	<b>✓</b> Passed
Next expiry date	2025-03-21

MOT #9		2023-07-04 12:50
MOT test	number	263379445270
Result		✓ Passed
Advice	Passenger seat(s) missing at time of test	
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Rear Standard fitment seat belt missing	
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	

CarCheck.co.uk page 3/12



report date: 2024-03-28

**MOT #8** 2023-07-04 08:47 290300659099 **MOT** test number Result × Failed **Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) **MAJOR** Brake fluid contaminated cap missing dirt (1.8 (a)) Advice Rear Standard fitment seat belt missing Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) Front Windscreen washer provides insufficient washer liquid (3.5 (a)) MAJOR Advice Passenger seat(s) missing at time of test

MOT #7

MOT test number

Result

Advice Nearside Rear Nail in tyre perishing

Advice Front Brake pad(s) wearing thin 50% worn (1.1.13 (a) (ii))

MOT test number

Result

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT #5		2020-06-17 11:14
MOT test	number	745472279982
Result		✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14	l (a) (ii))
Advice	Undertrays fitted obscuring some components	
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Engine trays fitted obscuring some components	
Minor	Central Front Windscreen damaged but not adversely affecting driver's view	v (3.2 (a) (i))

MOT #4	2019-07-16 09:22
MOT test number	880643168871
Result	<b>✓</b> Passed
MOT #3	2018-06-04 15:29
MOT test number	956764174182
Result	<b>✓</b> Passed
MOT #2	2017-03-21 12:55
MOT test number	529902429442
Result	<b>✓</b> Passed
MOT #1	2016-08-11 11:55
MOT test number	931132920127
Result	<b>✓</b> Passed

CarCheck.co.uk page 5/12



## Tax & MOT check



Tax status	Valid until 1 April
Days left	338
MOT expiry date	21 March 2025
Full MOT history	See MOT history

### Tax calculation

Vehicle class	49
Band	В
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-

CarCheck.co.uk page 6/12



report date: 2024-03-28

### Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



### Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

Owner matery		
For how long did the current and previous owner(s) have this MINI? How many owners die Check it in the premium report and see all owner registrations. Download the full report is		∋?
********		
***************************************		
	Maya infa	
	More info	>
Plate changes		
See in this check if this MINI had different number plates.		
Number of plates		,
Current registration	UK NE	
Plate since		
Current registration	UK NE	
Plate since		
	More info	>

CarCheck.co.uk page 9/12



## Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MINI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2014-03-28
Last registration	2024-03-22
Complete history	See info



Registration #1	2014-03-28	17 mi
Registration #2	2016-08-11	16.669 mi
Registration #3	2017-03-21	20.507 mi
Registration #4	2018-06-04	25.907 mi
Registration #5	2019-07-16	33.788 mi
Registration #6	2020-06-17	39.563 mi
Registration #7	2021-07-13	46.479 mi
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		D.777 es

More info >

CarCheck.co.uk page 11/12



# Car features

50225	Air conditioning
50295	
50482	
50501	
50566	
50567	
50569	

# Safety ratings

NCAP rating	****
Video	see crash video



# Dimensions & weight

Width	1683 mm
Height	1426 mm
Length	3961 mm
Wheel base	2547 mm
Kerb weight	1185 kg
Max. allowed weight	1685 kg

# Additional information

Fuel tank capacity	40	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5 page 12	/12

Number of axles 2

Engine number 94878805