





report date: 2024-03-29

General information

Make	HONDA
Model	CR-V I-VTEC EX
Colour	Blue
Year of manufacture	2017
Top speed	113 mph
0 - 60 mph	12.3 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	153 BHP
Max. torque	192 Nm at 4.300 rpm
Engine capacity	1.997 сс
Cylinders	4
Fuel type	Petrol
Consumption city	28.0 mpg
Consumption extra urban	45.6 mpg
Consumption combined	36.7 mpg
CO2 emission	179 g/km
CO2 label	1



CarCheck.co.uk page 1/11



Internet history

Entry 3

Date 2021-06-24

Pictures 29

Listing price <u>View report</u>









source: heycar.co.uk

Entry 2

Date 2021-06-23


Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1

Date 2021-06-06

Pictures 10

Listing price <u>View report</u>









source: autoonline.co.uk

CarCheck.co.uk page 2/11



MOT history

MOT expiry date	2024-05-24
MOT pass rate	83 %
MOT passed	5
Failed MOT tests	1
Total advice items	13
Total items failed	2

MOT #6		2023-05-25 14:34
MOT test	number	395241482202
Result		✓ Passed
Next expi	y date	2024-05-24
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakene	d (1.1.14 (a) (ii))
Advice	Advice Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))		
Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))		
Advice	Advice Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

CarCheck.co.uk page 3/11



Result

LD17JSX report date: 2024-03-29

✓ Passed

MOT #5 2022-05-17 10:00

MOT test number 348656689249

Advice Nearside Front Tyre worn close to legal limit/worn on edge outer edge (5.2.3 (e))

Advice Offside Front brake pads approx 4mm remaining

Advice Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Nearside Front brake pads approx 4mm remaining

Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #4 2021-05-18 14:55

MOT test number 111818562324

MOT #3 2021-05-18 14:55

MOT test number 491942189007

Result ★ Failed

Pass with rectification Offside Front Headlamp aim too high (4.1.2 (a))

Pass with rectification Nearside Front Headlamp aim too high (4.1.2 (a))

MOT #2 2020-06-23 09:04

MOT test number 464009849097

Result ✓ Passed

MOT #1 2020-03-31 20:35

MOT test number 467380967958

Advice COVID-19 6 MONTH EXTENSION

CarCheck.co.uk page 4/11



Tax & MOT check



Tax status	Valid until 1 August
Days left	95
MOT expiry date	24 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	J
First licence fee (12 months)	£ 1.040,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 5/11



Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Type	



Extra HONDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this HONDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

For how long did the current and previous owner(s) have this HONDA? How many owners have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.	

······	

	More info >
Plate changes	
See in this check if this HONDA had different number plates.	
Number of plates	
Current registration	NK SIK
Plate since	
Current registration	OK SIN
Plate since	
	More info >

CarCheck.co.uk page 8/11



Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HONDA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 9/11



Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2017-04-01
Last registration	2023-05-25
Complete history	See info



Registration #1	2017-04-01	10 mi
Registration #2	2020-06-23	12.102 mi
Registration #3	2021-05-18	13.397 mi
Registration #4	2021-05-18	13.397 mi
Registration #5		9.79 66
Registration #6		71.777 66
Registration #7		9.777 es
Registration #8		11.777 66
Registration #9		11.777 es

More info >

CarCheck.co.uk page 10/11



Safety ratings

NCAP rating	****
Adult	93%
Children	74%
Pedestrian	68%
Safety systems	66%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	2095 mm
Height	1685 mm
Length	4605 mm
Wheel base	2630 mm
Kerb weight	1645 kg
Max. allowed weight	2100 kg

Additional information

Fuel tank capacity	58 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Engine number	R20A94010368

CarCheck.co.uk page 11/11