



HYUNDAI



report date: 2024-03-28

General information

| | |
|---------------------|----------------------------|
| Make | HYUNDAI |
| Model | I30 CRDI ACTIVE BLUE DRIVE |
| Colour | Grey |
| Year of manufacture | 2014 |
| Top speed | 115 mph |
| 0 - 60 mph | 11.5 seconds |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 108 BHP |
| Max. torque | 260 Nm at 2.750 rpm |
| Engine capacity | 1.582 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 68.9 mpg |
| Consumption extra urban | 80.7 mpg |
| Consumption combined | 76.3 mpg |
| CO2 emission | 97 g/km |
| CO2 label | A |



**MOT history**

| | |
|---------------------------|------------|
| MOT expiry date | 2022-04-27 |
| MOT pass rate | 83 % |
| MOT passed | 5 |
| Failed MOT tests | 1 |
| Total advice items | 10 |
| Total items failed | 3 |

| | |
|-------------------------|------------------|
| MOT #6 | 2021-04-28 13:51 |
| MOT test number | 369135509049 |
| Result | ✓ Passed |
| Next expiry date | 2022-04-27 |

| | |
|------------------------|------------------|
| MOT #5 | 2020-07-31 10:07 |
| MOT test number | 574759634086 |
| Result | ✓ Passed |

| | |
|------------------------|------------------|
| MOT #4 | 2019-06-24 09:20 |
| MOT test number | 305817496515 |
| Result | ✓ Passed |

| | |
|------------------------|------------------|
| MOT #3 | 2018-07-04 15:53 |
| MOT test number | 181467607257 |
| Result | ✓ Passed |

Advice Vehicles internal headlight adjuster altered to recheck lights

Advice Rear wiper blade defective

Advice Items removed from driver's view prior to test

Advice Nearside rear fog lamp insecure

Minor Nearside Rear reflector insecure (4.8.1 (b) (i))

**MOT #2**

2018-07-04 11:53

MOT test number

588411971969

Result**✗ Failed****Fail**

Parking brake efficiency below requirements (1.4.2 (a) (i))

Minor

Nearside Rear reflector insecure (4.8.1 (b) (i))

Advice

Items removed from driver's view prior to test

Advice

Nearside rear fog lamp insecure

Fail

Windscreen wiper does not clear the windscreen effectively both (3.4 (b) (ii))

Fail

Nearside Parking brake inoperative on one side low effort (1.4.1 (a))

Advice

Vehicles internal headlight adjuster altered to recheck lights

Advice

Rear wiper blade defective

MOT #1

2017-03-07 13:43

MOT test number

550672307816

Result**✓ Passed**



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|--------------|
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

| | |
|----------------------|------------|
| Number of plates | 1 |
| Current registration | |
| Plate since | 2019-09-29 |
| Current registration | |
| Plate since | 2019-09-29 |

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

| | |
|-------------------|-------------|
| Finance company | XXXXXXXX XX |
| Date of agreement | XXXXXXXX XX |
| Agreement type | XXXXXXXX XX |
| Agreement term | XXXXXXXX XX |
| Agreement number | XXXXXXXX XX |
| Contact info | XXXXXXXX XX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 7 |
| First mileage registration | 2014-03-01 |
| Last registration | 2021-04-28 |
| Complete history | See info |



| | | |
|-----------------|------------|-----------|
| Registration #1 | 2014-03-01 | 15 mi |
| Registration #2 | 2017-03-07 | 32.264 mi |
| Registration #3 | 2018-07-04 | 47.987 mi |
| Registration #4 | 2018-07-04 | 47.987 mi |
| Registration #5 | 2019-05-29 | 55,377 mi |
| Registration #6 | 2019-05-29 | 55,377 mi |
| Registration #7 | 2021-04-28 | 55,377 mi |

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

| | |
|----------------|---------------------------------|
| NCAP rating | ★★★★★ |
| Adult | 90% |
| Children | 90% |
| Pedestrian | 67% |
| Safety systems | 86% |
| Overall rating | 85% |
| Video | see crash video |



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1780 mm |
| Height | 1470 mm |
| Length | 4300 mm |
| Wheel base | 2650 mm |
| Kerb weight | 1360 kg |
| Max. allowed weight | 1810 kg |

Additional information

| | |
|--------------------|------------------|
| Fuel tank capacity | 53 l |
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats | 5 |

| | |
|---------------|--------------|
| Engine number | D4FBEZ568579 |
|---------------|--------------|