



report date: 2024-03-28

General information

Make	VAUXHALL
Model	ANTARA EXCLUSIV CDTI S/S
Colour	Grey
Year of manufacture	2012
Top speed	117 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	161 BHP
Max. torque	350 Nm at 2.000 rpm
Engine capacity	2.231 cc
Cylinders	4
Fuel type	Diesel
Consumption city	32.8 mpg
Consumption extra urban	50.4 mpg
Consumption combined	42.8 mpg
CO2 emission	170 g/km
CO2 label	H





Internet history

Entry 1

Date	2021-06-23
Pictures	8
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date 2024-04-21**MOT pass rate** 64 %**MOT passed** 9**Failed MOT tests** 5**Total advice items** 25**Total items failed** 10**MOT #14** 2023-04-22 07:30**MOT test number** 492141531488**Result** ✓ Passed**Next expiry date** 2024-04-21**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge Tread depth @ 3 mm and worn on outer edge (5.2.3 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge Tread depth @ 3 mm, worn on outer edge, smooth on inner (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge Tread depth @ 3 mm, worn on inner edge, smooth on outer (5.2.3 (e))**MOT #13** 2023-04-21 10:58**MOT test number** 342935818508**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge Tread depth @ 3 mm, worn on inner edge, smooth on outer (5.2.3 (e))**Fail** Exhaust emissions exceed default limit of 1.5m-1 (8.2.2.2 (b))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge Tread depth @ 3 mm and worn on outer edge (5.2.3 (e))**Fail** Rear Reversing lamp inoperative (4.6.1 (a))**Advice** Offside Front Tyre worn close to legal limit/worn on edge Tread depth @ 3 mm, worn on outer edge, smooth on inner (5.2.3 (e))**Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))

**MOT #12** 2021-07-16 16:13**MOT test number** 759549016840**Result** ✓ Passed**MOT #11** 2021-07-13 10:16**MOT test number** 255941630102**Result** ✗ Failed**Fail** Exhaust particulate filter obviously defective (8.2.2.1 (a))**Fail** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))**MOT #10** 2021-01-29 11:05**MOT test number** 394568242115**Result** ✓ Passed**Advice** Suspension arm pin or bush worn but not resulting in excessive movement offside and nearside front lower (5.3.4 (a) (i))**Advice** Prop shaft is missing**MOT #9** 2021-01-29 11:05**MOT test number** 963564014251**Result** ✗ Failed**Pass with rectification** Offside Front Position lamp not working (4.2.1 (a) (ii))**Advice** Prop shaft is missing**Advice** Suspension arm pin or bush worn but not resulting in excessive movement offside and nearside front lower (5.3.4 (a) (i))**MOT #8** 2020-02-10 11:49**MOT test number** 547885905658**Result** ✓ Passed**Advice** Prop shaft is missing

**MOT #7** 2020-02-10 10:06**MOT test number** 800222010814**Result** ✗ Failed**Advice** Prop shaft is missing**Fail** Nearside Reversing lamp inoperative (4.6.1 (a))**Fail** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Fail** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))**MOT #6** 2019-02-02 08:53**MOT test number** 516360781690**Result** ✓ Passed**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Prop shaft is missing**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #5** 2019-02-02 08:53**MOT test number** 327476557893**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Pass with rectification** Offside Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Prop shaft is missing

**MOT #4** 2018-02-13 09:08**MOT test number** 922550028410**Result** ✓ Passed

- Advice** Nearside Front tyre wearing on edges
- Advice** Offside Rear disc slightly scored
- Advice** Offside Front Seat belt stitching slightly frayed (5.2.2b)
- Advice** Offside Front tyre wearing on edges

MOT #3 2016-12-07 10:27**MOT test number** 794823391943**Result** ✓ Passed**MOT #2** 2016-10-01 08:23**MOT test number** 925937545504**Result** ✓ Passed

- Advice** Nearside Rear Nail in tyre
- Advice** Power steering component(s) has slight seepage from a component steering rack (2.3.3b)

MOT #1 2015-09-28 16:01**MOT test number** 496172963339**Result** ✓ Passed

- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓
Taxed

Tax due:
1 July 2024

✗
MOT

Expired:
21 April 2024

Tax status	Valid until 1 July
Days left	62
MOT expiry date	21 April 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 CK62DLY
Plate since	2019-06-29
Current registration	 CK62DLY
Plate since	2019-06-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2012-10-02
Last registration	2023-04-22
Complete history	See info



Registration #1	2012-10-02	27 mi
Registration #2	2015-09-28	26.611 mi
Registration #3	2016-10-01	34.521 mi
Registration #4	2016-12-07	35.219 mi
Registration #5	2018-02-13	45.629 mi
Registration #6	2019-02-02	51.230 mi
Registration #7	2019-02-02	51.230 mi
Registration #8	2020-02-10	62.454 mi
Registration #9	2020-02-10	62.454 mi
Registration #10	2020-02-10	62.454 mi
Registration #11	2020-02-10	62.454 mi
Registration #12	2020-02-10	62.454 mi
Registration #13	2020-02-10	62.454 mi
Registration #14	2020-02-10	62.454 mi
Registration #15	2020-02-10	62.454 mi
Registration #16	2020-02-10	62.454 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	95%
Children	84%
Pedestrian	46%
Safety systems	71%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	2085 mm
Height	1717 mm
Length	4596 mm
Wheel base	2707 mm
Kerb weight	1836 kg
Max. allowed weight	2505 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	172361K