



report date: 2024-03-28

General information

Make	VOLVO
Model	XC90 D5 S AWD
Colour	Grey
Year of manufacture	2009
Top speed	118 mph
0 - 60 mph	11.1 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	185 BHP
Max. torque	400 Nm at 2.000 rpm
Engine capacity	2.401 cc
Cylinders	5
Fuel type	Diesel
Consumption city	25.5 mpg
Consumption extra urban	40.4 mpg
Consumption combined	33.2 mpg
CO2 emission	224 g/km
CO2 label	K



**MOT history**

MOT expiry date	2021-10-14
MOT pass rate	90 %
MOT passed	9
Failed MOT tests	1
Total advice items	15
Total items failed	1

MOT #10	2020-10-15 12:50
MOT test number	650289577195
Result	✓ Passed
Next expiry date	2021-10-14
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge and both front tyres worn on edge (5.2.3 (e))

MOT #9	2019-10-07 09:09
MOT test number	943893158053
Result	✓ Passed

MOT #8	2018-05-30 10:04
MOT test number	257064556998
Result	✓ Passed
Advice	Engine Covers And Undertrays Fitted
Advice	Offside Rear Upper Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #7** 2018-05-30 10:04**MOT test number** 484081469233**Result** ✗ Failed**Advice** Offside Rear Upper Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Pass with rectification** Offside Rear Position lamp not working (4.2.1 (a))**Advice** Engine Covers And Undertrays Fitted**MOT #6** 2017-05-09 10:50**MOT test number** 801069377861**Result** ✓ Passed**Advice** Nearside Front tyre slightly worn outside edge**Advice** Front Play in steering rack inner joint(s) both**Advice** Offside Rear Upper Suspension arm rubber bush deteriorated but not resulting in excessive movement front bush (2.4.G.2)**Advice** Engine covers and under covers fitted**Advice** Nearside Front Ball joint has slight play (2.2.B.1f)**MOT #5** 2016-05-31 15:47**MOT test number** 374107271369**Result** ✓ Passed**Advice** Plastic engine, under tray and floor covers fitted at time of test.

**MOT #4** 2015-05-08 11:55**MOT test number** 506738625110**Result** ✓ Passed**Advice** Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Notice** Under-trays fitted obscuring some underside components**Advice** Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Notice** Childseat fitted o/s/r.**MOT #3** 2014-03-19 16:51**MOT test number** 118968774438**Result** ✓ Passed**MOT #2** 2013-03-29 13:09**MOT test number** 168628583412**Result** ✓ Passed**MOT #1** 2012-03-05 15:12**MOT test number** 818315362023**Result** ✓ Passed



Tax & MOT check

✕
Untaxed

Tax expired:
28 December 2020

✕
MOT

Expired:
14 October 2021

Tax status	Expired at 28 December 2020
Days left	1217 days too late
MOT expiry date	14 October 2021
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	LR09GVT
Plate since	2019-09-28
Current registration	LR09GVT
Plate since	2019-09-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2009-03-31
Last registration	2020-10-15
Complete history	See info



Registration #1	2009-03-31	27 mi
Registration #2	2012-03-05	30.508 mi
Registration #3	2013-03-29	39.765 mi
Registration #4	2014-03-19	45.969 mi
Registration #5	2015-05-08	61.129 mi
Registration #6	2016-05-31	74.133 mi
Registration #7	2017-05-20	85.277 mi
Registration #8	2018-05-20	96.421 mi
Registration #9	2019-05-20	107.565 mi
Registration #10	2020-05-20	118.709 mi
Registration #11	2020-10-15	129.853 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1898 mm
Height	1743 mm
Length	4798 mm
Wheel base	2857 mm
Kerb weight	2135 kg
Max. allowed weight	2750 kg

Additional information

Fuel tank capacity	68 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Number of axles	2
Engine number	692724