



report date: 2024-03-29

General information

Make	VOLVO
Model	XC90 D5 SE AWD
Colour	Silver
Year of manufacture	2010
Top speed	118 mph
Gearbox	6 speed automatic

Engine & fuel consumption

Power	185 BHP
Max. torque	400 Nm at 2.000 rpm
Engine capacity	2.400 cc
Cylinders	5
Fuel type	Diesel
Consumption city	25.5 mpg
Consumption extra urban	40.4 mpg
Consumption combined	33.2 mpg
CO2 emission	224 g/km
CO2 label	K





Internet history

Entry 1

Date	2021-02-06
Pictures	1
Listing price	View report



source: autoonline.co.uk



MOT history

MOT expiry date	2023-10-22
MOT pass rate	67 %
MOT passed	10
Failed MOT tests	5
Total advice items	18
Total items failed	14

MOT #15	2022-09-26 11:21
MOT test number	285549359956
Result	✓ Passed
Next expiry date	2023-10-22
Minor	Offside Windscreen wiper blade defective (3.4 (b) (i))

MOT #14	2021-10-01 12:17
MOT test number	552235236003
Result	✓ Passed

MOT #13	2020-10-15 16:34
MOT test number	563137417629
Result	✓ Passed

**MOT #12** 2020-10-14 12:04**MOT test number** 614433046247**Result** ✗ Failed**Fail** Offside Front Seat belt buckle not functioning as intended (7.1.2 (d))**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))**Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))**Fail** Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Fail** Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))**MOT #11** 2019-10-17 14:35**MOT test number** 131983859289**Result** ✓ Passed**MOT #10** 2018-10-04 14:32**MOT test number** 173989939837**Result** ✓ Passed**Advice** Nearside front and back wheel arch damaged cover with tape**Advice** Nearside Body , door and panel wing all damaged dent but not sticking out or Sharpe edge**Advice** Engine cover and Under-Tray cover fitted



MOT #9	2018-10-04 10:08
MOT test number	474867843973
Result	✗ Failed
Advice	Engine cover and Under-Tray cover fitted
Fail	Nearside Rear Rear reflector missing (4.8.2 (a) (ii))
Advice	Nearside front and back wheel arch damaged cover with tape
Minor	Nearside Rear Position lamp light intensity obviously reduced (4.2.3 (a) (i))
Advice	Nearside Body , door and panel wing all damaged dent but not sticking out or Sharpe edge

MOT #8	2017-09-27 15:17
MOT test number	400814368015
Result	✓ Passed
Advice	Under tray fitted
Advice	Engine cover fitted

**MOT #7** 2017-09-26 14:59**MOT test number** 365555062634**Result** ✗ Failed**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**Advice** Under tray fitted**Fail** Nearside Front position lamp(s) not working Sidelight (1.1.A.3b)**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)**Advice** Engine cover fitted**Fail** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**Fail** Offside Rear Suspension arm damaged and seriously weakened Control arm (2.4.G.1)**MOT #6** 2016-09-29 15:44**MOT test number** 702020646292**Result** ✓ Passed**Advice** Under tray fitted**Advice** Engine cover fitted**MOT #5** 2015-09-29 14:12**MOT test number** 163657600176**Result** ✓ Passed**MOT #4** 2014-10-15 12:49**MOT test number** 655798684255**Result** ✓ Passed



MOT #3	2014-10-15 12:49
MOT test number	128598784228
Result	✗ Failed
Pass with rectification	Rear Fuel system component leaking (7.2.3)
Pass with rectification	Offside Rear fog lamp not working (1.3.2b)
Pass with rectification	Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

MOT #2	2013-10-17 16:03
MOT test number	619190993289
Result	✓ Passed

MOT #1	2013-10-17 16:03
MOT test number	279040393269
Result	✗ Failed
Pass with rectification	Front Brake pad(s) less than 1.5 mm thick (3.5.1g)
Pass with rectification	Front brake disc in such a condition that it is seriously weakened (3.5.1i)



Tax & MOT check

✕
Untaxed

Tax expired:
30 November 2023

✕
MOT

Expired:
22 October 2023

Tax status	Expired at 30 November 2023
Days left	152 days too late
MOT expiry date	22 October 2023
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2010-10-22
Last registration	2022-09-26
Complete history	See info



Registration #1	2010-10-22	20 mi
Registration #2	2013-10-17	42.171 mi
Registration #3	2014-10-15	57.055 mi
Registration #4	2015-09-29	69.127 mi
Registration #5	2016-09-29	78.505 mi
Registration #6	2017-09-26	84.674 mi
Registration #7	2017-09-27	84.674 mi
Registration #8	2018-10-04	91.607 mi
Registration #9	2019-09-26	95.377 mi
Registration #10	2020-09-26	95.377 mi
Registration #11	2021-09-26	95.377 mi
Registration #12	2022-09-26	95.377 mi
Registration #13	2023-09-26	95.377 mi
Registration #14	2024-03-29	95.377 mi
Registration #15	2024-03-29	95.377 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1898 mm
Height	1784 mm
Length	4798 mm
Wheel base	2857 mm
Kerb weight	2148 kg
Max. allowed weight	2750 kg

Additional information

Fuel tank capacity	68 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Number of axles	2
Engine number	871663