





report date: 2024-03-29

General information

Make	FORD
Model	TRANSIT 260 LR P/V
Colour	White
Year of manufacture	2011
Gearbox	5 speed Manual

Engine & fuel consumption

Power	84 BHP
Max. torque	250 Nm at 1.500 rpm
Engine capacity	2.198 cc
Cylinders	4
Fuel type	Diesel



CarCheck.co.uk page 1/13



Internet history

Entry 1

Date 2021-09-12

Pictures 17

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/13



MOT history

MOT expiry date	2022-09-14
MOT pass rate	57 %
MOT passed	8
Failed MOT tests	6
Total advice items	9
Total items failed	16

MOT #14	2021-09-15 13:07	
MOT test number	613005187717	
Result	✓ Passed	
Next expiry date 2022-09-1		
Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))		
Advice Nearside Front Steering linkage ball joint has slight play steering arm at ra	ack (2.1.3 (b) (i))	

MOT #13	2020-10-27 17:26
MOT test number	985616112326
Result	✓ Passed
Advice Both sills Have Minor Rust And Damage, Not Affecting Stability.	

MOT #12	2020-10-27 17:26
MOT test number	281263414074
Result	X Failed
Pass with rectification	Front Tyre tread depth below requirements of 1.6mm Both (5.2.3 (e))
Pass with rectification lamps (4.7.1 (b) (ii))	Nearside Registration plate lamp inoperative in the case of a single lamp or all
Pass with rectification	Front Tyre tread depth below requirements of 1.6mm both (5.2.3 (e))
Pass with rectification	Front Position lamp not working Both (4.2.1 (a) (ii))
Advice Both sills Have N	linor Rust And Damage, Not Affecting Stability.

CarCheck.co.uk page 3/13



MOT #11 2019-06-12 12:37

MOT test number 457916861603

Result
✓ Passed

Advice Front Anti-roll bar ball joint has slight play both side (5.3.4 (a) (i))

Advice Nearside Front Wheel bearing has slight play (5.1.3 (a) (i))

MOT #10 2019-06-12 10:06

MOT test number 835449287817

Result X Failed

Advice Front Anti-roll bar ball joint has slight play both side (5.3.4 (a) (i))

Fail Offside Headlamp aim too high and too far to the left. (4.1.2 (a))

Advice Nearside Front Wheel bearing has slight play (5.1.3 (a) (i))

MOT #9 2018-06-07 12:28

MOT test number 956947927006

Result ✓ Passed

MOT #8 2018-06-07 09:14

MOT test number 431318547859

Result ★ Failed

Fail Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))

Minor Nearside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Fail Nearside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))

Fail Offside Front Upper Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

MOT #7 2017-06-08 12:25

MOT test number 378043066317

Result
✓ Passed

CarCheck.co.uk page 4/13



MOT test number

Result

Fail Offside Registration plate lamp not working (1.1.C.1d)

Fail Front Brake pad(s) less than 1.5 mm thick (3.5.1g)

Fail Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)

MOT #5		2016-05-31 15:51
MOT test number		646452017957
Result		✓ Passed
MOT #4		2015-06-05 12:34
MOT test number		797986255110
Result		✓ Passed
MOT #3		2015-06-05 12:34
MOT test number		937496155133
Result		🗙 Failed
Pass with rectification	Nearside Front Headlamp not working on dipped beam (1.7.5a)	

MOT #2	2014-05-07 12:37
MOT test number	258927224159
Result	✓ Passed

CarCheck.co.uk page 5/13



MOT #1 2014-05-07 12:37

MOT test number 217827024184

Result ★ Failed

Pass with rectification Offside Front Headlamp aim too low (1.8)

Pass with rectification Offside Registration plate lamp not working (1.1.C.1d)

Pass with rectification Centre Rear Upper Stop lamp not working (1.2.1b)

CarCheck.co.uk page 6/13



Tax & MOT check



X MOT

Expired: 14 September 2022

Tax status Expired at 1 March 2022

Days left 790 days too late

MOT expiry date 14 September 2022

Full MOT history See MOT history

CarCheck.co.uk page 7/13



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner history

Owner matery	
For how long did the current and previous owner(s) have this FORD? How many owners of Check it in the premium report and see all owner registrations. Download the full report is	

THE STATE OF THE S	
THE STREET STREE	
	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	,
Current registration	UK UK
Plate since	
Current registration	UK SIE
Plate since	
	More info >

CarCheck.co.uk page 10/13



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact into

More info >


CarCheck.co.uk page 11/13



Mileage check

Registration #14

Odometer	In miles
Mileage registrations	14
First mileage registration	2011-06-30
Last registration	2021-09-15
Complete history	See info



Registration #1	2011-06-30	19 mi
Registration #2	2014-05-07	79.676 mi
Registration #3	2015-06-05	103.647 mi
Registration #4	2016-05-31	117.637 mi
Registration #5	2017-06-08	131.119 mi
Registration #6	2017-06-08	131.119 mi
Registration #7	2018-06-07	146.035 mi
Registration #8		111,7177 ess
Registration #9		11.777 esi
Registration #10		11.777 es
Registration #11		9.70 es
Registration #12		11.777 es
Registration #13		11.777 es

mn.n.n

More info >

77.777 86

CarCheck.co.uk page 12/13



Car features

50225	Air conditioning
50295	
60482	
0501	
0566	
0567	
60569	

Dimensions & weight

Width	2360 mm
Height	1989 mm
Length	4863 mm
Kerb weight	1699 kg
Max. allowed weight	2600 kg

Additional information

Fuel tank capacity	80 I
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	3
Engine number	AA82133

CarCheck.co.uk page 13/13