





report date: 2024-03-28

General information

Make	VOLVO
Model	V60 D5 TWIN ENGINE SE NAV
Colour	Silver
Year of manufacture	2016
Top speed	130 mph
0 - 60 mph	6.7 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	231 BHP
Max. torque	620 Nm at 1.500 rpm
Engine capacity	2.400 cc
Cylinders	5
Fuel type	Electric / Diesel
Consumption combined	156.9 mpg
CO2 emission	48 g/km
CO2 label	Α



CarCheck.co.uk page 1/11



Internet history

Entry 2

Date 2021-07-27

Pictures 29

Listing price <u>View report</u>









source: yesauto.com

Entry 1

Date	2021-07-23
Pictures	29

11000100

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/11



YP66ZJO

report date: 2024-03-28

MOT	history
-----	---------

MOT expiry date	2024-08-07
MOT pass rate	83 %
MOT passed	5
Failed MOT tests	1
Total advice items	1
Total items failed	1

MOT #6	2023-08-08 10:46
MOT test number	599197440116
Result	✓ Passed
Next expiry date	2024-08-07

MOT #5	2022-07-19 08:33
MOT test number	173077896413
Result	✓ Passed

MOT #4	2021-07-23 12:46
MOT test number	221912982976
Result	✓ Passed

MOT #3	2020-10-19 09:53
MOT test number	989757550441
Result	✓ Passed

MOT #2		2020-10-19 09:53
MOT test number		431585119128
Result		× Failed
Pass with rectification	Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))	

CarCheck.co.uk page 3/11



MOT #1

MOT test number

893812029064

Result

Advice Nearside Front Outer Road wheel slightly distorted (5.2.2 (c) (i))

CarCheck.co.uk page 4/11



Tax & MOT check



Tax status	Valid until 1 August
Days left	95
MOT expiry date	7 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	59
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable


CarCheck.co.uk page 5/11



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report here for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners have? Check it in the premium report and see all owner registrations. Download the full r	

	More info >
Plate changes	
See in this check if this VOLVO had different number plates.	
Number of plates	,
Current registration	UK ZIN
Plate since	
Current registration	UK ZIS
Plate since	
	More info >

CarCheck.co.uk page 8/11



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLVO is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Control info	

Contact info


More info >

CarCheck.co.uk page 9/11



Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2016-11-04
Last registration	2023-08-08
Complete history	See info



Registration #1	2016-11-04	7 mi
Registration #2	2019-10-21	92.045 mi
Registration #3	2020-10-19	114.928 mi
Registration #4	2020-10-19	114.928 mi
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		D.227 es

More info >

CarCheck.co.uk page 10/11



Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	94%
Children	82%
Pedestrian	64%
Safety systems	100%
Overall rating	86%
Video	see crash video



Dimensions & weight

Width	1899 mm
Height	1484 mm
Length	4635 mm
Wheel base	2776 mm
Kerb weight	2024 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	45 I	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5 page 3	11/11

Number of axles 2

Engine number 1693947