




report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	BEETLE 8V
Colour	Silver
Year of manufacture	2003
Top speed	111 mph
0 - 60 mph	12.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	102 BHP
Max. torque	147 Nm at 3.800 rpm
Engine capacity	1.596 cc
Cylinders	4
Fuel type	Petrol
Consumption city	26.9 mpg
Consumption extra urban	47.1 mpg
Consumption combined	36.7 mpg
CO2 emission	185 g/km
CO2 label	I






Internet history

Entry 2


Date	2021-06-22
Pictures	9
Listing price	View report



source: [autotrader.co.uk](#)

Entry 1

Date	2021-06-08
Pictures	9
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-07-10
MOT pass rate	64 %
MOT passed	18
Failed MOT tests	10
Total advice items	37
Total items failed	24

MOT #28	2023-07-11 15:57
MOT test number	135357749299
Result	✓ Passed
Next expiry date	2024-07-10
Advice	Rear Tyre slightly damaged/cracking or perishing both side (5.2.3 (d) (ii))

MOT #27	2023-07-07 15:29
MOT test number	791453941391
Result	✗ Failed
Fail	Front Tyre has a tear, caused by separation or partial failure of its structure both side (5.2.3 (d) (ii))
Pass with rectification	Windscreen washer provides insufficient washer liquid (3.5 (a))
Fail	Nearside Front Position lamp not working (4.2.1 (a) (ii))
Fail	Front Track rod end ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt both side (2.1.3 (g) (ii))
Advice	Rear Tyre slightly damaged/cracking or perishing both side (5.2.3 (d) (ii))
Pass with rectification	Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
Fail	Nearside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

**MOT #26**

2022-04-02 12:49

MOT test number

753753926304

Result

✓ Passed

Minor Nearside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

Minor Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

Advice Offside Rear Coil spring corroded (5.3.1 (b) (i))

MOT #25

2022-04-02 12:49

MOT test number

154944356975

Result

✗ Failed

Pass with rectification Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

Minor Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

Advice Offside Rear Coil spring corroded (5.3.1 (b) (i))

Minor Nearside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

MOT #24

2021-04-15 10:25

MOT test number

941879249881

Result

✓ Passed

Advice Nearside Front Nail in tyre

Minor Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

**MOT #23**

2021-04-15 09:51

MOT test number

204596147682

Result**✗ Failed****Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Minor** Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**Fail** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))**Advice** Nearside Front Nail in tyre**MOT #22**

2020-05-22 12:11

MOT test number

924519814586

Result**✓ Passed****Advice** Eml on**MOT #21**

2020-05-22 12:11

MOT test number

117098155346

Result**✗ Failed****Pass with rectification** Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Eml on**MOT #20**

2019-04-18 14:11

MOT test number

687998207569

Result**✓ Passed**

**MOT #19** 2019-04-18 11:56**MOT test number** 657045396067**Result** ✗ Failed

- Fail** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Fail** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))
- Fail** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Fail** Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

MOT #18 2018-04-25 14:58**MOT test number** 619609838895**Result** ✓ Passed**MOT #17** 2017-04-10 11:54**MOT test number** 663142103642**Result** ✓ Passed**MOT #16** 2016-05-26 12:30**MOT test number** 645479228164**Result** ✓ Passed**MOT #15** 2015-06-01 13:04**MOT test number** 725662555175**Result** ✓ Passed

Advice Nearside Outer Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)

Notice Centre exhaust mounting fractured

**MOT #14**

2015-05-28 12:30

MOT test number

109858845105

Result**✗ Failed**

- Fail** Nearside Rear position lamp(s) insecure (1.1.A.3a)
- Fail** Nearside Rear Direction indicator insecure (1.4.A.2b)
- Notice** Centre exhaust mounting fractured
- Fail** Offside Rear Tyre has ply or cords exposed (4.1.D.1b)
- Fail** Supplementary Restraint System warning lamp indicates a fault (5.4.2)
- Fail** Nearside Stop lamp insecure (1.2.1a)
- Fail** Offside Front coil spring broken (2.4.C.1a)
- Advice** Nearside Outer Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)

MOT #13

2014-05-23 13:05

MOT test number

936323444196

Result**✓ Passed**

- Notice** Engine covers fitted obscuring some components in the engine bay
- Notice** Slight brake bind offside rear
- Notice** Under-trays fitted obscuring some underside components
- Notice** Offside rear tyre ON LEGAL LIMIT
- Notice** Centre exhaust mounting insecure
- Notice** Items removed from driver's view prior to test

**MOT #12** 2014-05-23 13:05**MOT test number** 208513144187**Result** ✗ Failed**Notice** Under-trays fitted obscuring some underside components**Notice** Offside rear tyre ON LEGAL LIMIT**Notice** Centre exhaust mounting insecure**Notice** Items removed from driver's view prior to test**Notice** Engine covers fitted obscuring some components in the engine bay**Pass with rectification** Offside Headlamp aim too far to the right (1.8)**Notice** Slight brake bind offside rear**MOT #11** 2013-11-21 15:26**MOT test number** 177685523301**Result** ✓ Passed**MOT #10** 2013-11-18 09:11**MOT test number** 889082823385**Result** ✗ Failed**Fail** Supplementary Restraint System warning lamp indicates a fault (5.4.2)**Notice** Both rear tyres wearing on edges**Advice** Front coil spring corroded (2.4.C.1b)**MOT #9** 2013-05-24 10:56**MOT test number** 195644643185**Result** ✓ Passed

**MOT #8** 2012-05-11 11:35**MOT test number** 448572732129**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #7** 2012-05-09 09:14**MOT test number** 567170532198**Result** ✗ Failed**Fail** Seat belt retracting mechanism defective (5.2.5b)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Front Tyre worn close to the legal limit (4.1.E.1)**MOT #6** 2010-12-29 10:51**MOT test number** 533273860342**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Front Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**MOT #5** 2009-12-09 10:28**MOT test number** 920313649300**Result** ✓ Passed**MOT #4** 2008-12-18 16:01**MOT test number** 270943058349**Result** ✓ Passed



MOT #3	2008-12-17 15:33
MOT test number	402612058385
Result	✗ Failed
<div><div>Fail</div>Nearside Headlamp aim beam image kick up to the offside (1.8)</div>	

MOT #2	2007-12-03 16:33
MOT test number	800557837322
Result	✓ Passed

MOT #1	2006-12-20 13:07
MOT test number	583394156332
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
10 July 2024

Tax status	Valid until 1 July
Days left	63
MOT expiry date	10 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history


Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	WR53CUA
Plate since	2024-03-28
Current registration	WR53CUA
Plate since	2024-03-28

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.


Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	30
First mileage registration	2003-12-10
Last registration	2023-07-11
Complete history	See info



Registration #1	2003-12-10	27 mi
Registration #2	2006-12-20	16.308 mi
Registration #3	2007-12-03	22.016 mi
Registration #4	2008-12-17	28.401 mi
Registration #5	2008-12-18	28.411 mi
Registration #6	2009-12-09	36.991 mi
Registration #7	2010-12-29	44.009 mi
Registration #8	2012-05-09	52.088 mi
Registration #9	2012-05-11	52.101 mi
Registration #10	2013-05-24	55.079 mi
Registration #11	2013-11-18	57.253 mi
Registration #12	2013-11-21	57.253 mi
Registration #13	2014-05-23	62.415 mi
Registration #14	2015-05-28	67.752 mi
Registration #15	2015-06-01	67.754 mi
Registration #16	2015-06-01	67.754 mi
Registration #17	2015-06-01	67.754 mi
Registration #18	2015-06-01	67.754 mi
Registration #19	2015-06-01	67.754 mi
Registration #20	2015-06-01	67.754 mi
Registration #21	2015-06-01	67.754 mi
Registration #22	2015-06-01	67.754 mi
Registration #23	2015-06-01	67.754 mi
Registration #24	2015-06-01	67.754 mi
Registration #25	2015-06-01	67.754 mi
Registration #26	2015-06-01	67.754 mi

Registration #27	2025-25-25	25,252 442
Registration #28	2025-25-25	25,252 442
Registration #29	2025-25-25	25,252 442
Registration #30	2025-25-25	25,252 442

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1724 mm
Height	1498 mm
Length	4081 mm
Wheel base	2508 mm
Kerb weight	1385 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of axles	2

Engine number

BFS 009754