



WM66ZVD

report date: 2024-03-29

General information

| | |
|---------------------|-------------------|
| Make | NISSAN |
| Model | LEAF ACENTA |
| Colour | Black |
| Year of manufacture | 2016 |
| Top speed | 87 mph |
| Gearbox | 1 speed automatic |

Engine & fuel consumption

| | |
|-------------|----------------------|
| Power | 107 BHP |
| Max. torque | 254 Nm at 10.500 rpm |
| Fuel type | Electricity |



LABEL UNKNOWN



Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-08-12 |
| Pictures | 12 |
| Listing price | View report |



source: cargurus.co.uk



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2025-04-06 |
| MOT pass rate | 92 % |
| MOT passed | 12 |
| Failed MOT tests | 1 |
| Total advice items | 5 |
| Total items failed | 2 |

| | |
|------------------|---|
| MOT #13 | 2024-04-04 09:06 |
| MOT test number | 400342930410 |
| Result | ✓ Passed |
| Next expiry date | 2025-04-06 |
| Minor | Nearside Obligatory mirror slightly damaged mirror glass slightly damaged (3.3 (b) (i)) |

| | |
|-----------------|------------------|
| MOT #12 | 2023-03-31 09:29 |
| MOT test number | 772060378936 |
| Result | ✓ Passed |

| | |
|-----------------|--|
| MOT #11 | 2022-03-31 11:56 |
| MOT test number | 164206355130 |
| Result | ✓ Passed |
| Minor | Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i)) |
| Advice | Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) |

| | |
|-----------------|------------------|
| MOT #10 | 2021-04-07 10:58 |
| MOT test number | 394007490493 |
| Result | ✓ Passed |

**MOT #9** 2020-10-12 11:57**MOT test number** 574655320359**Result** ✓ Passed**MOT #8** 2020-06-17 11:34**MOT test number** 355805569778**Result** ✓ Passed**MOT #7** 2019-10-08 10:01**MOT test number** 133789983678**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #6** 2019-09-05 09:10**MOT test number** 318443015337**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #5** 2019-03-06 08:40**MOT test number** 291596102980**Result** ✓ Passed**MOT #4** 2019-03-05 12:46**MOT test number** 635703016289**Result** ✗ Failed**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))



| | |
|-----------------|------------------|
| MOT #3 | 2018-09-06 15:33 |
| MOT test number | 312768330225 |
| Result | ✓ Passed |
| MOT #2 | 2018-03-19 10:35 |
| MOT test number | 908868415391 |
| Result | ✓ Passed |
| MOT #1 | 2017-09-29 09:57 |
| MOT test number | 126865449467 |
| Result | ✓ Passed |



Tax & MOT check

✓
Taxed

Tax due:
1 September 2024

✓
MOT

Expires:
6 April 2025

Tax status

Valid until 1 September

Days left

124

MOT expiry date

6 April 2025

Full MOT history

[See MOT history](#)



Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|--------------|
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |

More info >

Plate changes

See in this check if this NISSAN had different number plates.

| | |
|----------------------|----------------|
| Number of plates | 1 |
| Current registration | WM66ZVD |
| Plate since | 2024-03-29 |
| Current registration | WM66ZVD |
| Plate since | 2024-03-29 |

More info >



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.


| | |
|-------------------|-------------|
| Finance company | XXXXXXXX XX |
| Date of agreement | XXXXXXXX XX |
| Agreement type | XXXXXXXX XX |
| Agreement term | XXXXXXXX XX |
| Agreement number | XXXXXXXX XX |
| Contact info | XXXXXXXX XX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 15 |
| First mileage registration | 2016-12-29 |
| Last registration | 2024-04-04 |
| Complete history | See info |



| | | |
|------------------|------------|-----------|
| Registration #1 | 2016-12-29 | 28 mi |
| Registration #2 | 2017-09-29 | 9.685 mi |
| Registration #3 | 2018-03-19 | 16.412 mi |
| Registration #4 | 2018-09-06 | 28.802 mi |
| Registration #5 | 2019-03-05 | 41.728 mi |
| Registration #6 | 2019-03-06 | 41.753 mi |
| Registration #7 | 2019-09-05 | 52.807 mi |
| Registration #8 | 2019-10-08 | 54.746 mi |
| Registration #9 | 2019-10-08 | 54.746 mi |
| Registration #10 | 2019-10-08 | 54.746 mi |
| Registration #11 | 2019-10-08 | 54.746 mi |
| Registration #12 | 2019-10-08 | 54.746 mi |
| Registration #13 | 2019-10-08 | 54.746 mi |
| Registration #14 | 2019-10-08 | 54.746 mi |
| Registration #15 | 2019-10-08 | 54.746 mi |

More info >



Car features

The NISSAN factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Safety ratings

| | |
|----------------|---------------------------------|
| NCAP rating | ★★★★★ |
| Adult | 89% |
| Children | 83% |
| Pedestrian | 65% |
| Safety systems | 84% |
| Overall rating | 83% |
| Video | see crash video |



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1770 mm |
| Height | 1550 mm |
| Length | 4445 mm |
| Wheel base | 2700 mm |
| Kerb weight | 1538 kg |
| Max. allowed weight | 1945 kg |

Additional information

| | |
|-----------------|----------------|
| Fuel delivery | Not Applicable |
| Number of doors | 5 |
| Number of seats | 5 |
| Number of axles | 2 |

| | |
|---------------|---------|
| Engine number | 106424A |
|---------------|---------|