



SVI8ZGJ

report date: 2024-03-28

General information

| | |
|---------------------|----------------|
| Make | MAZDA |
| Model | 3 D SE-L NAV |
| Colour | Silver |
| Year of manufacture | 2018 |
| Top speed | 131 mph |
| 0 - 60 mph | 9.1 seconds |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 148 BHP |
| Max. torque | 380 Nm at 2.600 rpm |
| Engine capacity | 2.191 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 60.1 mpg |
| Consumption extra urban | 83.1 mpg |
| Consumption combined | 72.4 mpg |
| CO2 emission | 107 g/km |
| CO2 label | B |





Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-06-21 |
| Pictures | 1 |
| Listing price | View report |



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2025-03-28 |
| MOT pass rate | 67 % |
| MOT passed | 4 |
| Failed MOT tests | 2 |
| Total advice items | 5 |
| Total items failed | 6 |

MOT #62024-03-25 13:09

MOT test number145449512492

Result✓ Passed

Next expiry date2025-03-28

Advice Offside Front Service brake fluctuating, but not excessively (1.2.1 (e))**Advice** Nearside Front Service brake fluctuating, but not excessively (1.2.1 (e))

MOT #52024-03-21 14:00

MOT test number378138843203

Result✗ Failed

Fail Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))**Fail** Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))**Advice** Offside Front Service brake fluctuating, but not excessively (1.2.1 (e))**Fail** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Nearside Front Service brake fluctuating, but not excessively (1.2.1 (e))

MOT #42023-03-23 10:30

MOT test number642494643226

Result✓ Passed

Advice Front Tyre worn close to legal limit/worn on edge both (5.2.3 (e))



| | |
|-----------------|---|
| MOT #3 | 2022-03-28 11:23 |
| MOT test number | 282912765431 |
| Result | ✓ Passed |
| MOT #2 | 2021-03-27 11:59 |
| MOT test number | 847237491131 |
| Result | ✓ Passed |
| MOT #1 | 2021-03-26 14:19 |
| MOT test number | 931834517535 |
| Result | ✗ Failed |
| Fail | Offside Rear Brake disc significantly and obviously worn (1.1.14 (a) (i)) |
| Fail | Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii)) |
| Fail | Nearside Rear Brake disc significantly and obviously worn (1.1.14 (a) (i)) |



Tax & MOT check

✓
Taxed

Tax due:
1 July 2024

✓
MOT

Expires:
28 March 2025

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 July |
| Days left | 63 |
| MOT expiry date | 28 March 2025 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|---|------------|
| Vehicle class | 49 |
| Band | F |
| First licence fee (12 months) | £ 185,00,- |
| First licence fee diesel non RDE2 tested (12 months) | £ 210,00,- |
| Standard rate (12 months) | £ 180,00,- |
| Standard rate (6 months) | £ 99,00,- |
| Premium rate (12 months) | £ 570,00,- |
| Premium rate (6 months) | £ 313,50,- |



Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,299 |
| Auction value | £ 19,299 |
| Average private trade value | £ 19,299 |

More info >



Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|--------------|
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |

More info >

Plate changes

See in this check if this MAZDA had different number plates.

| | |
|----------------------|----------------|
| Number of plates | 1 |
| Current registration | SV18ZGJ |
| Plate since | 2019-03-28 |
| Current registration | SV18ZGJ |
| Plate since | 2019-03-28 |

More info >



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MAZDA is financed.

| | |
|-------------------|-------------|
| Finance company | XXXXXXXX XX |
| Date of agreement | XXXXXXXX XX |
| Agreement type | XXXXXXXX XX |
| Agreement term | XXXXXXXX XX |
| Agreement number | XXXXXXXX XX |
| Contact info | XXXXXXXX XX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 8 |
| First mileage registration | 2018-03-29 |
| Last registration | 2024-03-25 |
| Complete history | See info |



| | | |
|-----------------|------------|-----------|
| Registration #1 | 2018-03-29 | 18 mi |
| Registration #2 | 2021-03-26 | 34.131 mi |
| Registration #3 | 2021-03-27 | 34.135 mi |
| Registration #4 | 2024-03-25 | 34.135 mi |
| Registration #5 | 2024-03-25 | 34.135 mi |
| Registration #6 | 2024-03-25 | 34.135 mi |
| Registration #7 | 2024-03-25 | 34.135 mi |
| Registration #8 | 2024-03-25 | 34.135 mi |

More info >



Safety ratings

| | |
|----------------|---------------------------------|
| NCAP rating | ★★★★★ |
| Adult | 92% |
| Children | 77% |
| Pedestrian | 66% |
| Safety systems | 81% |
| Overall rating | 83% |
| Video | see crash video |



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1840 mm |
| Height | 1450 mm |
| Length | 4865 mm |
| Wheel base | 2830 mm |
| Kerb weight | 1405 kg |
| Max. allowed weight | 2055 kg |

Additional information

| | |
|--------------------|------------------|
| Fuel tank capacity | 62 l |
| Fuel delivery | Direct Injection |
| Number of doors | 4 |
| Number of seats | 5 |
| Engine number | SH 30803742 |