



RENAULT



report date: 2024-03-29

General information

Make	RENAULT
Model	GRAND SCENIC DYNAMIQUE DCI 106 G/SCENIC
Colour	Silver
Year of manufacture	-
Top speed	111 mph
0 - 60 mph	12.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	106 BHP
Max. torque	240 Nm at 2.000 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	44.1 mpg
Consumption extra urban	57.6 mpg
Consumption combined	52.3 mpg





Internet history

Entry 1

Date	2022-01-15
Pictures	1
Listing price	<a href="#">View report</a>



source: [cargurus.co.uk](http://cargurus.co.uk)

**MOT history****MOT #22**

2024-02-20 09:09

**MOT test number**

408901256779

**Result****✗ Failed**

- Fail** Nearside Rear Wheel bearing rough when rotated (5.1.3 (b) (i))
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Both headlamp starting to mist up
- Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))
- Advice** Service reminder on
- Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- Advice** Nearside Front washer jet weak

**MOT #21**

2023-02-23 12:24

**MOT test number**

124070498092

**Result****✓ Passed**

- Advice** Nearside Front Play in steering rack inner joint(s)
- Advice** Offside Front Play in steering rack inner joint(s)
- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

**MOT #20**

2023-02-23 09:34

**MOT test number**

849579497231

**Result****✗ Failed****Fail** Nearside Front Direction indicator incorrect colour (4.4.3 (a))**Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))**Fail** Nearside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Advice** Offside Front Play in steering rack inner joint(s)**Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))**Fail** Offside Front Direction indicator incorrect colour (4.4.3 (a))**Advice** Nearside Front Play in steering rack inner joint(s)**Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))**MOT #19**

2022-02-25 09:37

**MOT test number**

457558160706

**Result****✓ Passed****MOT #18**

2021-02-04 10:28

**MOT test number**

807222108538

**Result****✓ Passed****Advice** Nearside Front Play in steering rack inner joint(s)**MOT #17**

2021-02-03 11:30

**MOT test number**

116224698111

**Result****✗ Failed****Advice** Nearside Front Play in steering rack inner joint(s)**Fail** Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))

**MOT #16** 2020-01-27 16:42**MOT test number** 239036589957**Result** ✓ Passed**MOT #15** 2020-01-27 16:42**MOT test number** 793785168059**Result** ✗ Failed**Pass with rectification** Offside Front Position lamp missing (4.2.1 (a) (ii))**Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a) (ii))**MOT #14** 2019-02-01 16:19**MOT test number** 625555632746**Result** ✓ Passed**MOT #13** 2018-01-30 08:15**MOT test number** 756174080754**Result** ✓ Passed**Advice** Offside Front Brake disc inner surface corroded.**MOT #12** 2018-01-29 11:26**MOT test number** 833890395325**Result** ✗ Failed**Fail** Offside Front position lamp(s) not working (1.1.A.3b)**Fail** Nearside Rear Brake pipe excessively corroded (3.6.B.2c)**Fail** Nearside Registration plate lamp not working (1.1.C.1d)**Advice** Offside Front Brake disc inner surface corroded.

**MOT #11** 2017-01-31 12:29**MOT test number** 109008161570**Result** ✓ Passed**MOT #10** 2016-02-08 12:40**MOT test number** 200543462187**Result** ✓ Passed**Advice** Offside Rear Stop lamp has light sources not illuminating, but not more than 50% (1.2.1b)**Advice** Offside Rear Rear position lamp(s) has light sources not illuminating, but not more than 50% (1.1.A.3b)**MOT #9** 2016-02-08 10:28**MOT test number** 211788702402**Result** ✗ Failed**Fail** Nearside Front Front position lamp(s) not working (1.1.A.3b)**Advice** Offside Rear Stop lamp has light sources not illuminating, but not more than 50% (1.2.1b)**Advice** Offside Rear Rear position lamp(s) has light sources not illuminating, but not more than 50% (1.1.A.3b)**MOT #8** 2015-02-04 14:40**MOT test number** 436595835084**Result** ✓ Passed**MOT #7** 2015-02-04 11:41**MOT test number** 179965135460**Result** ✗ Failed**Fail** Offside Front position lamp(s) not working (1.1.A.3b)**Fail** Offside Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

**MOT #6** 2014-01-28 14:42**MOT test number** 739958324088**Result** ✓ Passed**MOT #5** 2014-01-28 11:26**MOT test number** 916248524056**Result** ✗ Failed**Advice** Nearside Obligatory mirror damaged, but not seriously affecting the rear view (8.1.2a)**Fail** Nearside Front position lamp(s) not working (1.1.A.3b)**MOT #4** 2013-02-14 11:27**MOT test number** 507445743027**Result** ✓ Passed**MOT #3** 2012-02-16 14:58**MOT test number** 616207842060**Result** ✓ Passed**MOT #2** 2011-02-09 12:34**MOT test number** 678610641043**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Rear rear brake grabbing slightly (3.7.A.5b)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #1** 2010-03-22 15:09**MOT test number** 882181680013**Result** ✓ Passed



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	 
Plate since	2024-03-29
Current registration	 
Plate since	2024-03-29

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	RENAULT	2024
Date of agreement	RENAULT	2024
Agreement type	RENAULT	2024
Agreement term	RENAULT	2024
Agreement number	RENAULT	2024
Contact info	RENAULT	2024

More info >



Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2007-03-22
Last registration	2024-02-20
Complete history	<a href="#">See info</a>



Registration #1	2007-03-22	28 mi
Registration #2	2010-03-22	23.887 mi
Registration #3	2011-02-09	28.787 mi
Registration #4	2012-02-16	35.016 mi
Registration #5	2013-02-14	40.910 mi
Registration #6	2014-01-28	48.391 mi
Registration #7	2014-01-28	48.391 mi
Registration #8	2015-02-04	53.879 mi
Registration #9	2015-02-04	53.879 mi
Registration #10	2016-02-08	58.327 mi
Registration #11	2016-02-08	58.327 mi
Registration #12	2017-01-31	62.620 mi
Registration #13	2018-01-20	66.913 mi
Registration #14	2018-01-20	66.913 mi
Registration #15	2019-01-17	71.206 mi
Registration #16	2019-01-17	71.206 mi
Registration #17	2020-01-15	75.499 mi
Registration #18	2020-01-15	75.499 mi
Registration #19	2021-01-12	79.792 mi
Registration #20	2021-01-12	79.792 mi
Registration #21	2022-01-10	84.085 mi
Registration #22	2022-01-10	84.085 mi
Registration #23	2023-01-07	88.378 mi
Registration #24	2024-02-20	92.671 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2087 mm
Height	1636 mm
Length	4493 mm
Wheel base	2736 mm
Kerb weight	1490 kg
Max. allowed weight	2198 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Engine number	D278159
---------------	---------