



RENAULT

LSIOCFN

report date: 2024-03-28

General information

Make	RENAULT
Model	TRAFIC LL29 STANDARD DCI 115
Colour	White
Year of manufacture	-
Top speed	93 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	115 BHP
Max. torque	300 Nm at 1.500 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	32.8 mpg
Consumption extra urban	47.9 mpg
Consumption combined	40.9 mpg





Internet history

Entry 1

Date	2021-06-08
Pictures	6
Listing price	View report



source: autotrader.co.uk



MOT history

MOT #16	2023-07-03 14:00
MOT test number	359211014693
Result	✓ Passed
Next expiry date	2024-07-02
Advice	Nearside Rear Seat belt slightly damaged (7.1.2 (b) (i))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Rear Service brake imbalance requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (b) (i))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))

MOT #15	2023-06-16 16:07
MOT test number	377214226673
Result	✗ Failed
Advice	Nearside Rear Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))
Fail	Central Rear Seat belt missing (7.1.2 (a))
Advice	Nearside Front Service brake binding but not excessively (1.2.1 (f))
Advice	Oil leak, but not excessive engine (8.4.1 (a) (i))
Fail	Rear Other passenger door likely to open inadvertently or not remain closed (6.2.3 (b) (ii))
Fail	Offside Front Macpherson strut top bush or bearing has excessive wear or free play (5.3.4 (a) (i))
Advice	Offside Front Suspension arm pin or bush worn but not resulting in excessive movement front bush (5.3.4 (a) (i))
Advice	Coolant leak
Advice	Oil leak, but not excessive transmission (8.4.1 (a) (i))

MOT #14	2022-06-01 14:17
MOT test number	726387203062
Result	✓ Passed

**MOT #13** 2022-06-01 14:17**MOT test number** 593552884322**Result** ✗ Failed**Pass with rectification** Offside Front Position lamp not working (4.2.1 (a) (ii))**MOT #12** 2020-09-22 16:28**MOT test number** 147306759563**Result** ✓ Passed**MOT #11** 2019-10-10 11:31**MOT test number** 898820035360**Result** ✓ Passed**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Central Rear Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))**Advice** Seat belt webbing slightly damaged or frayed Central row nearside of vehicle close to excessive (7.1.2 (b) (ii))**Advice** Central row nearside of vehicle foldable seat has movement when locked upright

**MOT #10**

2019-10-10 09:23

MOT test number

684389252782

Result

✗ Failed

Advice Seat belt webbing slightly damaged or frayed Central row nearside of vehicle close to excessive (7.1.2 (b) (ii))

Fail Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))

Advice Central Rear Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))

Advice Central row nearside of vehicle foldable seat has movement when locked upright

Pass with rectification Nearside Headlamp aim too low (4.1.2 (a))

Fail Offside Front Headlamp aim not tested (4.1.2 (b))

Fail Offside Front Position lamp not working (4.2.1 (a) (ii))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Minor Hazard warning switch faulty (4.4.2 (a) (i))

Fail Parking brake efficiency below requirements (1.4.2 (a) (i))

Fail Offside Rear Parking brake inoperative on one side (1.4.1 (a))

MOT #9

2018-10-12 15:09

MOT test number

221587530636

Result

✓ Passed

MOT #8

2018-10-11 11:13

MOT test number

463619266306

Result

✗ Failed

Fail Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Fail Offside Parking brake inoperative on one side (1.4.1 (a))

Fail Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))

Fail Nearside Parking brake inoperative on one side (1.4.1 (a))

**MOT #7** 2017-10-04 12:30**MOT test number** 775968009751**Result** ✓ Passed**MOT #6** 2016-07-26 14:28**MOT test number** 838121474936**Result** ✓ Passed**MOT #5** 2015-07-29 16:59**MOT test number** 535130815203**Result** ✓ Passed**MOT #4** 2015-07-29 12:19**MOT test number** 399350215225**Result** ✗ Failed**Fail** Front Brakes imbalanced across an axle (3.7.B.5b)**MOT #3** 2014-07-22 16:27**MOT test number** 798263004223**Result** ✓ Passed**Notice** N/s/r and o/s/r seat belts slight damage**MOT #2** 2013-07-24 12:15**MOT test number** 668155703201**Result** ✓ Passed**MOT #1** 2012-08-29 16:41**MOT test number** 599322542203**Result** ✓ Passed



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-06-29
Current registration	*****
Plate since	2019-06-29

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	RENAULT	2024
Date of agreement	RENAULT	2024
Agreement type	RENAULT	2024
Agreement term	RENAULT	2024
Agreement number	RENAULT	2024
Contact info	RENAULT	2024

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2010-04-12
Last registration	2023-07-03
Complete history	See info



Registration #1	2010-04-12	13 mi
Registration #2	2012-08-29	23.835 mi
Registration #3	2013-07-24	34.163 mi
Registration #4	2014-07-22	44.179 mi
Registration #5	2015-07-29	51.516 mi
Registration #6	2015-07-29	51.528 mi
Registration #7	2016-07-26	58.101 mi
Registration #8	2017-10-04	65.098 mi
Registration #9	2018-10-11	67.155 mi
Registration #10	2019-05-29	75.277 mi
Registration #11	2019-05-29	75.277 mi
Registration #12	2019-05-29	75.277 mi
Registration #13	2019-05-29	75.277 mi
Registration #14	2019-05-29	75.277 mi
Registration #15	2019-05-29	75.277 mi
Registration #16	2019-05-29	75.277 mi
Registration #17	2019-05-29	75.277 mi
Registration #18	2019-05-29	75.277 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1904 mm
Height	1954 mm
Length	5182 mm
Kerb weight	1907 kg
Max. allowed weight	3040 kg

Additional information

Fuel tank capacity	90 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	9
Number of axles	2
Engine number	C022157