



report date: 2024-03-29

General information

Make	FIAT
Model	TIPO MULTIJET EASY PLUS
Colour	Black
Year of manufacture	2017
Top speed	124 mph
0 - 60 mph	9.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	118 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	64.2 mpg
Consumption extra urban	85.6 mpg
Consumption combined	76.4 mpg
CO2 emission	98 g/km
CO2 label	A






Internet history

Entry 1

Date	2022-06-26
Pictures	12
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-07-21
MOT pass rate	71 %
MOT passed	5
Failed MOT tests	2
Total advice items	7
Total items failed	5

MOT #7	2023-07-20 14:38
MOT test number	520679523001
Result	✓ Passed
Next expiry date	2024-07-21

MOT #6	2023-07-19 12:19
MOT test number	442981847135

Result	✗ Failed
--------	----------

- Fail** Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h))
- Advice** Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))
- Fail** Nearside Windscreen washer provides insufficient washer liquid (3.5 (a))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge on inner edge and close to limit (5.2.3 (e))
- Fail** Nearside Outer Track rod end ball joint has excessive play (2.1.3 (b) (i))
- Fail** Offside Windscreen washer provides insufficient washer liquid (3.5 (a))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge on inner edge and close to limit (5.2.3 (e))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing perishing and cracking (5.2.3 (d) (ii))

MOT #5	2022-07-22 12:41
MOT test number	536074042786
Result	✓ Passed

**MOT #4** 2022-07-22 07:03**MOT test number** 437064830393**Result** ✗ Failed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Windscreen washer provides insufficient washer liquid (3.5 (a))**MOT #3** 2022-02-23 11:41**MOT test number** 879842009258**Result** ✓ Passed**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #2** 2021-02-19 10:42**MOT test number** 106002516702**Result** ✓ Passed**MOT #1** 2020-02-21 10:01**MOT test number** 240832064342**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
21 July 2024

Tax status	Valid until 1 July
Days left	62
MOT expiry date	21 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	WN17BVX
Plate since	2019-09-29
Current registration	WN17BVX
Plate since	2019-09-29

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2017-03-03
Last registration	2023-07-20
Complete history	See info



Registration #1	2017-03-03	15 mi
Registration #2	2020-02-21	25.708 mi
Registration #3	2021-02-19	33.014 mi
Registration #4	2022-02-23	41.795 mi
Registration #5	2023-07-20	41.795 mi
Registration #6	2023-07-20	41.795 mi
Registration #7	2023-07-20	41.795 mi
Registration #8	2023-07-20	41.795 mi
Registration #9	2023-07-20	41.795 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★☆
Adult	82%
Children	60%
Pedestrian	62%
Safety systems	57%
Overall rating	68%
Video	see crash video



Copyright © 2016 Euro NCAP

Dimensions & weight

Width	1792 mm
Height	1495 mm
Length	4368 mm
Wheel base	2638 mm
Kerb weight	1370 kg
Max. allowed weight	1795 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	7973051