



report date: 2024-03-29

General information

Make	VOLVO
Model	V50 D DRIVE SE LUX
Colour	Blue
Year of manufacture	2011
Top speed	118 mph
0 - 60 mph	10.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	109 BHP
Max. torque	240 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	57.7 mpg
Consumption extra urban	83.1 mpg
Consumption combined	72.4 mpg
CO2 emission	99 g/km
CO2 label	A





Internet history

Entry 1

Date	2021-07-21
Pictures	1
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-09-25
MOT pass rate	67 %
MOT passed	10
Failed MOT tests	5
Total advice items	28
Total items failed	16

MOT #15	2023-09-25 13:11
MOT test number	376263978067
Result	✓ Passed
Next expiry date	2024-09-25
Minor	Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge worn on inner edge (5.2.3 (e))
Advice	Offside Front Tyre worn close to legal limit/worn on edge worn on inner edge (5.2.3 (e))

MOT #14	2023-09-25 13:11
MOT test number	621431008274
Result	✗ Failed
Advice	Offside Rear Tyre worn close to legal limit/worn on edge worn on inner edge (5.2.3 (e))
Pass with rectification	Front Windscreen washer not working Pipe split (3.5 (a))
Minor	Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Advice	Offside Front Tyre worn close to legal limit/worn on edge worn on inner edge (5.2.3 (e))

**MOT #13**

2022-09-26 13:52

MOT test number

501145229320

Result

✓ Passed

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Offside Front Upper Macpherson strut pin or bush worn but not resulting in excessive movement upper bearing slightly noisy (5.3.4 (a) (i))

Advice Nearside Front Play in steering rack inner joint(s)

MOT #12

2022-09-24 12:20

MOT test number

816004032457

Result

✗ Failed

Fail Windscreen washer jets misaligned and not providing sufficient fluid to the windscreen spraying off windscreen (3.5 (a))

Fail Offside Rear Anti-roll bar linkage fractured (5.3.3 (b) (ii))

Fail Nearside Front Shock absorbers has a serious fluid leak (5.3.2 (b))

Advice Nearside Front Play in steering rack inner joint(s)

Fail Brake lever has insufficient reserve travel (1.1.2 (a))

Fail Offside Rear Position lamp not working (4.2.1 (a) (ii))

Advice Offside Front Upper Macpherson strut pin or bush worn but not resulting in excessive movement upper bearing slightly noisy (5.3.4 (a) (i))

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #11

2021-09-24 14:31

MOT test number

546342786043

Result

✓ Passed

**MOT #10**

2021-09-22 07:51

MOT test number

950391602005

Result**✗ Failed****Fail** Offside Rear Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**Fail** Nearside Front Road wheel badly distorted (5.2.2 (c) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Fail** Offside Rear Road wheel badly distorted (5.2.2 (c) (i))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Exhaust heat shield loose**MOT #9**

2020-09-09 14:17

MOT test number

613073828336

Result**✓ Passed****MOT #8**

2020-09-03 10:52

MOT test number

182377577559

Result**✗ Failed****Fail** Tyre has a cut in excess of the requirements deep enough to reach the ply or cords n/s/r (5.2.3 (d) (i))**Fail** Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt n/s/f inner cv boot (6.1.7 (g) (ii))**Fail** Tyre has a cut in excess of the requirements deep enough to reach the ply or cords 205/50/r17 (5.2.3 (d) (i))

**MOT #7** 2019-08-05 12:01**MOT test number** 709701484147**Result** ✓ Passed**MOT #6** 2018-09-03 09:43**MOT test number** 727563619514**Result** ✓ Passed**Advice** Some damage to heat shield by fuel tank**MOT #5** 2018-08-23 09:18**MOT test number** 258464634682**Result** ✗ Failed**Fail** Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt o/s/f inner drive boot (6.1.7 (g) (ii))**Minor** Registration plate lamp inoperative in the case of multiple lamps or light sources fit new bulb at time of test (4.7.1 (b) (i))**Advice** Some damage to heat shield by fuel tank**MOT #4** 2017-09-04 09:47**MOT test number** 918100217355**Result** ✓ Passed**Advice** Rear tyres bald on inner edges**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement rear (2.4.G.2)**Advice** Front tyres bald on inner edges**Advice** Offside Front Tyre worn close to the legal limit 2mm (4.1.E.1)**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement rear (2.4.G.2)



MOT #3	2016-10-20 12:21
MOT test number	953276952349
Result	✓ Passed
Advice	Nearside rear tyre worn inner edge
Advice	Front Brake pad(s) wearing thin (3.5.1g)

MOT #2	2015-10-31 10:29
MOT test number	429686550261
Result	✓ Passed

MOT #1	2014-10-13 12:43
MOT test number	636866584275
Result	✓ Passed
Notice	Near Side Front Tyre Running Low On Inner Edge..



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
25 September 2024

Tax status	Valid until 1 September
Days left	124
MOT expiry date	25 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2011-11-02
Last registration	2023-09-25
Complete history	See info



Registration #1	2011-11-02	24 mi
Registration #2	2014-10-13	26.835 mi
Registration #3	2015-10-31	39.223 mi
Registration #4	2016-10-20	51.242 mi
Registration #5	2017-09-04	63.367 mi
Registration #6	2018-08-23	75.795 mi
Registration #7	2018-09-03	76.051 mi
Registration #8	2019-08-05	86.894 mi
Registration #9	2020-09-03	96.887 mi
Registration #10	2021-09-03	106.880 mi
Registration #11	2022-09-03	116.873 mi
Registration #12	2023-09-25	126.866 mi
Registration #13	2024-03-29	136.859 mi
Registration #14	2024-03-29	146.852 mi
Registration #15	2024-03-29	156.845 mi
Registration #16	2024-03-29	166.838 mi
Registration #17	2024-03-29	176.831 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	78%
Pedestrian	26%
Safety systems	71%
Overall rating	73%
Video	see crash video



Dimensions & weight

Width	1770 mm
Height	1457 mm
Length	4522 mm
Wheel base	2640 mm
Kerb weight	1437 kg
Max. allowed weight	1900 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	1760212