



report date: 2024-03-28

## General information

Make	VAUXHALL
Model	AGILA DESIGN
Colour	Blue
Year of manufacture	2010
Top speed	106 mph
0 - 60 mph	14.2 seconds
Gearbox	5 speed automatic

## Engine & fuel consumption

Power	79 BHP
Max. torque	114 Nm at 4.400 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	36.2 mpg
Consumption extra urban	57.6 mpg
Consumption combined	47.9 mpg
CO2 emission	142 g/km
CO2 label	F






Internet history

Entry 1

Date	2021-10-27
Pictures	18
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-08-31
MOT pass rate	65 %
MOT passed	11
Failed MOT tests	6
Total advice items	29
Total items failed	12

MOT #17	2023-08-24 09:50
MOT test number	333532761849
Result	✓ Passed
Next expiry date	2024-08-31

MOT #16	2022-08-31 09:16
MOT test number	739249930684
Result	✓ Passed
Advice	Parking brake lever defective but can be satisfactorily operated Travel (1.1.6 (d))
Advice	Macpherson strut pin or bush worn but not resulting in excessive movement Both front upper (5.3.4 (a) (i))
Advice	Brake disc worn, pitted or scored, but not seriously weakened Both front (1.1.14 (a) (ii))
Advice	Coil spring corroded Both front (5.3.1 (b) (i))

**MOT #15**

2022-08-31 09:16

**MOT test number**

829146998383

**Result****✗ Failed**

- Advice** Coil spring corroded Both front (5.3.1 (b) (i))
- Advice** Brake disc worn, pitted or scored, but not seriously weakened Both front (1.1.14 (a) (ii))
- Advice** Parking brake lever defective but can be satisfactorily operated Travel (1.1.6 (d))
- Advice** Macpherson strut pin or bush worn but not resulting in excessive movement Both front upper (5.3.4 (a) (i))
- Pass with rectification** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

**MOT #14**

2021-08-31 10:25

**MOT test number**

687422853272

**Result****✓ Passed**

- Advice** Park brake has little reserve travel and just meets performance requirements, advised to adjust the system asap
- Advice** Nearside Front Shock absorbers has a slightly worn bush top mount (5.3.2 (c))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Shock absorbers has a slightly worn bush top mount (5.3.2 (c))

**MOT #13**

2021-08-31 09:07

**MOT test number**

800402030009

**Result****✗ Failed**

- Fail** Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Shock absorbers has a slightly worn bush top mount (5.3.2 (c))
- Advice** Park brake has little reserve travel and just meets performance requirements, advised to adjust the system asap
- Fail** Offside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))
- Advice** Offside Front Shock absorbers has a slightly worn bush top mount (5.3.2 (c))

**MOT #12** 2020-09-01 11:08**MOT test number** 864780807914**Result** ✓ Passed**MOT #11** 2019-03-28 16:53**MOT test number** 135932651735**Result** ✓ Passed**MOT #10** 2019-03-28 10:54**MOT test number** 832815195334**Result** ✗ Failed**Pass with rectification** Battery insecure and likely to fall from carrier (4.13 (a) (ii))**Fail** Offside Rear Brake pipe excessively corroded (1.1.11 (c))**MOT #9** 2018-02-23 15:13**MOT test number** 252336186480**Result** ✓ Passed**MOT #8** 2018-02-23 09:28**MOT test number** 765414865408**Result** ✗ Failed**Fail** Offside rear brake binding (3.7.B.1)**Advice** Travel on hand brake**Fail** Windscreen wiper does not clear the windscreen effectively x2 (8.2.2)**Fail** Parking brake: efficiency below requirements (3.7.B.7)

**MOT #7**

2017-07-31 07:42

**MOT test number**

347434937240

**Result**

✓ Passed

**Advice** Oil leak**MOT #6**

2017-07-25 10:28

**MOT test number**

390992718897

**Result**

✗ Failed

**Advice** Front brake disc worn, pitted or scored, but not seriously weakened both sides (3.5.1i)**Fail** Offside Front Anti-roll bar linkage ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)**Advice** Offside Rear Brake pipe slightly corroded (3.6.B.2c)**Advice** Oil filter corroded**Fail** Front Brake pad(s) less than 1.5 mm thick both sides (3.5.1g)**MOT #5**

2016-08-20 10:22

**MOT test number**

624870208555

**Result**

✓ Passed

**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front tyre cracking**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Brake warning light illuminated

**MOT #4** 2016-08-19 15:05**MOT test number** 346866677197**Result** ✗ Failed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front tyre cracking**Fail** Offside Front coil spring broken (2.4.C.1a)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Brake warning light illuminated**Fail** Nearside Front coil spring broken (2.4.C.1a)**MOT #3** 2015-08-07 12:22**MOT test number** 739459815207**Result** ✓ Passed**MOT #2** 2014-02-14 14:44**MOT test number** 118545744050**Result** ✓ Passed**MOT #1** 2013-02-13 10:25**MOT test number** 179124843403**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 December 2024

✓  
**MOT**  
**Expires:**  
31 August 2024

<b>Tax status</b>	Valid until 1 December
<b>Days left</b>	216
<b>MOT expiry date</b>	31 August 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	F
<b>Single payment (12 months)</b>	£ 200,00,-
<b>Single six month payment</b>	£ 110,00,-
<b>Total payable by 12 monthly instalments</b>	£ 210,00,-





Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

XXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXX	XXXXXXXXXX
XXXXXX	XXXXXXXXXX
XXXXXXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXX	XXXXXXXXXX

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 <b>XXXXXX</b>
Plate since	2019-01-01
Current registration	 <b>XXXXXX</b>
Plate since	2019-01-01

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2010-03-01
Last registration	2023-08-24
Complete history	<a href="#">See info</a>



Registration #1	2010-03-01	17 mi
Registration #2	2013-02-13	11.477 mi
Registration #3	2014-02-14	13.136 mi
Registration #4	2015-08-07	25.756 mi
Registration #5	2016-08-19	41.308 mi
Registration #6	2016-08-20	41.308 mi
Registration #7	2017-07-25	49.248 mi
Registration #8	2017-07-31	49.290 mi
Registration #9	2018-02-23	51.261 mi
Registration #10	2018-02-23	51.265 mi
Registration #11	2019-05-20	55.277 mi
Registration #12	2019-05-20	55.277 mi
Registration #13	2019-05-20	55.277 mi
Registration #14	2019-05-20	55.277 mi
Registration #15	2019-05-20	55.277 mi
Registration #16	2019-05-20	55.277 mi
Registration #17	2019-05-20	55.277 mi
Registration #18	2019-05-20	55.277 mi
Registration #19	2019-05-20	55.277 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1932 mm
Height	1590 mm
Length	3740 mm
Wheel base	2360 mm
Kerb weight	1065 kg
Max. allowed weight	1485 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Engine number	1237765