



report date: 2024-03-29

General information

Make	CITROEN
Model	C2 CODE
Colour	Black
Year of manufacture	2008
Top speed	126 mph
0 - 60 mph	8.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	121 BHP
Max. torque	143 Nm at 3.750 rpm
Engine capacity	1.587 cc
Cylinders	4
Fuel type	Petrol
Consumption city	30.4 mpg
Consumption extra urban	52.3 mpg
Consumption combined	40.9 mpg
CO2 emission	163 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-09-13
Pictures	20
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-03-01
MOT pass rate	75 %
MOT passed	12
Failed MOT tests	4
Total advice items	36
Total items failed	11

MOT #16	2023-02-20 09:44
MOT test number	810711191001
Result	✓ Passed
Next expiry date	2024-03-01

MOT #15	2022-02-28 16:42
MOT test number	466733081345
Result	✓ Passed
Advice	Nearside Rear Road wheel slightly distorted (5.2.2 (c) (i))

MOT #14	2021-02-25 13:42
MOT test number	302424136599
Result	✓ Passed
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #13**

2020-02-25 08:34

MOT test number

823864724310

Result

✓ Passed

- Advice** Offside Rear Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e))
- Minor** Offside Front Windscreen wiper blade defective (3.4 (b) (i))

MOT #12

2020-02-22 10:59

MOT test number

946184566096

Result

✗ Failed

- Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e))
- Fail** Offside Rear Suspension component mounting prescribed area excessively corroded significantly reducing structural strength outer sill (5.3.6 (a) (i))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e))
- Minor** Offside Front Windscreen wiper blade defective (3.4 (b) (i))
- Fail** Nearside Rear Suspension component mounting prescribed area excessively corroded significantly reducing structural strength outer sill (5.3.6 (a) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e))

**MOT #11**

2019-03-01 15:27

MOT test number

524695216983

Result

✓ Passed

- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Offside Rear Inner disc shield missing
- Advice** Offside Rear Exhaust mounting defective supported by jubilee clips (6.1.2 (a))
- Advice** Engine under tray missing
- Advice** Offside Front Inner Brake disc worn, pitted or scored, but not seriously weakened pitted (1.1.14 (a) (ii))

MOT #10

2019-03-01 15:23

MOT test number

178880837329

Result

✗ Failed

- Advice** Offside Front Inner Brake disc worn, pitted or scored, but not seriously weakened pitted (1.1.14 (a) (ii))
- Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Advice** Offside Rear Exhaust mounting defective supported by jubilee clips (6.1.2 (a))
- Advice** Engine under tray missing
- Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Offside Rear Inner disc shield missing

MOT #9

2017-09-04 11:42

MOT test number

957106357623

Result

✓ Passed

- Advice** Nearside Rear Road wheel with a slightly distorted bead rim (4.2.A.1a)
- Advice** Rear exhaust bracket broken (exhaust still supported)
- Advice** Offside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)

**MOT #8**

2016-08-24 15:21

MOT test number

428211161712

Result

✓ Passed

- Advice** Nearside Rear tyre 2-3 mm in places
- Advice** Exhaust back box band heavily corroded
- Advice** Offside Rear tyre 3mm in places
- Advice** Rear discs slightly scored

MOT #7

2016-08-24 10:05

MOT test number

152004520618

Result

✗ Failed

- Advice** Offside Front disc inner face heavily corroded
- Fail** Offside front brake excessively fluctuating (3.7.B.3)
- Advice** Nearside Rear tyre 2-3 mm in places
- Fail** Offside Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)
- Advice** Exhaust back box band heavily corroded
- Advice** Rear discs slightly scored
- Fail** Exhaust emissions Lambda reading after 2nd fast idle outside specified limits (7.3.D.3)
- Fail** Nearside Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)
- Advice** Offside Rear tyre 3mm in places

MOT #6

2015-08-20 09:02

MOT test number

163128053522

Result

✓ Passed

- Advice** Both front discs corroded

**MOT #5** 2015-08-20 09:02**MOT test number** 404003507849**Result** ✗ Failed**Pass with rectification** Offside Headlamp aim too low (1.8)**Advice** Both front discs corroded**Pass with rectification** Nearside Headlamp aim too low (1.8)**MOT #4** 2014-08-20 13:59**MOT test number** 537792334252**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #3** 2013-08-27 11:53**MOT test number** 139799933225**Result** ✓ Passed**MOT #2** 2012-08-20 11:51**MOT test number** 329543932288**Result** ✓ Passed**MOT #1** 2011-08-26 11:43**MOT test number** 525758731285**Result** ✓ Passed



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-29
Current registration	
Plate since	2019-09-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2008-09-06
Last registration	2023-02-20
Complete history	See info



Registration #1	2008-09-06	28 mi
Registration #2	2011-08-26	20.055 mi
Registration #3	2012-08-20	22.563 mi
Registration #4	2013-08-27	25.010 mi
Registration #5	2014-08-20	26.944 mi
Registration #6	2015-08-20	28.391 mi
Registration #7	2015-08-20	28.391 mi
Registration #8	2016-08-24	32.722 mi
Registration #9	2016-08-24	32.722 mi
Registration #10	2016-08-24	32.722 mi
Registration #11	2016-08-24	32.722 mi
Registration #12	2016-08-24	32.722 mi
Registration #13	2016-08-24	32.722 mi
Registration #14	2016-08-24	32.722 mi
Registration #15	2016-08-24	32.722 mi
Registration #16	2016-08-24	32.722 mi
Registration #17	2016-08-24	32.722 mi
Registration #18	2016-08-24	32.722 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	1659 mm
Height	1474 mm
Length	3666 mm
Wheel base	2315 mm
Kerb weight	1084 kg
Max. allowed weight	1415 kg

Additional information

Fuel tank capacity	41 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Number of axles	2
Engine number	FX7P3373933