



report date: 2024-03-29

General information

Make	MAZDA
Model	CX-7 16V
Colour	Grey
Year of manufacture	2007
Top speed	130 mph
0 - 60 mph	8.0 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	256 BHP
Max. torque	380 Nm at 3.000 rpm
Engine capacity	2.261 cc
Cylinders	4
Fuel type	Petrol
Consumption city	20.5 mpg
Consumption extra urban	34.9 mpg
Consumption combined	27.7 mpg
CO2 emission	243 g/km
CO2 label	L





Internet history

Entry 2

Date	2022-11-13
Pictures	16
Listing price	<a href="#">View report</a>



source: [cargurus.co.uk](https://www.cargurus.co.uk)

Entry 1

Date	2022-02-24
Pictures	1
Listing price	<a href="#">View report</a>



source: [cargurus.co.uk](https://www.cargurus.co.uk)



## MOT history

MOT expiry date	2024-12-06
MOT pass rate	70 %
MOT passed	16
Failed MOT tests	7
Total advice items	31
Total items failed	10

MOT #23	2023-11-30 14:02
MOT test number	891685572670
Result	✓ Passed
Next expiry date	2024-12-06
Advice	Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm bush (5.3.4 (a) (i))
Advice	Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm bush (5.3.4 (a) (i))

MOT #22	2022-12-07 10:01
MOT test number	262918239839
Result	✓ Passed

MOT #21	2022-12-06 16:33
MOT test number	963219012119
Result	✗ Failed
Fail	Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))

MOT #20	2022-03-05 10:35
MOT test number	865807230504
Result	✓ Passed

**MOT #19**

2022-02-28 17:19

**MOT test number**

737612483797

**Result****✗ Failed**

- Fail** Emissions not tested Over filled with oil (8.2.2.2 (e))
- Fail** Brake performance not tested (1.2.1 (g))
- Fail** Nearside Front Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))
- Advice** Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))

**MOT #18**

2021-02-04 13:46

**MOT test number**

894279066300

**Result****✓ Passed**

- Advice** Steering rough on rotation
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #17**

2019-12-19 11:07

**MOT test number**

747191916575

**Result****✓ Passed**

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #16** 2018-12-11 14:26**MOT test number** 264555465378**Result** ✓ Passed

- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #15** 2018-07-12 17:03**MOT test number** 751323110465**Result** ✓ Passed

- Advice** Nearside sill slightly corroded
- Advice** Nearside Rear Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))
- Advice** Offside sill slightly corroded
- Advice** Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))

**MOT #14** 2018-07-11 16:22**MOT test number** 868954891387**Result** ✗ Failed

- Fail** Offside Front Position lamp not working (4.2.1 (a))
- Advice** Offside sill slightly corroded
- Advice** Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))
- Advice** Nearside sill slightly corroded
- Advice** Nearside Rear Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))

**MOT #13** 2017-11-13 12:20**MOT test number** 735291021941**Result** ✓ Passed**Advice** Offside Rear Tyre perished**MOT #12** 2016-11-14 14:25**MOT test number** 965064603887**Result** ✓ Passed**MOT #11** 2016-11-14 14:25**MOT test number** 515582391612**Result** ✗ Failed**Pass with rectification** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Pass with rectification** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #10** 2016-05-27 13:01**MOT test number** 851203774298**Result** ✓ Passed**MOT #9** 2016-05-25 15:37**MOT test number** 461255185739**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Front Lower Suspension arm has excessive play in a ball joint (2.4.G.2)**Advice** Nearside inner rack joint

**MOT #8** 2015-09-18 08:12**MOT test number** 968577915971**Result** ✓ Passed**Advice** N/s/f tyre wearing edges .....**Advice** Play felt at n/s & o/s/f anti roll bar links .....**MOT #7** 2014-09-02 10:29**MOT test number** 745495444288**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Notice** Engine covers fitted obscuring some components in the engine bay**Advice** Offside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #6** 2013-09-25 14:22**MOT test number** 139458763297**Result** ✓ Passed**MOT #5** 2013-09-17 11:32**MOT test number** 368030963408**Result** ✗ Failed**Fail** Offside Track rod end ball joint has excessive play (2.2.B.1f)**MOT #4** 2012-09-18 10:58**MOT test number** 825092362201**Result** ✓ Passed**Notice** Rear wiper blade split



MOT #3	2011-09-19 16:42
MOT test number	889012761206
Result	✓ Passed
MOT #2	2010-09-24 12:42
MOT test number	801147960279
Result	✓ Passed
MOT #1	2010-09-20 15:05
MOT test number	864133760208
Result	✗ Failed
Fail	Nearside Track rod end ball joint has excessive play (2.2.B.1f)





Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 March 2025

✓  
**MOT**  
**Expires:**  
6 December 2024

<b>Tax status</b>	Valid until 1 March
<b>Days left</b>	305
<b>MOT expiry date</b>	6 December 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	L
<b>Single payment (12 months)</b>	£ 675,00,-
<b>Single six month payment</b>	£ 371,25,-
<b>Total payable by 12 monthly instalments</b>	£ 708,75,-



Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this MAZDA had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MAZDA is financed.

Finance company	XXXXXXXXXX XXXX
Date of agreement	XXXXXXXXXX XXXX
Agreement type	XXXXXXXXXX XXXX
Agreement term	XXXXXXXXXX XXXX
Agreement number	XXXXXXXXXX XXXX
Contact info	XXXXXXXXXX XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	26
First mileage registration	2007-09-11
Last registration	2023-11-30
Complete history	<a href="#">See info</a>



Registration #1	2007-09-11	26 mi
Registration #2	2010-09-20	25.784 mi
Registration #3	2010-09-24	25.786 mi
Registration #4	2011-09-19	32.922 mi
Registration #5	2012-09-18	42.515 mi
Registration #6	2013-09-17	54.142 mi
Registration #7	2013-09-25	54.531 mi
Registration #8	2014-09-02	66.399 mi
Registration #9	2015-09-18	74.232 mi
Registration #10	2016-05-25	76.513 mi
Registration #11	2016-05-27	76.513 mi
Registration #12	2016-11-14	79.396 mi
Registration #13	2016-11-14	79.396 mi
Registration #14	2016-11-14	79.396 mi
Registration #15	2016-11-14	79.396 mi
Registration #16	2016-11-14	79.396 mi
Registration #17	2016-11-14	79.396 mi
Registration #18	2016-11-14	79.396 mi
Registration #19	2016-11-14	79.396 mi
Registration #20	2016-11-14	79.396 mi
Registration #21	2016-11-14	79.396 mi
Registration #22	2016-11-14	79.396 mi
Registration #23	2016-11-14	79.396 mi
Registration #24	2016-11-14	79.396 mi
Registration #25	2016-11-14	79.396 mi
Registration #26	2016-11-14	79.396 mi

**More info** >



Dimensions & weight

Width	1870 mm
Height	1645 mm
Length	4680 mm
Wheel base	2750 mm
Kerb weight	1695 kg
Max. allowed weight	2270 kg

Additional information

Fuel tank capacity	69 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	L3 20238764