



report date: 2024-03-29

General information

Make	HONDA
Model	FR-V VTEC SE
Colour	Grey
Year of manufacture	2004
Top speed	113 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	123 BHP
Max. torque	153 Nm at 4.800 rpm
Engine capacity	1.668 cc
Cylinders	4
Fuel type	Petrol
Consumption city	30.4 mpg
Consumption extra urban	43.5 mpg
Consumption combined	37.7 mpg
CO2 emission	179 g/km
CO2 label	I





Internet history

Entry 1

Date	2021-07-18
Pictures	31
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-02-07
MOT pass rate	84 %
MOT passed	16
Failed MOT tests	3
Total advice items	44
Total items failed	14

MOT #19	2023-02-08 13:42
MOT test number	151311614098
Result	✓ Passed
Next expiry date	2024-02-07
Minor	Offside Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))
Minor	Nearside Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))
Minor	Nearside Headlamp lens slightly defective (4.1.1 (b) (i))

**MOT #18**

2023-01-31 11:14

MOT test number

758283271595

Result**✗ Failed****Advice** Rear Coil spring corroded Both sides (5.3.1 (b) (i))**Minor** Front Headlamp lens slightly defective Both sides (4.1.1 (b) (i))**Fail** Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))**Fail** Nearside Front Upper Track rod end ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))**Advice** Front Brake hose has slight corrosion to ferrule Both sides (1.1.12 (f) (i))**Minor** Front Lower Suspension arm ball joint dust cover severely deteriorated Both sides (5.3.4 (b) (i))**Fail** Nearside Front Headlamp aim not tested (4.1.2 (b))**Fail** Offside Front Windscreen washer provides insufficient washer liquid (3.5 (a))**Fail** Nearside Front Shock absorbers has a serious fluid leak (5.3.2 (b))**Fail** Offside Front Upper Track rod end ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))**MOT #17**

2022-01-29 17:02

MOT test number

871176174082

Result**✓ Passed****Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened both side (1.1.14 (a) (ii))**Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Rear Suspension Component Corroded**Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #16**

2022-01-26 11:08

MOT test number

111909612538

Result**✗ Failed**

- Fail** Exhaust emissions likely to be affected by an exhaust leak (8.2.1.1 (b))
- Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Fail** Nearside Rear Anti-roll bar linkage damaged and seriously weakened (5.3.3 (b) (i))
- Fail** Exhaust silencer insecure (8.1.1 (b) (i))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened both side (1.1.14 (a) (ii))
- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Rear Suspension Component Corroded
- Fail** Offside Rear Anti-roll bar linkage damaged and seriously weakened (5.3.3 (b) (i))

MOT #15

2021-01-18 13:24

MOT test number

684798703929

Result**✓ Passed**

- Advice** Both track rod end boots deteriorated and suspension arm boot deteriorated slightly..
- Minor** Nearside Headlamp lens slightly defective (4.1.1 (b) (i))
- Advice** Slight play in rear anti roll bar links and offside front link..
- Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Minor** Offside Headlamp lens slightly defective (4.1.1 (b) (i))

**MOT #14**

2020-01-28 12:27

MOT test number

283334385067

Result

✓ Passed

- Advice** Both front tyres worn on shoulders slightly..
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))
- Advice** Nearside Rear Anti-roll bar ball joint has slight play (5.3.4 (a) (i))
- Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Both front suspension arm front bushes deteriorated slightly..
- Advice** Offside Rear Anti-roll bar ball joint has slight play (5.3.4 (a) (i))

MOT #13

2018-12-28 11:45

MOT test number

371176153763

Result

✓ Passed

- Advice** Offside Rear Anti-roll bar ball joint has slight play (5.3.4 (a) (i))
- Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement front (5.3.4 (a) (i))
- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Re call notice applies to this vehicle

**MOT #12**

2018-12-24 11:45

MOT test number

648542142433

Result

✗ Failed

Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Pass with rectification** Offside Rear Road wheel more than one fixing missing (5.2.1 (a) (ii))**Fail** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Rear tyre perishing badly**Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement front (5.3.4 (a) (i))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Pass with rectification** Offside Windscreen washer provides insufficient washer liquid (3.5 (a))**Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Re call notice applies to this vehicle**Advice** Offside Rear Anti-roll bar ball joint has slight play (5.3.4 (a) (i))**MOT #11**

2017-12-11 12:12

MOT test number

579145671858

Result

✓ Passed

Advice Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #10**

2016-12-05 09:15

MOT test number

847262396081

Result

✓ Passed

MOT #9

2015-10-06 07:22

MOT test number

673487832093

Result

✓ Passed

**MOT #8** 2014-10-07 08:13**MOT test number** 496670484233**Result** ✓ Passed**MOT #7** 2013-10-08 07:43**MOT test number** 398161083494**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #6** 2012-10-10 07:48**MOT test number** 285994382240**Result** ✓ Passed**Advice** Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #5** 2011-10-07 08:25**MOT test number** 705030881240**Result** ✓ Passed**Notice** Nail in offside rear tyre**MOT #4** 2010-10-05 13:52**MOT test number** 451578170268**Result** ✓ Passed**MOT #3** 2009-10-14 11:25**MOT test number** 671057289207**Result** ✓ Passed



MOT #2	2008-10-23 09:26
MOT test number	782047098261
Result	✓ Passed

MOT #1	2007-10-23 09:21
MOT test number	852296997201
Result	✓ Passed



Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HONDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HONDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HONDA? How many owners did this HONDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this HONDA had different number plates.

Number of plates	1
Current registration	 
Plate since	2024-03-29
Current registration	 
Plate since	2024-03-29

More info >



Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HONDA is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2004-10-27
Last registration	2023-02-08
Complete history	See info



Registration #1	2004-10-27	25 mi
Registration #2	2007-10-23	22.827 mi
Registration #3	2008-10-23	28.901 mi
Registration #4	2009-10-14	38.999 mi
Registration #5	2010-10-05	46.821 mi
Registration #6	2011-10-07	54.635 mi
Registration #7	2012-10-10	64.232 mi
Registration #8	2013-10-08	73.025 mi
Registration #9	2014-10-07	81.131 mi
Registration #10	2015-10-06	89.068 mi
Registration #11	2016-12-05	95.921 mi
Registration #12	2019-05-29	95.921 mi
Registration #13	2019-05-29	95.921 mi
Registration #14	2019-05-29	95.921 mi
Registration #15	2019-05-29	95.921 mi
Registration #16	2019-05-29	95.921 mi
Registration #17	2019-05-29	95.921 mi
Registration #18	2019-05-29	95.921 mi
Registration #19	2019-05-29	95.921 mi
Registration #20	2019-05-29	95.921 mi
Registration #21	2019-05-29	95.921 mi

More info >



Dimensions & weight

Width	1810 mm
Height	1610 mm
Length	4285 mm
Wheel base	2680 mm
Kerb weight	1397 kg
Max. allowed weight	1890 kg

Additional information

Fuel tank capacity	58 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	6
Number of axles	2
Engine number	D17A24300063