



report date: 2024-03-29

General information

Make	MINI
Model	MINI (R57) COOPER
Colour	White
Year of manufacture	2009
Top speed	123 mph
0 - 60 mph	9.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	120 BHP
Max. torque	160 Nm at 4.250 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	38.2 mpg
Consumption extra urban	60.1 mpg
Consumption combined	49.6 mpg
CO2 emission	137 g/km
CO2 label	E





Internet history

Entry 1

Date	2022-03-18
Pictures	25
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-05-08
MOT pass rate	71 %
MOT passed	12
Failed MOT tests	5
Total advice items	20
Total items failed	12

MOT #17	2023-05-09 15:39
MOT test number	202647432178
Result	✓ Passed
Next expiry date	2024-05-08

MOT #16	2022-04-05 15:36
MOT test number	705985986427
Result	✓ Passed

MOT #15	2021-10-11 12:14
MOT test number	347911312971
Result	✓ Passed

MOT #14	2021-10-04 12:51
MOT test number	651076853391

Result	✗ Failed
--------	----------

- Fail** Nearside Rear Direction indicator incorrect colour (4.4.3 (a))
- Fail** Exhaust carbon monoxide content after 2nd fast idle exceeds manufacturer's specified limits (8.2.1.2 (a))
- Fail** Horn not working (7.7 (a))
- Fail** Offside Rear Direction indicator incorrect colour (4.4.3 (a))

**MOT #13** 2020-09-25 11:09**MOT test number** 334042567361**Result** ✓ Passed**MOT #12** 2020-09-21 09:27**MOT test number** 417226534718**Result** ✗ Failed

- Fail** Horn not working (7.7 (a) (ii))
- Fail** Offside Front Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))
- Fail** Nearside Rear Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

MOT #11 2019-09-28 09:33**MOT test number** 688147155263**Result** ✓ Passed

- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Coolant leak

MOT #10 2018-09-13 14:23**MOT test number** 621301869273**Result** ✓ Passed

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #9** 2018-09-13 14:23**MOT test number** 541151063967**Result** ✗ Failed**Pass with rectification** Nearside Rear Position lamp not working (4.2.1 (a))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Pass with rectification** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))**MOT #8** 2017-09-06 13:29**MOT test number** 444090999305**Result** ✓ Passed**Advice** N/s/f brake wear indicator wire rubbing on wheel**Advice** Nearside Stop lamp has light sources not illuminating, but not more than 50% (1.2.1b)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** O/s/r tyre out of shape on inner edge**Advice** Nearside Rear position lamp(s) has light sources not illuminating, but not more than 50% (1.1.A.3b)**Advice** Tyre pressure light on

**MOT #7** 2017-09-06 13:29**MOT test number** 819649938704**Result** ✗ Failed**Pass with rectification** Windscreen washer provides insufficient washer liquid (8.2.3)**Advice** Nearside Rear position lamp(s) has light sources not illuminating, but not more than 50% (1.1.A.3b)**Advice** Tyre pressure light on**Advice** N/s/f brake wear indicator wire rubbing on wheel**Advice** Nearside Stop lamp has light sources not illuminating, but not more than 50% (1.2.1b)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** O/s/r tyre out of shape on inner edge**MOT #6** 2016-09-17 08:57**MOT test number** 853533977093**Result** ✓ Passed**MOT #5** 2015-09-12 08:08**MOT test number** 974472865219**Result** ✓ Passed**MOT #4** 2014-08-22 12:33**MOT test number** 925464334257**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2013-08-27 11:32**MOT test number** 297869333253**Result** ✓ Passed



MOT #2	2013-08-24 10:51
MOT test number	229336633203
Result	✗ Failed
<div>Fail</div> Nearside Front Tyre has a lump, caused by separation or partial failure of its structure (4.1.D.1b)	

MOT #1	2012-09-19 09:21
MOT test number	388443962245
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
8 May 2024

Tax status	Valid until 1 April
Days left	336
MOT expiry date	8 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2009-09-03
Last registration	2023-05-09
Complete history	See info



Registration #1	2009-09-03	17 mi
Registration #2	2012-09-19	17.441 mi
Registration #3	2013-08-24	22.663 mi
Registration #4	2013-08-27	22.675 mi
Registration #5	2014-08-22	25.972 mi
Registration #6	2015-09-12	31.223 mi
Registration #7	2016-09-17	39.261 mi
Registration #8	2017-09-06	46.252 mi
Registration #9	2017-09-06	46.252 mi
Registration #10	2018-09-13	54.713 mi
Registration #11	2019-05-20	55.377 mi
Registration #12	2019-05-20	55.377 mi
Registration #13	2019-05-20	55.377 mi
Registration #14	2019-05-20	55.377 mi
Registration #15	2019-05-20	55.377 mi
Registration #16	2019-05-20	55.377 mi
Registration #17	2019-05-20	55.377 mi
Registration #18	2019-05-20	55.377 mi
Registration #19	2019-05-20	55.377 mi

More info >



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1683 mm
Height	1414 mm
Length	3699 mm
Wheel base	2467 mm
Kerb weight	1165 kg
Max. allowed weight	1595 kg

Additional information

Fuel tank capacity	40 l
Fuel delivery	Multi-Point Injection
Number of doors	2

Number of seats 4

Engine number	B314I445
---------------	----------