

Ford



### General information

Make	FORD
Model	FUSION STYLE CLIMATE
Colour	Orange
Year of manufacture	2008
Top speed	102 mph
0 - 60 mph	14.5 seconds
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	79 BHP
Max. torque	124 Nm at 3.500 rpm
Engine capacity	1.388 cc
Cylinders	4
Fuel type	Petrol
Consumption city	35.3 mpg
Consumption extra urban	54.3 mpg
Consumption combined	45.6 mpg
CO2 emission	154 g/km
CO2 label	G





### MOT history

MOT expiry date	2021-06-08
MOT pass rate	73 %
MOT passed	11
Failed MOT tests	4
Total advice items	8
Total items failed	13

MOT #15	2020-06-09 10:55
MOT test number	493601872321
Result	✓ Passed
Next expiry date	2021-06-08

MOT #3	14	2020-06-09 08:49
MOT te	st number	985366506662
Result		🗙 Failed
Fail	Offside Rear fog lamp not working (4.5.1 (a) (ii))	
Fail	Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	

MOT #13	2019-07-16 11:58
MOT test number	119783369955
Result	✓ Passed
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #12	2018-08-21 12:46
MOT test number	409018660811
Result	✓ Passed



MOT #11	2018-08-21 10:25
MOT test number	899003175743
Result	🗙 Failed
Fail Nearside Stop lamp(s) not working (4.3.1 (a) (ii))	
<b>Fail</b> Offside Front Coil spring fractured or broken (5.3.1 (b) (i))	
<b>Fail</b> Offside Front fog lamp not working (4.5.1 (a) (ii))	
<b>Fail</b> Nearside Rear Wheel bearing rough when rotated (5.1.3 (b) (i))	
MOT #10	2017-09-06 09:56

MOT test	number	756856377644
Result		✓ Passed
Advice	Offside Rear Brake pipe slightly corroded (3.6.B.2c)	
Advice	Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	
Advice	Nearside Front Tyre worn close to the legal limit Outer edge (4.1.E.1)	

МОТ #9	2016-09-24 10:25
MOT test number	232245891800
Result	✓ Passed

**SD08APY** 

report date: 2024-03-29



MOT #8	2016-09-17 08:39
MOT test number	254517618076
Result	🗙 Failed
Fail Offside Front Steering rack gaiter split (2.2.D.2d)	
Advice Rear high level brake light inoperative	
Fail Nearside Rear Rear wheel bearing rough when rotated (2.6.1)	
Fail Nearside Front Steering rack gaiter split (2.2.D.2d)	
Fail Offside Rear Stop lamp not working (1.2.1b)	
Fail Offside Front Shock absorber has a serious fluid leak (2.7.3)	

MOT #7	2015-10-15 08:43
MOT test number	309077932006
Result	✓ Passed
<b>Advice</b> Offside Front Front constant velocity joint gaiter damaged, but pr (2.5.C.1a)	reventing the ingress of dirt

MOT #6	2014-10-28 14:27
MOT test number	205551404361
Result	✓ Passed
MOT #5	2014-04-01 14:46
MOT test number	156201494426
Result	✓ Passed
MOT #4	2013-04-03 12:32

	2013 04 03 12.32
MOT test number	159143493409
Result	✓ Passed

**SD08APY** 

report date: 2024-03-29





MOT #3	2012-04-04 16:42
MOT test number	609405392075
Result	✓ Passed
MOT #2	2012-04-03 12:09
MOT test number	915654792068
Result	🗙 Failed
Fail Power steering component(s) leaking (2.3.3b)	
Fail Power steering fluid level below minimum (2.3.1)	
MOT #1	2011-02-07 09:34
MOT test number	659498031096
Result	✓ Passed

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

X Untaxed Tax expired: 31 January 2021	X MOT Expired: 8 June 2021
Tax status	Expired at 31 January 2021
Days left	1184 days too late
MOT expiry date	8 June 2021
Full MOT history	See MOT history
Tax calculation	

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-





#### Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1		
Date	F	
Category		ARME
Туре		
Damage 2		AMPLE
	E E	
Date		\$
Category	AMP	
Туре	No. Contraction of the second se	

#### Extra FORD salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info  $\rightarrow$ 





#### Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4

More info  $\rightarrow$ 





### Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	
***********	
********	
*******	
***********	
********	
	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	
	More info >





#### Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info  $\rightarrow$ 



SD08APY report date: 2024-03-29

# Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2008-03-31
Last registration	2020-06-09
Complete history	See info



Registration #1	2008-03-31	21 mi
Registration #2	2011-02-07	13.529 mi
Registration #3	2012-04-03	23.089 mi
Registration #4	2012-04-04	23.089 mi
Registration #5	2013-04-03	31.052 mi
Registration #6	2014-04-01	39.529 mi
Registration #7	2014-10-28	45.318 mi
Registration #8	2015-10-15	52.431 mi
Registration #9		11.777 mi
Registration #10		11.777 esi
Registration #11		11.777 mi
Registration #12		11.777 esi
Registration #13		11.777 mi
Registration #14		11.777 esi
Registration #15		11.777 mi
Registration #16		

More info >





### Car features

S0225	Air conditioning
\$0295	
S0482	
\$0501	
S0566	
S0567	
S0569	

# Safety ratings

**NCAP** rating

Video

see crash video



Dimensions & weight	
Width	1963 mm
Height	1543 mm
Length	4013 mm
Wheel base	2485 mm
Kerb weight	1199 kg
Max. allowed weight	1605 kg
Additional information	
Fuel tank capacity	45 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 12/12

Number of axles	2
Engine number	8A48618