





report date: 2024-03-28

General information

Make	MERCEDES
Model	SL SL500
Colour	Blue
Year of manufacture	1998
Top speed	155 mph
Gearbox	4 speed automatic

Engine & fuel consumption

Power	235 BHP
Max. torque	636 Nm at 3.900 rpm
Engine capacity	4.973 cc
Cylinders	8
Fuel type	Petrol



CarCheck.co.uk page 1/14



Internet history

Entry 1

Date 2021-02-02

Pictures 10

Listing price <u>View report</u>









source: autoonline.co.uk

CarCheck.co.uk page 2/14



MACE	history
MOL	nictory

MOT expiry date	2024-09-24
MOT pass rate	77 %
MOT passed	17
Failed MOT tests	5
Total advice items	26
Total items failed	14

MOT #22	2023-09-25 13:17
MOT test number	347054924970
Result	✓ Passed
Next expiry date	2024-09-24

MOT #21	2022-04-29 13:22
MOT test number	352707056096
Result	✓ Passed

MOT #20	2021-06-24 14:27
MOT test number	195057835377
Result	✓ Passed

CarCheck.co.uk page 3/14



Advice

(d) (i))

R995JBJ

report date: 2024-03-28

MOT #19 2019-11-13 15:36 851006704173 **MOT** test number ✓ Passed Result **Advice** Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords on inner wall (5.2.3 (d) (i)) **Advice** Wheel bearing has slight play both front (5.1.3 (a) (i)) Rear Fuel Pipe/s corroded **Advice** Minor Nearside Front Side repeater lens defective which has no effect on emitted light missing (4.4.1 (b) (i)) **Advice** Brake disc worn, pitted or scored, but not seriously weakened both sets on inner face (1.1.14 (a) (ii)) Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c)) **Advice**

Nearside Front Tyre has a cut but not deep enough to reach the ply or cords on outer wall (5.2.3

MOT #18	2019-11-13 11:19
MOT test number	609183049673
Result	X Failed
Advice Rear Fuel Pipe/s corroded	
Minor Nearside Front Side repeater lens defective which has no effect on emitted (i))	red light missing (4.4.1 (b)
Advice Nearside Rear Tyre has a cut but not deep enough to reach the ply or co	ords on inner wall (5.2.3 (d)
Advice Brake disc worn, pitted or scored, but not seriously weakened both sets (ii))	s on inner face (1.1.14 (a)
Advice Wheel bearing has slight play both front (5.1.3 (a) (i))	
Fail Headlamp aim too high both (4.1.2 (a))	
Advice Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice Nearside Front Tyre has a cut but not deep enough to reach the ply or c (d) (i))	cords on outer wall (5.2.3
Fail Nearside Front Side repeater incorrect colour (4.4.3 (a))	

CarCheck.co.uk page 4/14



report date: 2024-03-28

MOT #17 2018-10-30 13:20

MOT test number 259194535630

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Advice Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #16 2017-11-21 15:17

MOT test number 125843805020

Result

Passed

MOT #15 2016-11-21 17:24

MOT test number 223615437881

Advice Exhaust has a minor leak of exhaust gases rear silencer has corrosion . center silencer loose internal part (7.1.2)

MOT #14 2016-11-16 16:05

MOT test number 599272262394

Result X Failed

Fail Offside Front Anti-roll bar linkage cracked (2.4.G.1)

Advice Exhaust has a minor leak of exhaust gases rear silencer has corrosion . center silencer loose internal part (7.1.2)

MOT #13 2015-11-27 14:09

MOT test number 262710813594

Result ✓ Passed

CarCheck.co.uk page 5/14



Fail

R995JBJ

report date: 2024-03-28

MOT #12 2015-11-18 15:11 338394488800 **MOT** test number Result × Failed Fail Offside Rear Direction indicator adversely affected by the operation of another lamp (1.4.A.2h) Fail Offside Rear position lamp(s) adversely affected by the operation of another lamp (1.1.A.3f) Fail Service brake: efficiency below requirements (3.7.B.7) Front brake application uneven (3.7.B.2) Fail Fail Nearside Front Brake pad(s) less than 1.5 mm thick (3.5.1g) Fail Offside Rear fog lamp not working (1.3.2b) Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i) **Advice** Fail Supplementary Restraint System warning lamp indicates a fault (5.4.2) **Advice** O/s front tyre low on pressure

MOT #11	2014-10-06 15:22
MOT test number	936449574285
Result	✓ Passed
Notice Oil leak	

Brake pedal has insufficient reserve movement (3.3.A.5)

MOT #10	2013-09-30 09:52
MOT test number	878303973226
Result	√ Passed

MOT #9	2012-09-10 12:58
MOT test number	495374052252
Result	✓ Passed
Notice Oil leak	

CarCheck.co.uk page 6/14



MOT #8	2011-06-30 14:12
MOT test number	517681481186
Result	✓ Passed
MOT #7	2010-06-14 16:46
MOT test number	924155860114
Result	✓ Passed
Notice High level stop light not working	
Notice Centre exhaust bracket cracked	

MOT #6	2010-06-10 16:37
MOT test number	121401560145
Result	X Failed
Notice Centre exhaust bracket cracked	
Fail Offside Front Tyre(s) incorrect because different size tyres are fitted on the s	ame axle. (4.1.A.1a)
Notice High level stop light not working	
Fail Nearside Stop lamp not working (1.2.1b)	

MOT #5	2009-07-16 09:48
MOT test number	842717499171
Result	✓ Passed
MOT #4	2008-07-08 15:44
MOT test number	732360098114
Result	✓ Passed
MOT #3	2007-07-13 15:20
MOT test number	842384097184
Result	✓ Passed

CarCheck.co.uk page 7/14



report date: 2024-03-28

 MOT #2
 2006-06-26 16:11

 MOT test number
 901497376101

 Result
 ✓ Passed

 MOT #1
 2006-06-26 09:46

 MOT test number
 662547176123

 Result
 X Failed

 Fail

 Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

CarCheck.co.uk page 8/14



report date: 2024-03-28

Tax & MOT check





Tax status Expired at 5 October 2020

Days left 1302 days too late

MOT expiry date 24 September 2024

Full MOT history See MOT history

CarCheck.co.uk page 9/14



report date: 2024-03-28

Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report <u>here</u> for the results.

Damage 1

Date	
Category	
Туре	
Damage 2	
Date	



Extra MERCEDES salvage check



Category

Type

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 10/14



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many ow MERCEDES have? Check it in the premium report and see all owner registrations. Downlo <u>here</u> .	

Plate changes	More info >
See in this check if this MERCEDES had different number plates.	
Number of plates	,
Current registration	OK SIE
Plate since	
Current registration	UK SIR
Plate since	
	More info >

CarCheck.co.uk page 11/14



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MERCEDES is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Courts at info	

Contact info

More info >

CarCheck.co.uk page 12/14



Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	1998-12-31
Last registration	2023-09-25
Complete history	See info



Registration #1	1998-12-31	19 mi
Registration #2	2006-06-26	92.155 mi
Registration #3	2006-06-26	92.175 mi
Registration #4	2007-07-13	96.703 mi
Registration #5	2008-07-08	100.725 mi
Registration #6	2009-07-16	104.826 mi
Registration #7	2010-06-10	106.843 mi
Registration #8	2010-06-14	106.843 mi
Registration #9	2011-06-30	110.170 mi
Registration #10	2012-09-10	113.298 mi
Registration #11	2013-09-30	115.738 mi
	00111000	117 602
Registration #12	2014-10-06	117.682 mi
Registration #12 Registration #13	2014-10-06	117.682 MI
Registration #13		
Registration #13 Registration #14		
Registration #13 Registration #14 Registration #15		
Registration #13 Registration #14 Registration #15 Registration #16		
Registration #13 Registration #14 Registration #15 Registration #16 Registration #17		
Registration #13 Registration #14 Registration #15 Registration #16 Registration #17 Registration #18		
Registration #13 Registration #14 Registration #15 Registration #16 Registration #17 Registration #18 Registration #19		
Registration #13 Registration #14 Registration #15 Registration #16 Registration #17 Registration #18 Registration #19 Registration #20		
Registration #13 Registration #14 Registration #15 Registration #16 Registration #17 Registration #18 Registration #19 Registration #20 Registration #21		

More info >

page 13/14 CarCheck.co.uk



Additional information

Number of axles	2
Engine number	11998222013532

CarCheck.co.uk page 14/14