





report date: 2024-03-28

General information

Make	MINI
Model	MINI COOPER S CLUBMAN
Colour	White
Year of manufacture	2008
Top speed	139 mph
0 - 60 mph	7.6 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	175 BHP
Max. torque	240 Nm at 5.000 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	35.3 mpg
Consumption extra urban	53.3 mpg
Consumption combined	44.8 mpg
CO2 emission	150 g/km
CO2 label	F



CarCheck.co.uk page 1/14



Internet history


Entry 1

Date 2021-08-28

Pictures 20

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/14



MOT history

MOT expiry date	2024-06-14
MOT pass rate	73 %
MOT passed	11
Failed MOT tests	4
Total advice items	21
Total items failed	10

MOT #15	2023-05-31 08:59
MOT test number	469707248931
Result	✓ Passed
Next expiry date	2024-06-14
Advice Front Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. 28% n/s low (1.2.1 (b) (i))	

MOT #14	2023-05-31 08:59
MOT test number	773988829427
Result	★ Failed
Pass with rectification	Nearside Headlamp not working on main beam (4.1.1 (a) (ii))
Advice Front Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. 28% n/s low (1.2.1 (b) (i))	
Pass with rectification	Windscreen washer not working (3.5 (a))
Pass with rectification	Offside Headlamp not working on main beam (4.1.1 (a) (ii))

MOT #13	2022-06-15 13:51
MOT test number	770021918568
Result	✓ Passed

CarCheck.co.uk page 3/14



MOT #12 2021-08-10 07:43

MOT test number 437281469439

Result X Failed

Fail Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Fail Front Brakes imbalanced across an axle Axle 1 (1.2.1 (b) (i))

Fail Offside Front Position lamp not working (4.2.1 (a) (ii))

Advice Brake warning lamp on dash

Advice Offside Rear Service brake binding but not excessively (1.2.1 (f))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened Both sides (1.1.14 (a) (ii))

Fail Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))

MOT #11 2019-07-11 15:55

MOT test number 508390173983

Result

Passed

Advice Front Brake pad(s) wearing thin 70% worn (1.1.13 (a) (ii))

Minor Brake warning device malfunctioning or defective (1.1.4 (a) (i))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

CarCheck.co.uk page 4/14



MOT #10 2019-07-11 09:16 682724825451 **MOT** test number Result × Failed Fail Driver's airbag obviously inoperative (7.1.5 (c)) **Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) Minor Brake warning device malfunctioning or defective (1.1.4 (a) (i)) Fail Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h)) Front Brake pad(s) wearing thin 70% worn (1.1.13 (a) (ii)) **Advice**

MOT #9

MOT test number

968111543570

Result

Advice Oil leak

Advice Wiper blades smearing screen

Advice Corrosion to rear brake discs

MOT #8

MOT test number

756100190830

Result

Advice Oil leak

Advice Nail in o/s/r tyre

Advice Corrosion to rear brake discs

CarCheck.co.uk page 5/14



MOT #7

MOT test number

Result

Advice Slight play in both front wishbones, Rear bushes

Advice Nail in offside rear tyre

 MOT #6
 2015-06-01 11:53

 MOT test number
 549802355199

 Result
 ✓ Passed

 MOT #5
 2014-05-27 11:25

 MOT test number
 286357344185

 Result
 ✓ Passed

MOT #4 2013-06-21 15:39

MOT test number 556942673119

Result ✓ Passed

MOT #3 2013-06-14 09:36
MOT test number 358615063131

Result × Failed

Notice Child seat fitted not allowing full inspection of adult belt

Fail Offside Front Anti-roll bar linkage ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)

 MOT #2
 2012-06-14 12:30

 MOT test number
 235596162456

 Result
 ✓ Passed

CarCheck.co.uk page 6/14



MOT #1 2011-06-15 15:44

MOT test number 245816461184

CarCheck.co.uk page 7/14



Tax & MOT check



Tax status	Valid until 1 August
Days left	94
MOT expiry date	14 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-

CarCheck.co.uk page 8/14



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 10/14



Owner	history
OWITEL	HISLULY

For how long did the current and previous owner(s) have this MINI? How many owners did Check it in the premium report and see all owner registrations. Download the full report \(\frac{1}{2} \)		e?
THE STATE OF THE S		

	More info	>
Plate changes		
See in this check if this MINI had different number plates.		
Number of plates		,
Current registration	UK NE	
Plate since		
Current registration	UK NE	
Plate since		
	More info	>

CarCheck.co.uk page 11/14



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MINI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 12/14



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2008-06-20
Last registration	2023-05-31
Complete history	See info



Registration #1	2008-06-20	26 mi
Registration #2	2011-06-15	18.171 mi
Registration #3	2012-06-14	27.418 mi
Registration #4	2013-06-14	35.024 mi
Registration #5	2013-06-21	35.155 mi
Registration #6	2014-05-27	47.217 mi
Registration #7	2015-06-01	55.226 mi
Registration #8	2016-06-27	65.055 mi
Registration #9	2017-06-29	69.868 mi
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		91.777 es
Registration #16		11.777 es
Registration #17		D.277 es

More info >

CarCheck.co.uk page 13/14



Car features

50225	Air conditioning
50295	
60482	
0501	
0566	
0567	
60569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1683 mm
Height	1432 mm
Length	3958 mm
Wheel base	2547 mm
Kerb weight	1205 kg
Max. allowed weight	1690 kg

Additional information

Fuel tank capacity	50 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 14/