



HYUNDAI




report date: 2024-03-29

General information

Make	HYUNDAI
Model	I800 CRDI STYLE
Colour	Silver
Year of manufacture	2013
Top speed	112 mph
0 - 60 mph	14.4 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	168 BHP
Max. torque	440 Nm at 2.500 rpm
Engine capacity	2.497 cc
Cylinders	4
Fuel type	Diesel
Consumption city	25.2 mpg
Consumption extra urban	38.7 mpg
Consumption combined	32.1 mpg
CO2 emission	231 g/km
CO2 label	L





Internet history

Entry 2

Date	2023-04-09
Pictures	36
Listing price	View report



source: [cargurus.co.uk](#)

Entry 1

Date	2022-02-12
Pictures	44
Listing price	View report



source: [cargurus.co.uk](#)



MOT history

MOT expiry date	2025-04-06
MOT pass rate	74 %
MOT passed	14
Failed MOT tests	5
Total advice items	27
Total items failed	13

MOT #19	2024-04-02 12:42
MOT test number	495258452873
Result	✓ Passed
Next expiry date	2025-04-06

MOT #18	2023-04-07 16:00
MOT test number	981238164604
Result	✓ Passed

MOT #17	2022-02-08 11:45
MOT test number	610113618089
Result	✓ Passed

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Advice Slight travel in handbrake

Minor Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**MOT #16**

2021-07-28 15:10

MOT test number

569157973507

Result

✓ Passed

Advice Cuts to tyres**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Oil leak**Advice** Free-travel in parking brake**MOT #15**

2021-07-28 09:08

MOT test number

200285179972

Result

✗ Failed

Fail Offside Rear Tyre has ply or cords exposed Cut showing inner cord (5.2.3 (d) (ii))**Fail** Offside Front Service brake lagging in operation (1.2.1 (d))**Advice** Cuts to tyres**Fail** Offside Headlamp aim projected beam image is obviously incorrect No image (4.1.2 (c))**Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Oil leak**Fail** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))**Advice** Free-travel in parking brake**Advice** Front Inner Brake disc worn, pitted or scored, but not seriously weakened Lipped (1.1.14 (a) (ii))**MOT #14**

2020-07-29 14:09

MOT test number

968742305963

Result

✓ Passed

**MOT #13** 2020-07-29 14:09**MOT test number** 301521047133**Result** ✗ Failed**Pass with rectification** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))**MOT #12** 2020-01-23 13:51**MOT test number** 915497337774**Result** ✓ Passed**MOT #11** 2018-12-29 13:51**MOT test number** 554007916243**Result** ✓ Passed**Advice** Front Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Front Brake pad(s) wearing thin both sides (1.1.13 (a) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Rear Brake pad(s) wearing thin both sides (1.1.13 (a) (ii))**MOT #10** 2018-06-19 14:23**MOT test number** 341095874218**Result** ✓ Passed**Advice** Brake pad(s) wearing thin Both rear (1.1.13 (a) (ii))**Advice** Brake pad(s) wearing thin Both front (1.1.13 (a) (ii))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge 2.2mm (5.2.3 (e))**MOT #9** 2017-12-21 11:14**MOT test number** 340251526444**Result** ✓ Passed

**MOT #8** 2017-12-13 11:56**MOT test number** 194031270421**Result** ✗ Failed**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Nearside Headlamp aim too low and too far to the right. (1.8)**MOT #7** 2017-01-03 11:22**MOT test number** 425048992063**Result** ✓ Passed**Advice** Nearside Front wiper slightly smearing**Advice** Nearside Rear Tyre worn close to the legal limit And deteriorating (4.1.E.1)**MOT #6** 2017-01-03 11:22**MOT test number** 589772050368**Result** ✗ Failed**Pass with rectification** Offside Registration plate lamp does not illuminate simultaneously with the position lamps (1.1.C.1a)**Advice** Nearside Rear Tyre worn close to the legal limit And deteriorating (4.1.E.1)**Advice** Nearside Front wiper slightly smearing**MOT #5** 2015-08-25 16:26**MOT test number** 569057935250**Result** ✓ Passed**MOT #4** 2015-02-10 10:52**MOT test number** 679821545078**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Front Brake pad(s) wearing thin (3.5.1g)



MOT #3	2014-08-05 10:08
MOT test number	639717314227
Result	✓ Passed

MOT #2	2014-07-30 16:35
MOT test number	336481814471
Result	✗ Failed
<div><div>Fail</div>Front Windscreen washer provides insufficient washer liquid (8.2.3)</div> <div><div>Fail</div>Offside Front Headlamp aim beam image obviously incorrect (1.8.A.1b)</div> <div><div>Fail</div>Offside Registration plate lamp not working (1.1.C.1d)</div> <div><div>Fail</div>Offside Rear Rear position lamp(s) excessively damaged so that it is not visible from a reasonable distance (1.1.A.3d)</div> <div><div>Fail</div>Offside Front position lamp(s) not working (1.1.A.3b)</div>	

MOT #1	2014-01-25 09:36
MOT test number	576885124046
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
6 April 2025

Tax status	Valid until 1 April
Days left	337
MOT expiry date	6 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	L
Single payment (12 months)	£ 675,00,-
Single six month payment	£ 371,25,-
Total payable by 12 monthly instalments	£ 708,75,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	EN62LMO
Plate since	2024-03-29
Current registration	EN62LMO
Plate since	2024-03-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2013-01-18
Last registration	2024-04-02
Complete history	See info



Registration #1	2013-01-18	14 mi
Registration #2	2014-01-25	25.873 mi
Registration #3	2014-07-30	27.076 mi
Registration #4	2014-08-05	27.076 mi
Registration #5	2015-02-10	43.938 mi
Registration #6	2015-08-25	49.361 mi
Registration #7	2017-01-03	58.564 mi
Registration #8	2017-01-03	58.564 mi
Registration #9	2017-12-13	63.520 mi
Registration #10	2017-12-21	63.520 mi
Registration #11	2018-06-19	73.913 mi
Registration #12	2019-06-20	75.277 mi
Registration #13	2019-06-20	75.277 mi
Registration #14	2019-06-20	75.277 mi
Registration #15	2019-06-20	75.277 mi
Registration #16	2019-06-20	75.277 mi
Registration #17	2019-06-20	75.277 mi
Registration #18	2019-06-20	75.277 mi
Registration #19	2019-06-20	75.277 mi
Registration #20	2019-06-20	75.277 mi
Registration #21	2019-06-20	75.277 mi
Registration #22	2019-06-20	75.277 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1920 mm
Height	1925 mm
Length	5125 mm
Wheel base	3200 mm
Kerb weight	2270 kg
Max. allowed weight	3030 kg

Additional information

Fuel tank capacity	75 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	8

Engine number

D4CBD342155