



report date: 2024-03-29

General information

Make	CITROEN
Model	DS3 DSTYLE PLUS
Colour	Red
Year of manufacture	2012
Top speed	118 mph
0 - 60 mph	9.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	120 BHP
Max. torque	160 Nm at 4.200 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	29.1 mpg
Consumption extra urban	52.3 mpg
Consumption combined	40.4 mpg
CO2 emission	136 g/km
CO2 label	E







Internet history

Entry 5

Date 2023-12-12

Pictures 8




source: g3remarketing.co.uk

Entry 4

Date 2021-09-10

Pictures 30

Listing price [View report](#)




source: autotrader.co.uk

Entry 3

Date 2021-08-27

Pictures 30

Listing price [View report](#)



source: autotrader.co.uk



Entry 2

Date 2021-07-28

Pictures 30

Listing price

[View report](#)



source: [autotrader.co.uk](#)

Entry 1

Date



2021-06-08

Pictures

30

Listing price

[View report](#)



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2025-03-01
MOT pass rate	67 %
MOT passed	10
Failed MOT tests	5
Total advice items	53
Total items failed	5

MOT #15	2024-02-09 12:37
MOT test number	902042869394
Result	✓ Passed
Next expiry date	2025-03-01

MOT #14	2024-02-09 08:13
MOT test number	907591017230
Result	✗ Failed
MAJOR	Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))
Advice	Nearside Rear Nail in tyre

MOT #13	2023-02-27 09:16
MOT test number	132458993792
Result	✓ Passed

MOT #12	2023-02-27 08:10
MOT test number	779924503512
Result	✗ Failed
MAJOR	Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

**MOT #11** 2022-02-24 14:06**MOT test number** 740081723370**Result** ✓ Passed**MOT #10** 2021-02-19 09:26**MOT test number** 373949018761**Result** ✓ Passed

- Advice** Rear Exhaust mounting defective ONE OF TWO BACK EXHAUST BOX HANGING BRACKETS RUSTED OFF ,ADVISE WELD BACK ON. (6.1.2 (a))
- Advice** COOLANT BELOW MINIMUM.
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Front Service brake binding but not excessively BOTH FRONT BRAKES BINDING,ADVISE INSPECTION A.S.A.P (1.2.1 (f))

MOT #9 2020-02-19 15:29**MOT test number** 523484017208**Result** ✓ Passed

- Advice** OSF TYRE ON 3 MM & WORN LOW ON EDGES.
- Advice** Rear Exhaust mounting defective REAR EXHAUST HANGER SNAPPED OFF,ADVISE WELD BACK ON. (6.1.2 (a))
- Advice** NSR & OSF TYRES HEAVILY CRACKING ON SIDE WALLS.(195-55X16T)
- Advice** COOLANT LOW IN EXPANSION TANK.
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge NSF TYRE 4 MM & WORN LOW ON EDGES. (5.2.3 (e))
- Advice** NSR & OSF TYRE 2011 YEAR OF MANUFACTURE,ADVISE OLD & DETERIORATING.

**MOT #8**

2020-02-19 14:16

MOT test number

767005507911

Result

✗ Failed

Advice Rear Exhaust mounting defective REAR EXHAUST HANGER SNAPPED OFF,ADVISE WELD BACK ON.
(6.1.2 (a))

Advice NSR & OSF TYRES HEAVILY CRACKING ON SIDE WALLS.(195-55X16T)

Advice Front Brake disc worn, pitted or scored, but not seriously weakened FRONT BRAKE DISCS WORN
,LIPPED & CORRODED. (1.1.14 (a) (ii))

Advice COOLANT LOW IN EXPANSION TANK.

Advice Nearside Front Tyre worn close to legal limit/worn on edge NSF TYRE 4 MM & WORN LOW ON
EDGES. (5.2.3 (e))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Advice NSR & OSF TYRE 2011 YEAR OF MANUFACTURE,ADVISE OLD & DETERIORATING.

DANGEROUS Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

Advice OSF TYRE ON 3 MM & WORN LOW ON EDGES.

MOT #7

2019-02-25 15:08

MOT test number

810044638367

Result

✓ Passed

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Advice Nearside Lower NS LOWER PLASTIC SILL TRIM MISSING.

Advice Front Brake disc worn, pitted or scored, but not seriously weakened FRONT BRAKE DISCS LIPPED
& WORN. (1.1.14 (a) (ii))

Advice Front Exhaust mounting defective REAR EXHAUST BOX HANGER HAS SNAPPED OFF,ADVISE WELD
BACK ON. (6.1.2 (a))

Advice NSR & OSF TYRE 2011 YEAR OF MANUFACTURE,CRACKING ON OUTER SIDE WALL.(195-55X16T)

Advice Front Brake pad(s) wearing thin FRONT BRAKE PADS APPEAR TO BE LOW. (1.1.13 (a) (ii))

**MOT #6**

2018-02-23 16:41

MOT test number

661162926081

Result

✓ Passed

Advice NSR TYRE 2011 YEAR,PERISHING & CRACKING. 195-55X16V**Advice** FRONT BRAKE DISCS LIPPED & WORN & PADS ABOUT 60% WORN.**Advice** EXHAUST HANGER SNAPPED OFF BACK BOX.**Advice** OSF TYRE 2011 YEAR,PERISHING & CRACKING.**MOT #5**

2018-02-23 14:42

MOT test number

502209756321

Result

✗ Failed

Advice NSR TYRE 2011 YEAR,PERISHING & CRACKING. 195-55X16V**Advice** FRONT BRAKE DISCS LIPPED & WORN & PADS ABOUT 60% WORN.**Fail** Nearside Front Headlamp aim too high DONE. (1.8)**Advice** EXHAUST HANGER SNAPPED OFF BACK BOX.**Advice** OSF TYRE 2011 YEAR,PERISHING & CRACKING.**Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Offside Front Headlamp aim too high DONE. (1.8)**MOT #4**

2017-02-06 13:44

MOT test number

427342474650

Result

✓ Passed

Advice Items removed from driver's view prior to test**Advice** Exhaust mounting corroded away from exhaust**Advice** Front brake pads worn low, discs in very poor condition - worn, grooved, corroded**Advice** N/s/r tyre sidewall heavily perished/cracked

**MOT #3** 2017-02-03 15:03**MOT test number** 754320498552**Result** ✗ Failed**Fail** Rear brake application uneven (3.7.B.2)**Advice** Rear brake discs heavily corroded**Advice** N/s/r tyre sidewall heavily perished/cracked**Advice** Items removed from driver's view prior to test**Advice** Front brake pads worn low, discs in very poor condition - worn, grooved, corroded**Fail** Rear brakes release unevenly (3.7.B.4)**Advice** Exhaust mounting corroded away from exhaust**MOT #2** 2016-02-05 12:44**MOT test number** 533816888664**Result** ✓ Passed**Advice** Front brake discs grooved/corroded/worn**Advice** Items removed from driver's view**Advice** Rear brake discs corroded on inner face**Advice** N/s/r tyre sidewall perishing**MOT #1** 2015-02-27 14:02**MOT test number** 335158355093**Result** ✓ Passed**Notice** Front brake discs worn, grooved and corroded**Notice** Items removed from driver's view prior to test**Notice** Rear brake discs corroded



Tax & MOT check

✓
Taxed
Tax due:
1 May 2025

✓
MOT
Expires:
1 March 2025

Tax status	Valid until 1 May
Days left	367
MOT expiry date	1 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.


Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2012-03-01
Last registration	2024-02-09
Complete history	See info



Registration #1	2012-03-01	16 mi
Registration #2	2015-02-27	14.696 mi
Registration #3	2016-02-05	17.759 mi
Registration #4	2017-02-03	20.529 mi
Registration #5	2017-02-06	20.539 mi
Registration #6	2018-02-23	22.382 mi
Registration #7	2018-02-23	22.382 mi
Registration #8	2019-02-25	24.468 mi
Registration #9	2020-02-19	26.401 mi
Registration #10	2020-02-19	26.401 mi
Registration #11	2020-02-19	26.401 mi
Registration #12	2020-02-19	26.401 mi
Registration #13	2020-02-19	26.401 mi
Registration #14	2020-02-19	26.401 mi
Registration #15	2020-02-19	26.401 mi
Registration #16	2020-02-19	26.401 mi
Registration #17	2020-02-19	26.401 mi
Registration #18	2020-02-19	26.401 mi
Registration #19	2020-02-19	26.401 mi
Registration #20	2020-02-19	26.401 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	87%
Children	71%
Pedestrian	35%
Safety systems	83%
Overall rating	73%
Video	see crash video



Dimensions & weight

Width	1715 mm
Height	1483 mm
Length	3948 mm
Wheel base	2464 mm
Kerb weight	1147 kg
Max. allowed weight	1554 kg

Additional information

Fuel tank capacity	48 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	5
Number of axles	2
Engine number	FHCA1665093