





report date: 2024-03-28

### General information

Make	HYUNDAI
Model	IX35 CRDI PREMIUM
Colour	Silver
Year of manufacture	2010
Top speed	112 mph
0 - 60 mph	11.3 seconds
Gearbox	6 speed Manual

### Engine & fuel consumption

Power	134 BHP
Max. torque	320 Nm at 2.500 rpm
Engine capacity	1.995 cc
Cylinders	4
Fuel type	Diesel
Consumption city	41.5 mpg
Consumption extra urban	54.3 mpg
Consumption combined	48.7 mpg
CO2 emission	154 g/km
CO2 label	G



CarCheck.co.uk page 1/13



## Internet history

#### Entry 1


Date 2021-01-31

Pictures 8

Listing price <u>View report</u>









source: autoonline.co.uk

CarCheck.co.uk page 2/13



B 4	$\sim$ $-$		
10.71	$^{\prime}$	hic	torv.
101	C I	1115	IUI V
	•		tory

MOT expiry date	2024-11-05
MOT pass rate	73 %
MOT passed	11
Failed MOT tests	4
Total advice items	14
Total items failed	8

MOT #15	2023-11-06 10:42
MOT test number	452474968218
Result	✓ Passed
Next expiry date	2024-11-05

MOT #14	2023-11-02 12:08
MOT test number	649113308821
Result	<b>★</b> Failed
Fail Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))	
Advice Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Fail Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))	

MOT #13	2022-10-06 14:20
MOT test number	450396660894
Result	✓ Passed
MOT #12	2022-09-30 11:13
MOT test number	849628661192
Result	<b>X</b> Failed
Fail Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))	
Fail Parking brake efficiency below requirements (1.4.2 (a) (i))	

CarCheck.co.uk page 3/13



MOT #11

MOT test number

Fesult

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #10 2020-09-07 07:37 **MOT test number** 754565502162 Result ✓ Passed **MOT #9** 2019-09-26 07:57 **MOT** test number 427352642355 Result ✓ Passed MOT #8 2018-09-18 15:46 531024387522 **MOT** test number Result Passed **Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) **Advice** Nearside Front tyre is starting top wear faster on the inside edge. **Advice** Offside Front tyre is wearing faster on the out side edge.

MOT #7	2017-09-11 12:46
MOT test number	889658272500
Result	✓ Passed
MOT #6	2016-09-20 13:34
MOT test number	854221698175
Result	✓ Passed
Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	
Advice Noise from gearbox aera	

CarCheck.co.uk page 4/13



**Advice** 

CA60UJT report date: 2024-03-28

 MOT #5
 2015-09-11 12:51

 MOT test number
 508470110242

 Result
 ✓ Passed

 MOT #4
 2014-09-12 10:40

 MOT test number
 486695754291

 Result
 ✓ Passed

Rear Brake pad(s) wearing thin (3.5.1g)

MOT test number

Fass with rectification

Offside Headlamp aim too low (1.8)

Pass with rectification

Nearside Headlamp aim too low (1.8)

Advice

Rear Brake pad(s) wearing thin (3.5.1g)

MOT #2

MOT test number

Result

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 5/13



MOT #1 2013-09-16 11:00 **MOT test number** 925279253204 Result **X** Failed **Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1) Front Brake pad(s) wearing thin (3.5.1g) Advice Service brake: efficiency below requirements (3.7.C.1a) Fail Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1) Pass with rectification Nearside Headlamp aim too low (1.8)

CarCheck.co.uk page 6/13



## Tax & MOT check



Tax status	Valid until 1 May
Days left	2
MOT expiry date	5 November 2024
Full MOT history	See MOT history

### Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 7/13



#### Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report <a href="here">here</a> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Type	



#### Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



#### Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 9/13



$\sim$		
Owner	hictory	7
OWITCE	1113601	7

,		
For how long did the current and previous owner(s) have this HYUNDAI? How many owne have? Check it in the premium report and see all owner registrations. Download the full r		NDAI
*******		
***************************************		
	More info	>
Plate changes		
See in this check if this HYUNDAI had different number plates.		
Number of plates		,
Current registration	UK UK	
Plate since		
Current registration	UK	
Plate since		
	More info	>

CarCheck.co.uk page 10/13



#### Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

**Contact info** 

 $\quad \text{More info} \quad > \quad$ 

CarCheck.co.uk page 11/13



## Mileage check

Registration #16

Odometer	In miles
Mileage registrations	16
First mileage registration	2010-10-01
Last registration	2023-11-06
Complete history	See info



Registration #1	2010-10-01	19 mi
Registration #2	2013-09-16	39.507 mi
Registration #3	2013-09-16	39.514 mi
Registration #4	2014-09-12	51.571 mi
Registration #5	2015-09-11	63.133 mi
Registration #6	2016-09-20	74.041 mi
Registration #7	2017-09-11	89.608 mi
Registration #8	2018-09-18	102.865 mi
Registration #9		11.777 es
Registration #10		11.177 es
Registration #11		11.777 mi
Registration #12		11.777 es
Registration #13		11.777 mi
Registration #14		0.00 44
Registration #15		0.07 66

7075.75.75

More info >

77. 777 mg

CarCheck.co.uk page 12/13



## Car features

S0225	Air conditioning
S0295	
50482	
S0501	
S0566	
S0567	
S0569	

# Safety ratings

NCAP rating	****
Adult	90%
Children	88%
Pedestrian	54%
Safety systems	71%
Overall rating	81%
Video	see crash video



# Dimensions & weight

Width	1820 mm
Height	1670 mm
Length	4410 mm
Wheel base	2640 mm
Kerb weight	1679 kg
Max. allowed weight	2140 kg

## Additional information

Fuel tank capacity	58 I	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5	page 13/13

Number of axles 2

**Engine number** D4HAAU191364