





report date: 2024-03-29

General information

Make	VOLVO
Model	S40 D S S40
Colour	Silver
Year of manufacture	2005
Top speed	118 mph
0 - 60 mph	11.4 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	110 BHP
Max. torque	240 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	45.6 mpg
Consumption extra urban	67.3 mpg
Consumption combined	57.7 mpg
CO2 emission	129 g/km
CO2 label	D



CarCheck.co.uk page 1/13



Internet history

Entry 1

Date	2021-10-19
Pictures	1
Listing price	View report



source: autotrader.co.uk

CarCheck.co.uk page 2/13



B 4	\sim $-$		
10.71	$^{\prime}$	hic	tory
101	C I	1115	I OI V
	•		,

MOT expiry date	2024-11-28
MOT pass rate	89 %
MOT passed	16
Failed MOT tests	2
Total advice items	8
Total items failed	1

MOT #18	2023-11-24 09:13
MOT test number	115894286149
Result	✓ Passed
Next expiry date	2024-11-28
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #17	2022-11-29 13:40
MOT test number	219127096676
Result	✓ Passed

MOT #16	2021-11-26 12:39
MOT test number	463035068511
Result	✓ Passed

MOT #15	2021-01-12 15:23

MOT test number 379137481302

Result
✓ Passed

Minor Nearside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

CarCheck.co.uk page 3/13



MOT #14 2021-01-12 14:07

MOT test number 673655167075

Result X Failed

Minor Nearside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

MAJOR Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

MOT #13 2020-02-17 10:56

MOT test number 602268879392

Result ✓ Passed

MOT #12 2019-01-16 10:47

MOT test number 486193530812

Result ✓ Passed

MOT #11 2018-01-03 12:54

MOT test number 277473872735

Result ✓ Passed

MOT #10 2017-01-09 13:17

MOT test number 589440138899

Result

Passed

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #9 2016-01-12 11:52

MOT test number 894838691208

Result \rightarrow Passed

CarCheck.co.uk page 4/13



LT55WCL

report date: 2024-03-29

MOT #8	2015-01-08 11:09
MOT test number	316778805083
Result	✓ Passed
Notice Under-trays fitted obscuring some underside components	

MOT #7		2014-01-02 13:25
MOT test	number	365522504093
Result		✓ Passed
MOT #6		2013-01-11 16:58
MOT test	number	419561113036
Result		✓ Passed
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)	

Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)	
NOT "5		2012 01 21 12 01
MOT #5		2012-01-21 12:01
MOT test	number	927321922076
Result		✓ Passed
MOT #4		2011-01-24 13:48
MOT test	number	169484621067
Result		✓ Passed

MOT #3	2011-01-24 11:33
MOT test number	898104621014
Result	X Failed
Fail Nearside Front Coil spring not correctly located (2.4.C.2)	

CarCheck.co.uk page 5/13



MOT #2

LT55WCL report date: 2024-03-29

2010-01-18 12:45

MOT test number 480938110031

MOT #1 2009-01-13 11:52

MOT test number 183893819008

CarCheck.co.uk page 6/13



Tax & MOT check





Tax expired: 13 April 2024

Expires: 28 November 2024

Tax status	Expired at 13 April 2024
Days left	16 days too late
MOT expiry date	28 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-

CarCheck.co.uk page 7/13



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner history

e mier metery	
For how long did the current and previous owner(s) have this VOLVO? How many owners have? Check it in the premium report and see all owner registrations. Download the full	
manus .	

,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	

	More info >
Plate changes	
See in this check if this VOLVO had different number plates.	
Number of plates	,
Current registration	AIS UK
Plate since	
Current registration	NK NK
Plate since	
	More info >

CarCheck.co.uk page 10/13



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLVO is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 11/13



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2005-09-28
Last registration	2023-11-24
Complete history	See info



Registration #1	2005-09-28	7 mi
Registration #2	2009-01-13	22.651 mi
Registration #3	2010-01-18	25.042 mi
Registration #4	2011-01-24	28.767 mi
Registration #5	2011-01-24	28.767 mi
Registration #6	2012-01-21	32.753 mi
Registration #7	2013-01-11	35.097 mi
Registration #8	2014-01-02	37.108 mi
Registration #9	2015-01-08	38.896 mi
Registration #10	2016-01-12	40.090 mi
Registration #11		9.70 es
Registration #12		11.777 es
Registration #13		9.70 es
Registration #14		71.777 es
Registration #15		9.70 es
Registration #16		71.777 es
Registration #17		11.777 es
Registration #18		11.777 es
Registration #19		9.70 es
Registration #20		71.777 es

More info >

CarCheck.co.uk page 12/13



Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1770 mm
Height	1452 mm
Length	4468 mm
Wheel base	2640 mm
Kerb weight	1410 kg
Max. allowed weight	1880 kg

Additional information

Fuel tank capacity	52 l	
Fuel delivery	Direct Injection	
Number of doors	4	
Number of seats CarCheck.co.uk	5	page 13/13

Number of axles	2
Engine number	113192