



UK

SHI4KEJ

report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	POLO MATCH EDITION TDI
Colour	Silver
Year of manufacture	2014
Top speed	105 mph
0 - 60 mph	13.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	74 BHP
Max. torque	180 Nm at 2.000 rpm
Engine capacity	1.199 cc
Cylinders	3
Fuel type	Diesel
Consumption city	58.9 mpg
Consumption extra urban	83.1 mpg
Consumption combined	72.4 mpg
CO2 emission	102 g/km
CO2 label	B





MOT history

MOT expiry date	2025-04-27
MOT pass rate	73 %
MOT passed	8
Failed MOT tests	3
Total advice items	41
Total items failed	4



MOT #11	2024-04-26 13:08
MOT test number	577504175287
Result	✓ Passed
Next expiry date	2025-04-27
Advice	Offside Front Macpherson strut pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Central Front Items removed from driver's view prior to test
Advice	Nearside Rear Coil spring corroded (5.3.1 (b) (i))
Advice	Nearside Front Macpherson strut pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Central Rear exhaust back-box skin peeling
Advice	Nearside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Rear Wheel bearing has slight play (5.1.3 (a) (i))
Advice	Central Front Oil leak, but not excessive engine oil (8.4.1 (a) (i))
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #10**

2024-04-26 13:08

MOT test number

614745715938

Result**✗ Failed**

Advice Offside Front Macpherson strut pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Pass with rectification Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Nearside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Rear Coil spring corroded (5.3.1 (b) (i))

Advice Nearside Front Macpherson strut pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Pass with rectification Central Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice Central Front Items removed from driver's view prior to test

Advice Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Rear Wheel bearing has slight play (5.1.3 (a) (i))

Advice Central Front Oil leak, but not excessive engine oil (8.4.1 (a) (i))

Advice Central Rear exhaust back-box skin peeling

**MOT #9**

2023-04-28 09:48

MOT test number

117681892391

Result

✓ Passed

Advice

Nearside Front Tyre worn close to legal limit/worn on edge close to legal limit and inner edge wear (5.2.3 (e))

Advice

Offside Rear Brake pipe corroded, covered in grease or other material over axle (1.1.11 (c))

Advice

Nearside Front Tyre slightly damaged/cracking or perishing cracking between tread (5.2.3 (d) (ii))

Advice

Offside Front Suspension arm pin or bush worn but not resulting in excessive movement bottom arm rear bush deteriorated (5.3.4 (a) (i))

Advice

Offside Front Tyre worn close to legal limit/worn on edge inner edge wear (5.2.3 (e))

MOT #8

2022-04-27 12:57

MOT test number

786042701609

Result

✓ Passed

Advice

Coolant leak

MOT #7

2020-08-27 16:44

MOT test number

850891396951

Result

✓ Passed

Advice

Nearside Play in steering rack inner joint(s)

Advice

Suspension arm pin or bush worn but not resulting in excessive movement both front suspension arms rear bushes deteriorated (5.3.4 (a) (i))

MOT #6

2019-08-22 10:10

MOT test number

706493160264

Result

✓ Passed

MOT #5

2019-08-22 10:10

MOT test number

673127323301

Result

✗ Failed

Pass with rectification

Registration plate lamp inoperative in the case of a single lamp or all lamps both number plate lights not working (4.7.1 (b) (ii))

**MOT #4** 2018-08-21 13:47**MOT test number** 822701532596**Result** ✓ Passed**Advice** Front tyres perished**Advice** Rear tyres worn on edges**Advice** Front discs corroded**MOT #3** 2017-08-30 14:15**MOT test number** 737319124928**Result** ✓ Passed**MOT #2** 2017-08-29 09:23**MOT test number** 453473397162**Result** ✗ Failed**Fail** Nearside Windscreen has damage to an area in excess of a 10mm circle within zone 'A' (8.3.1a)**MOT #1** 2017-05-24 09:18**MOT test number** 470247239927**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
27 April 2025

Tax status	Valid until 1 June
Days left	32
MOT expiry date	27 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	B
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 SH14KEJ
Plate since	2020-03-29
Current registration	 SH14KEJ
Plate since	2020-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2014-05-30
Last registration	2024-04-26
Complete history	See info



Registration #1	2014-05-30	11 mi
Registration #2	2017-05-24	24.778 mi
Registration #3	2017-08-29	25.209 mi
Registration #4	2017-08-30	25.209 mi
Registration #5	2018-08-21	38.359 mi
Registration #6	2019-08-22	54.860 mi
Registration #7	2019-08-22	55.277 mi
Registration #8	2019-08-22	55.277 mi
Registration #9	2019-08-22	55.277 mi
Registration #10	2019-08-22	55.277 mi
Registration #11	2019-08-22	55.277 mi
Registration #12	2019-08-22	55.277 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	90%
Children	86%
Pedestrian	41%
Safety systems	71%
Overall rating	78%
Video	see crash video



Dimensions & weight

Width	1682 mm
Height	1462 mm
Length	3970 mm
Wheel base	2470 mm
Kerb weight	1134 kg
Max. allowed weight	1620 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Direct Injection
Number of doors	5

Number of seats	5
Engine number	CFWA427596