





report date: 2024-03-29

## General information

Make	HONDA
Model	ACCORD I-DTEC ES
Colour	Grey
Year of manufacture	2010
Top speed	132 mph
0 - 60 mph	9.4 seconds
Gearbox	6 speed Manual

## Engine & fuel consumption

Power	148 BHP
Max. torque	350 Nm at 2.000 rpm
Engine capacity	2.199 сс
Cylinders	4
Fuel type	Diesel
Consumption city	41.5 mpg
Consumption extra urban	64.2 mpg
Consumption combined	53.3 mpg
CO2 emission	147 g/km
CO2 label	F



CarCheck.co.uk page 1/12



Internet history

Entry 1

Date 2022-02-27

Pictures 8

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



MOT history

YE10FBD report date: 2024-03-29

MOT expiry date	2024-11-06
MOT pass rate	81 %
MOT passed	13
Failed MOT tests	3
Total advice items	11
Total items failed	Δ

MOT #16	2023-10-14 13:37
MOT test number	914483383900
Result	✓ Passed
Next expiry date	2024-11-06

MOT #15	2022-11-05 08:40
MOT test number	193552868487
Result	✓ Passed

MOT #14	2022-11-05 08:40
MOT test number	823314090169
Result	<b>★</b> Failed
Pass with rectification	Parking hrake lever has excessive movement indicating incorrect adjustment

Pass with rectification
Parking brake lever has excessive movement indicating incorrect adjustment
(1.1.6 (c))

MOT #13	2021-10-11 07:45
MOT test number	939353757160
Result	✓ Passed
Advice Offside Front slow to return	

MOT #12	2020-10-31 09:14
MOT test number	159431451557
Result	<b>✓</b> Passed

CarCheck.co.uk page 3/12



YE10FBD

report date: 2024-03-29

**MOT #11** 2019-11-07 17:28

**MOT test number** 941569008521

**MOT #10** 2019-05-30 10:13

**MOT test number** 486441356047

Advice Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))

**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #9 2019-05-30 10:13

**MOT test number** 850446969111

**Result** X Failed

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Pass with rectification Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

**Advice** Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))

**Pass with rectification** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MOT #8 2018-05-30 15:41

MOT test number 885197931618

Result \( \sqrt{Passed} \)

Advice Rear Anti-roll bar pin or bush worn but not resulting in excessive movement both (5.3.4 (a) (i))

MOT #7 2017-06-01 15:52

MOT test number 903062842550

Result \( \sqrt{Passed} \)

**Advice** Front both tyres wearing on inner and outer

CarCheck.co.uk page 4/12



MOT #6 2016-06-02 12:19

MOT test number 177875516429

**Result** ✓ Passed

**Advice** Rear Brake pad(s) wearing thin offside and nearside (3.5.1g)

**Advice** Front brake disc worn, pitted or scored, but not seriously weakened offside and nearside (3.5.1i)

**MOT #5** 2016-06-02 12:19

MOT test number 303851111810

**Result** X Failed

**Advice** Front brake disc worn, pitted or scored, but not seriously weakened offside and nearside (3.5.1i)

Pass with rectification Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)

**Advice** Rear Brake pad(s) wearing thin offside and nearside (3.5.1g)

MOT #4 2015-06-03 13:02

MOT test number 246204555490

MOT #3 2014-05-29 11:53

**MOT test number** 535189544194

Result 

Passed

MOT #2 2013-11-02 09:48

MOT test number 285566003335

**Result** ✓ Passed

**MOT #1** 2013-05-21 10:16

**MOT test number** 978621343120

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 August
Days left	93
MOT expiry date	6 November 2024
Full MOT history	See MOT history

## Tax calculation

Vehicle class	49
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-

CarCheck.co.uk page 6/12



YE10FBD

report date: 2024-03-29

### Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



#### Extra HONDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this HONDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



YE10FBD

report date: 2024-03-29

Owner history	
For how long did the current and previous owner(s) have this HONDA? How many owners have? Check it in the premium report and see all owner registrations. Download the full it	
*********	
***************************************	
***************************************	
***********	
***************************************	
THEFT IN THE STATE OF THE STATE	
Plate changes	More info >
See in this check if this HONDA had different number plates.	
Number of plates	
Current registration	UK UK
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 9/12



### Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HONDA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info


More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2010-05-29
Last registration	2023-10-14
Complete history	See info



Registration #1	2010-05-29	18 mi
Registration #2	2013-05-21	29.475 mi
Registration #3	2013-11-02	34.082 mi
Registration #4	2014-05-29	40.958 mi
Registration #5	2015-06-03	51.658 mi
Registration #6	2016-06-02	60.478 mi
Registration #7	2016-06-02	60.478 mi
Registration #8	2017-06-01	67.949 mi
Registration #9	2018-05-30	75.425 mi
Registration #10		11.177 es
Registration #11		11.777 es
Registration #12		11.177 es
Registration #13		11.777 es
Registration #14		11.177 es
Registration #15		11.777 es
Registration #16		11.177 es
Registration #17		11.777 es
Registration #18		111.7777 mag

More info >

CarCheck.co.uk page 11/12



# Safety ratings

NCAP rating	****
Adult	86%
Children	79%
Pedestrian	54%
Safety systems	86%
Overall rating	78%
Video	see crash video



# Dimensions & weight

Width	1840 mm
Height	1440 mm
Length	4725 mm
Wheel base	2705 mm
Kerb weight	1540 kg

## Additional information

Fuel tank capacity	65 I
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Number of axles	2
Engine number	N22B13000711

CarCheck.co.uk page 12/12