



report date: 2024-03-29

General information

Make	VOLVO
Model	XC70 D SE AWD
Colour	Green
Year of manufacture	2008
Top speed	118 mph
0 - 60 mph	10.4 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	163 BHP
Max. torque	340 Nm at 1.750 rpm
Engine capacity	2.400 cc
Cylinders	5
Fuel type	Diesel
Consumption city	25.9 mpg
Consumption extra urban	41.5 mpg
Consumption combined	34.0 mpg
CO2 emission	219 g/km
CO2 label	K





Internet history

Entry 1

Date	2021-09-12
Pictures	50
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



MOT history

MOT expiry date	2025-04-10
MOT pass rate	94 %
MOT passed	15
Failed MOT tests	1
Total advice items	8
Total items failed	2

MOT #16

2024-04-11 09:53

MOT test number

579662287501

Result

✓ Passed

Next expiry date

2025-04-10

MOT #15

2023-03-03 11:25

MOT test number

354910453938

Result

✓ Passed

Advice

Underbody rusty

Advice

Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #14

2022-02-04 17:58

MOT test number

588250460394

Result

✓ Passed

MOT #13

2021-09-10 17:57

MOT test number

737603222776

Result

✓ Passed

**MOT #12** 2021-07-28 11:28**MOT test number** 909394957498**Result** ✓ Passed**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Advice** Direction indicator slightly discoloured n/s/r and o/s/r (4.4.3 (a))**Minor** Offside Front Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))**MOT #11** 2020-07-28 08:44**MOT test number** 691405836707**Result** ✓ Passed**Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))**MOT #10** 2019-07-29 09:06**MOT test number** 911023836043**Result** ✓ Passed**MOT #9** 2018-07-23 09:28**MOT test number** 385173649532**Result** ✓ Passed**Advice** Offside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #8** 2017-06-27 08:40**MOT test number** 609438724054**Result** ✓ Passed**MOT #7** 2016-06-27 13:01**MOT test number** 782085671141**Result** ✓ Passed



<b>MOT #6</b>	2015-06-04 14:02
---------------	------------------

<b>MOT test number</b>	248905655444
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #5</b>	2014-06-30 12:45
---------------	------------------

<b>MOT test number</b>	469761684184
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #4</b>	2013-06-21 11:34
---------------	------------------

<b>MOT test number</b>	298702973476
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #3</b>	2012-07-03 09:25
---------------	------------------

<b>MOT test number</b>	826525482118
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #2</b>	2011-12-15 10:22
---------------	------------------

<b>MOT test number</b>	417199441484
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #1</b>	2011-12-13 11:03
---------------	------------------

<b>MOT test number</b>	439017241414
------------------------	--------------

<b>Result</b>	✗ Failed
---------------	----------

<b>Fail</b>	Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
-------------	--

<b>Fail</b>	Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
-------------	---



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 March 2025

✓  
**MOT**  
**Expires:**  
10 April 2025

<b>Tax status</b>	Valid until 1 March
<b>Days left</b>	306
<b>MOT expiry date</b>	10 April 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	K
<b>Single payment (12 months)</b>	£ 395,00,-
<b>Single six month payment</b>	£ 217,25,-
<b>Total payable by 12 monthly instalments</b>	£ 414,75,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >





Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2008-12-22
Last registration	2024-04-11
Complete history	<a href="#">See info</a>



Registration #1	2008-12-22	16 mi
Registration #2	2011-12-13	40.674 mi
Registration #3	2011-12-15	40.749 mi
Registration #4	2012-07-03	44.955 mi
Registration #5	2013-06-21	53.357 mi
Registration #6	2014-06-30	61.681 mi
Registration #7	2015-06-04	69.573 mi
Registration #8	2016-06-27	81.035 mi
Registration #9	2017-06-27	89.267 mi
Registration #10	2018-06-27	97.500 mi
Registration #11	2019-06-27	105.733 mi
Registration #12	2020-06-27	113.966 mi
Registration #13	2021-06-27	122.199 mi
Registration #14	2022-06-27	130.432 mi
Registration #15	2023-06-27	138.665 mi
Registration #16	2024-03-29	146.898 mi
Registration #17	2024-03-29	155.131 mi
Registration #18	2024-03-29	163.364 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2142 mm
Height	1713 mm
Length	4628 mm
Wheel base	2774 mm
Kerb weight	1862 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	660312