



report date: 2024-03-28

General information

Make	VOLVO
Model	V40 T2 R-DESIGN
Colour	Red
Year of manufacture	2017
Top speed	118 mph
0 - 60 mph	9.2 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	120 BHP
Max. torque	220 Nm at 1.100 rpm
Engine capacity	1.969 cc
Cylinders	4
Fuel type	Petrol
Consumption city	38.7 mpg
Consumption extra urban	62.8 mpg
Consumption combined	51.4 mpg
CO2 emission	127 g/km
CO2 label	D







Internet history

Entry 2

Date	2021-06-28
Pictures	19
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)

Entry 1

Date	2021-06-03
Pictures	23
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2025-03-23
MOT pass rate	83 %
MOT passed	5
Failed MOT tests	1
Total advice items	11
Total items failed	2

MOT #6	2024-03-04 16:37
MOT test number	563662755894
Result	✓ Passed
Next expiry date	2025-03-23
Advice	Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement Rear bush (5.3.4 (a) (i))
Advice	Very slight play detected in both sides of steering gear assembly.
Advice	Nearside front brake lagging in effort slightly, up to 24% lower than offside during increase and decrease checks.
Advice	Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement Rear bush (5.3.4 (a) (i))

**MOT #5** 2024-03-01 10:48**MOT test number** 105140243839**Result** ✗ Failed

**Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement  
Rear bush (5.3.4 (a) (i))

**Advice** Very slight play detected in both sides of steering gear assembly.

**Advice** Nearside Front Tyre worn close to legal limit/worn on edge Inner edge entirely bald and showing inner carcass. No plies visible. (5.2.3 (e))

**Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))

**Advice** Nearside front brake lagging in effort slightly, up to 24% lower than offside during increase and decrease checks.

**Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement  
Rear bush (5.3.4 (a) (i))

**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

**Advice** Offside Front Tyre worn close to legal limit/worn on edge Inner edge entirely bald and showing inner carcass. No plies visible. (5.2.3 (e))

**MOT #4** 2023-03-10 11:24**MOT test number** 548297479128**Result** ✓ Passed**MOT #3** 2022-03-24 10:03**MOT test number** 543073430089**Result** ✓ Passed**MOT #2** 2021-03-03 15:31**MOT test number** 488083443237**Result** ✓ Passed

**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

**MOT #1** 2020-02-28 12:10**MOT test number** 229597070236**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 July 2024

✓  
**MOT**  
**Expires:**  
23 March 2025

<b>Tax status</b>	Valid until 1 July
<b>Days left</b>	62
<b>MOT expiry date</b>	23 March 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	D
<b>Single payment (12 months)</b>	£ 150,00,-
<b>Single six month payment</b>	£ 82,50,-
<b>Total payable by 12 monthly instalments</b>	£ 157,50,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >





Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2017-02-23
Last registration	2024-03-04
Complete history	<a href="#">See info</a>



Registration #1	2017-02-23	14 mi
Registration #2	2020-02-28	43.114 mi
Registration #3	2021-03-03	51.050 mi
Registration #4	2022-03-03	51.050 mi
Registration #5	2023-03-03	51.050 mi
Registration #6	2024-03-03	51.050 mi
Registration #7	2025-03-03	51.050 mi
Registration #8	2026-03-03	51.050 mi
Registration #9	2027-03-03	51.050 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	98%
Children	75%
Pedestrian	88%
Safety systems	100%
Overall rating	92%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	2041 mm
Height	1439 mm
Length	4369 mm
Wheel base	2647 mm
Kerb weight	1457 kg
Max. allowed weight	1965 kg

Additional information

Fuel tank capacity	62 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	2032759