



report date: 2024-03-28

General information

Make	AUDI
Model	A6 TDI LE MANS EDITION
Colour	Green
Year of manufacture	2008
Top speed	136 mph
Gearbox	1 speed CVT

Engine & fuel consumption

Power	180 BHP
Max. torque	380 Nm at 1.400 rpm
Engine capacity	2.698 cc
Cylinders	6
Fuel type	Diesel
Consumption city	28.0 mpg
Consumption extra urban	48.7 mpg
Consumption combined	38.2 mpg
CO2 emission	197 g/km
CO2 label	J





Internet history

Entry 1

Date	2021-06-13
Pictures	21
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2025-01-28
MOT pass rate	65 %
MOT passed	13
Failed MOT tests	7
Total advice items	48
Total items failed	15

MOT #20	2024-01-29 11:59
MOT test number	178946684535
Result	✓ Passed
Next expiry date	2025-01-28
Advice	Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

MOT #19	2023-01-26 17:44
MOT test number	449594494671
Result	✓ Passed
Advice	Front Brake disc worn, but not excessively (1.1.14 (a) (i))

MOT #18	2023-01-25 10:59
MOT test number	899731823631
Result	✗ Failed
Fail	Offside Front Upper Suspension arm pin or bush excessively worn REAR ARM (5.3.4 (a) (i))
Fail	Nearside Rear Registration plate lamp does not illuminate simultaneously with the position lamps (4.7.2 (a))
Fail	Offside Front Upper Suspension arm pin or bush excessively worn FRONT ARM (5.3.4 (a) (i))
Advice	Front Brake disc worn, but not excessively (1.1.14 (a) (i))
Fail	Offside Rear Registration plate lamp does not illuminate simultaneously with the position lamps (4.7.2 (a))

**MOT #17** 2022-01-28 10:08**MOT test number** 879439845203**Result** ✓ Passed

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Minor Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #16 2021-01-28 16:23**MOT test number** 518528287936**Result** ✓ Passed

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Minor Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice Rear both rear shock abs dust shields adrift

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Front Upper Suspension arm pin or bush worn but not resulting in excessive movement both upper arms partly unbound split (5.3.4 (a) (i))

MOT #15 2021-01-22 13:58**MOT test number** 415206154572**Result** ✗ Failed

Fail Nearside Front Upper Suspension arm pin or bush excessively worn bush totally unbonded (5.3.4 (a) (i))

Advice Offside Front Upper Suspension arm pin or bush worn but not resulting in excessive movement both upper arms partly unbound split (5.3.4 (a) (i))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Minor Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice Nearside Front Upper Suspension arm pin or bush worn but not resulting in excessive movement partly unbound split (5.3.4 (a) (i))

Advice Rear both rear shock abs dust shields adrift

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #14** 2019-07-16 15:36**MOT test number** 319476394185**Result** ✓ Passed**Advice** Lip and corrosion on front brake discs / engine x under covers fitted / n/s/r spring corroding / slight play in front top upper arm link joints**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #13** 2019-07-16 15:19**MOT test number** 987124754540**Result** ✗ Failed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))**Advice** Lip and corrosion on front brake discs / engine x under covers fitted / n/s/r spring corroding / slight play in front top upper arm link joints**Fail** Nearside Rear Tyre has ply or cords damaged cords on outer wall (5.2.3 (d) (ii))**MOT #12** 2018-07-17 10:21**MOT test number** 243788778581**Result** ✓ Passed**Advice** Wear in front sub frame mount bushes**Advice** Engine x under covers fitted / rear heat shield loose / top arm link bushes wearing / slight lip on front discs**MOT #11** 2017-07-17 14:51**MOT test number** 412133788120**Result** ✓ Passed**Advice** Very slight play in o/s/f rear top arm joint**Advice** Eml light on**Advice** Rear heat shield loose**Advice** Engine x under covers fitted / slight lip on front discs /



MOT #10	2017-07-17 10:44
MOT test number	128403136736
Result	✗ Failed
Fail	Offside Rear Tyre has ply or cords exposed (4.1.D.1b)
Advice	Eml light on
Advice	Rear heat shield loose
Fail	Nearside Rear Tyre has ply or cords exposed 255/35/r19 96y (4.1.D.1b)
Advice	Engine x under covers fitted / slight lip on front discs /
Advice	Very slight play in o/s/f rear top arm joint

MOT #9	2016-06-21 15:05
MOT test number	812870201803
Result	✓ Passed
Advice	Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Advice	Nearside Rear Tyre side wall damaged
Advice	Child Seat fitted not allowing full inspection of adult belt
Advice	Rear Brake pad(s) wearing thin (3.5.1g)
Advice	Engine warning light on

**MOT #8** 2016-06-21 09:21**MOT test number** 292482518489**Result** ✗ Failed

- Advice** Child Seat fitted not allowing full inspection of adult belt
- Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Advice** Rear Brake pad(s) wearing thin (3.5.1g)
- Advice** Nearside Rear Tyre side wall damaged
- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Engine warning light on

MOT #7 2015-06-17 15:49**MOT test number** 696888165171**Result** ✓ Passed

- Advice** Nearside Front Anti-roll bar linkage has slight play in a pin/bush (2.4.G.2)
- Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Offside Front Anti-roll bar linkage has slight play in a pin/bush (2.4.G.2)

MOT #6 2014-02-27 14:26**MOT test number** 846078954063**Result** ✓ Passed

- Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #5** 2014-02-26 16:47**MOT test number** 696007354002**Result** ✗ Failed**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**MOT #4** 2013-02-25 17:46**MOT test number** 805646853047**Result** ✓ Passed**MOT #3** 2012-02-27 17:24**MOT test number** 335338452037**Result** ✓ Passed**MOT #2** 2011-02-02 08:55**MOT test number** 788413231038**Result** ✓ Passed**MOT #1** 2011-02-01 15:48**MOT test number** 675882831022**Result** ✗ Failed**Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
28 January 2025

Tax status	Valid until 1 June
Days left	34
MOT expiry date	28 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-




Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra AUDI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this AUDI? How many owners did this AUDI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this AUDI had different number plates.

Number of plates	1
Current registration	KK57PXR
Plate since	2019-09-28
Current registration	KK57PXR
Plate since	2019-09-28

More info >



Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this AUDI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2008-01-30
Last registration	2024-01-29
Complete history	See info



Registration #1	2008-01-30	6 mi
Registration #2	2011-02-01	69.304 mi
Registration #3	2011-02-02	69.304 mi
Registration #4	2012-02-27	80.728 mi
Registration #5	2013-02-25	82.181 mi
Registration #6	2014-02-26	86.691 mi
Registration #7	2014-02-27	86.727 mi
Registration #8	2015-06-17	105.235 mi
Registration #9	2016-06-21	116.151 mi
Registration #10	2016-06-21	116.151 mi
Registration #11	2017-07-17	127.767 mi
Registration #12	2018-06-20	131.277 mi
Registration #13	2019-06-20	131.277 mi
Registration #14	2020-06-20	131.277 mi
Registration #15	2021-06-20	131.277 mi
Registration #16	2022-06-20	131.277 mi
Registration #17	2023-06-20	131.277 mi
Registration #18	2024-01-29	131.277 mi
Registration #19	2024-01-29	131.277 mi
Registration #20	2024-01-29	131.277 mi
Registration #21	2024-01-29	131.277 mi
Registration #22	2024-01-29	131.277 mi

More info >



Car features

The AUDI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete AUDI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1855 mm
Height	1463 mm
Length	4933 mm
Wheel base	2843 mm
Kerb weight	1725 kg
Max. allowed weight	2355 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	BPP 120836