



report date: 2024-03-28

General information

Make	VOLVO
Model	S60 D2 R-DESIGN
Colour	Red
Year of manufacture	2012
Top speed	121 mph
0 - 60 mph	10.7 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	113 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	53.3 mpg
Consumption extra urban	74.3 mpg
Consumption combined	65.7 mpg
CO2 emission	114 g/km
CO2 label	C







Internet history

Entry 1

Date	2021-06-25
Pictures	11
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)



## MOT history

MOT expiry date	2024-08-30
MOT pass rate	69 %
MOT passed	9
Failed MOT tests	4
Total advice items	25
Total items failed	9

MOT #13 2023-08-16 10:04

MOT test number 621777523680

Result ✓ Passed

Next expiry date 2024-08-30

**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**Advice** Offside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))

**Advice** Nearside Front Tyre worn close to legal limit/worn on edge inner edge heavily worn (5.2.3 (e))

MOT #12 2022-08-31 13:10

MOT test number 455896907810

Result ✓ Passed

MOT #11 2022-08-30 10:22

MOT test number 468301673158

Result ✗ Failed

**Advice** Rear Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (b) (i))

**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**Fail** Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))

**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

**Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))

**MOT #10** 2021-11-22 14:33**MOT test number** 797250803267**Result** ✓ Passed**MOT #9** 2020-11-10 13:04**MOT test number** 991886004788**Result** ✓ Passed**MOT #8** 2020-11-07 11:38**MOT test number** 133121532184**Result** ✗ Failed**Fail** Nearside Front Tyre(s) of different sizes are fitted on the same axle. (5.2.3 (b))**Fail** Nearside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**MOT #7** 2019-05-20 15:11**MOT test number** 959814886822**Result** ✓ Passed**MOT #6** 2018-05-14 14:49**MOT test number** 388478171278**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit 3mm and balding Inner Edge (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit Uneven Wear across tread 3mm (4.1.E.1)**Advice** Offside Rear Lower Trailing arm rubber bush deteriorated but not resulting in excessive movement Front Bush (2.4.G.2)**Advice** Nearside Front Road wheel with a slightly distorted bead rim Inner edge (4.2.A.1a)**Advice** Offside Front Tyre worn close to the legal limit 3mm and Balding Inner Edge (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit Uneven Wear Across Tread 3mm (4.1.E.1)

**MOT #5** 2018-05-11 10:46**MOT test number** 279295484974**Result** ✗ Failed**Pass with rectification** Front Headlamp cleaning device inoperative (1.7.2)**Advice** Nearside Front Tyre worn close to the legal limit 3mm and balding Inner Edge (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit Uneven Wear across tread 3mm (4.1.E.1)**Fail** Nearside Rear Lower Trailing arm rubber bush bonding deteriorated resulting in excessive movement Front Bush (2.4.G.2)**Fail** Offside Front Lower Suspension arm has excessive play in a ball joint Outer ball joint (2.4.G.2)**Fail** Offside Front Headlamp aim too far to the right (1.8)**Advice** Nearside Front Road wheel with a slightly distorted bead rim Inner edge (4.2.A.1a)**Advice** Offside Front Tyre worn close to the legal limit 3mm and Balding Inner Edge (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit Uneven Wear Across Tread 3mm (4.1.E.1)**Advice** Offside Rear Lower Trailing arm rubber bush deteriorated but not resulting in excessive movement Front Bush (2.4.G.2)**Advice** Nearside Front Lower Suspension arm has slight play in a ball joint Outer Ball joint (2.4.G.2)**MOT #4** 2017-05-26 15:23**MOT test number** 526036710710**Result** ✓ Passed**Advice** Emission clean**MOT #3** 2016-04-08 14:20**MOT test number** 874234981275**Result** ✓ Passed**Advice** Offside front tyre worn on the inner edge**Advice** Nearside front tyre worn on the inner edge**Advice** Offside rear stepped on the inner edge



MOT #2 2015-03-16 09:45

MOT test number 887195175041

Result ✓ Passed

**Notice** Child seat fitted not allowing full inspection of adult belt

MOT #1 2015-03-16 09:45

MOT test number 168365275081

Result ✗ Failed

**Notice** Child seat fitted not allowing full inspection of adult belt

**Pass with rectification** Offside Rear Tyre has ply or cords exposed (4.1.D.1b)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 September 2024

✓  
**MOT**  
**Expires:**  
30 August 2024

<b>Tax status</b>	Valid until 1 September
<b>Days left</b>	125
<b>MOT expiry date</b>	30 August 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	C
<b>Single payment (12 months)</b>	£ 35,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	£ 36,75,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	<b>BF12DYY</b>
Plate since	2019-03-28
Current registration	<b>BF12DYY</b>
Plate since	2019-03-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2012-04-10
Last registration	2023-08-16
Complete history	<a href="#">See info</a>



Registration #1	2012-04-10	10 mi
Registration #2	2015-03-16	93.915 mi
Registration #3	2016-04-08	120.045 mi
Registration #4	2017-05-26	137.785 mi
Registration #5	2018-05-11	140.822 mi
Registration #6	2018-05-14	140.822 mi
Registration #7	2019-05-20	149.556 mi
Registration #8	2019-05-20	149.556 mi
Registration #9	2019-05-20	149.556 mi
Registration #10	2019-05-20	149.556 mi
Registration #11	2019-05-20	149.556 mi
Registration #12	2019-05-20	149.556 mi
Registration #13	2019-05-20	149.556 mi
Registration #14	2019-05-20	149.556 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	78%
Pedestrian	26%
Safety systems	71%
Overall rating	73%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1782 mm
Height	1447 mm
Length	4266 mm
Wheel base	2640 mm
Kerb weight	1359 kg
Max. allowed weight	1780 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	4

<b>Number of axles</b>	2
<b>Engine number</b>	2259719