





report date: 2024-03-29

#### General information

Make	VOLKSWAGEN
Model	EOS TDI SPORT 5 STR
Colour	Silver
Year of manufacture	2009
Top speed	122 mph
0 - 60 mph	10.6 seconds
Gearbox	6 speed Manual

### Engine & fuel consumption

Power	138 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.968 сс
Cylinders	4
Fuel type	Diesel
Consumption city	36.7 mpg
Consumption extra urban	53.3 mpg
Consumption combined	46.3 mpg
CO2 emission	159 g/km
CO2 label	G



CarCheck.co.uk page 1/12



report date: 2024-03-29

# Internet history

#### Entry 1

Date	2021-02-06	
Pictures	1	
Listing price	<u>View report</u>	



source: autoonline.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-29

B 4	$\sim$ $-$		
10.71	$^{\prime}$	hic	tory
101	C I	1115	I OI V
	•		,

MOT expiry date	2022-10-14
MOT pass rate	83 %
MOT passed	10
Failed MOT tests	2
Total advice items	14
Total items failed	4

MOT #12	2021-10-13 09:50
MOT test number	796131907142
Result	✓ Passed
Next expiry date	2022-10-14

MOT #11	2020-10-15 09:31
MOT test number	113939049258
Result	<b>✓</b> Passed

MOT #10	2019-11-27 13:26
MOT test number	743240713669
Result	<b>✓</b> Passed

MOT #9		2018-07-25 09:49
MOT test	number	124716354449
Result		✓ Passed
Advice	Emissions zero reading	
Advice	Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))	

MOT #8	2017-07-27 09:04
MOT test number	172695197012
Result	<b>✓</b> Passed

CarCheck.co.uk page 3/12



report date: 2024-03-29

MOT #7	2016-07-25 10:02
MOT test number	133150291670
Result	✓ Passed
MOT #6	2015-07-10 13:34
MOT test number	215561895172
Result	✓ Passed
MOT #5	2015-07-10 11:46
MOT test number	106261095192
Result	<b>★</b> Failed
Fail Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)	
Fail Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)	
Fail Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)	

MOT #4		2014-03-04 12:21
MOT test	number	308273464094
Result		✓ Passed
Advice	Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8	3.1d)
Notice	Both front brake discs are corroded on inner face. Only just acceptable for mot.	
Notice	Rear brake discs are starting to corrode.	
Notice	O/S/R tyre is wearing on inner edge.[slightly destorted]	

CarCheck.co.uk page 4/12



report date: 2024-03-29

MOT #3 2014-03-04 11:08

**MOT test number** 948613964006

**Result** X Failed

Advice Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

**Notice** O/S/R tyre is wearing on inner edge.[slightly destorted]

**Fail** Nearside Front Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

**Notice** Both front brake discs are corroded on inner face. Only just acceptable for mot.

**Notice** Rear brake discs are starting to corrode.

MOT #2 2013-02-26 14:53

**MOT test number** 559657153008

Result \( \sqrt{Passed} \)

**Notice** All brake discs corroding

Advice Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

**MOT #1** 2012-03-13 15:45

MOT test number 548283472049

Result J Passed

**Notice** Rear tyres worn on inner edges and slightly out of shape

**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

CarCheck.co.uk page 5/12



report date: 2024-03-29

#### Tax & MOT check



X MOT

Tax expired: 4 April 2022

Expired: 14 October 2022

Tax status	Expired at 4 April 2022
Days left	755 days too late
MOT expiry date	14 October 2022
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 6/12




report date: 2024-03-29

#### Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report <a href="here">here</a> for the results.

#### Damage 1

Date	
Category	
Туре	
Damage 2	
Date	



#### Extra VOLKSWAGEN salvage check



**Category** 

**Type** 

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-29

#### Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-29

# Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Dow here.	
***************************************	
***************************************	
***************************************	
***************************************	
***************************************	
	More info >
Plate changes	
See in this check if this VOLKSWAGEN had different number plates.	
Number of plates	,
Current registration	UK UK
Plate since	
Current registration	NK.
Plate since	
	More info >

CarCheck.co.uk page 9/12



report date: 2024-03-29

#### Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

**Contact info** 

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-29

# Mileage check

Registration #14

Odometer	In miles
Mileage registrations	14
First mileage registration	2009-03-16
Last registration	2021-10-13
Complete history	See info



Registration #1	2009-03-16	22 mi
Registration #2	2012-03-13	51.982 mi
Registration #3	2013-02-26	60.621 mi
Registration #4	2014-03-04	66.328 mi
Registration #5	2014-03-04	66.328 mi
Registration #6	2015-07-10	80.904 mi
Registration #7	2015-07-10	80.907 mi
Registration #8		71.777 es
Registration #9		11.777 es
Registration #10		71.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es

mn.n.n

More info >

77.777 au

CarCheck.co.uk page 11/12



report date: 2024-03-29

#### Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

# Safety ratings

NCAP rating	****
Video	see crash video



# Dimensions & weight

Width	2066 mm
Height	1635 mm
Length	4391 mm
Wheel base	2677 mm
Kerb weight	1561 kg
Max. allowed weight	2260 kg

#### Additional information

Fuel tank capacity	60 I
Fuel delivery	Direct Injection
Number of doors	5
CarChaeleeeule	maga 17/17

CarCheck.co.uk page 12/12

Number of seats	7
Engine number	BKD C72007