





report date: 2024-03-29

#### General information

Make	MINI
Model	ONE
Colour	Red
Year of manufacture	2017
Top speed	121 mph
0 - 60 mph	9.9 seconds
Gearbox	6 speed Manual

### Engine & fuel consumption

Power	102 BHP
Max. torque	180 Nm at 4.000 rpm
Engine capacity	1.198 сс
Cylinders	3
Fuel type	Petrol
Consumption city	49.6 mpg
Consumption extra urban	70.6 mpg
Consumption combined	61.4 mpg
CO2 emission	109 g/km
CO2 label	В



CarCheck.co.uk page 1/11



# Internet history

#### Entry 1

Date 2022-03-15

Pictures 20

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/11



MOT history

MOT expiry date	2025-03-24
MOT pass rate	86 %
MOT passed	6
Failed MOT tests	1
Total advice items	8
Total items failed	2

MOT #7		2024-03-05 10:07
MOT test	number	531485525646
Result		✓ Passed
Next expi	ry date	2025-03-24
Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))		
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

MOT #6		2024-03-05 10:07
MOT test number		982177667380
Result		<b>X</b> Failed
Pass with rectification	Nearside Front Headlamp aim too high (4.1.2 (a))	
Advice Offside Rear Tyr	e slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Pass with rectification	Offside Front Headlamp aim too high (4.1.2 (a))	
Advice Nearside Rear T	yre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

MOT #5	2023-03-07 10:12
MOT test number	865213765115
Result	✓ Passed
Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

CarCheck.co.uk page 3/11



**Advice** 

OU17NVJ report date: 2024-03-29

MOT #4 2022-03-25 16:09 **MOT test number** 991387080690 Result ✓ Passed 2022-03-03 09:26 MOT #3 **MOT test number** 685857283363 Result ✓ Passed **Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) Minor Offside Windscreen wiper blade defective (3.4 (b) (i))

MOT #2	2021-02-10 11:48
MOT test number	147091679194
Result	<b>✓</b> Passed
MOT #1	2020-02-26 16:08
MOT test number	927602511582
Result	✓ Passed

Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

CarCheck.co.uk page 4/11



## Tax & MOT check



Tax status	Valid until 1 April
Days left	336
MOT expiry date	24 March 2025
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	48
Band	В
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-

CarCheck.co.uk page 5/11



#### Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



#### Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



## Owner history

For how long did the current and provious owner(s) have this MINI2 How many owners di	d this MINI bays?
For how long did the current and previous owner(s) have this MINI? How many owners did Check it in the premium report and see all owner registrations. Download the full report \( \frac{1}{2} \)	
THE STATE OF THE S	
***************************************	
***************************************	
	More info >
Plate changes	
See in this check if this MINI had different number plates.	
Number of plates	,
Current registration	UK UK
Plate since	
Current registration	UK 215
Plate since	

CarCheck.co.uk page 8/11



#### Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MINI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Courts at info	

**Contact info** 

More info >

CarCheck.co.uk page 9/11



# Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2017-03-10
Last registration	2024-03-05
Complete history	See info



Registration #1	2017-03-10	23 mi
Registration #2	2020-02-26	15.599 mi
Registration #3	2021-02-10	18.074 mi
Registration #4	2022-03-03	21.829 mi
Registration #5		11.777 esi
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es

More info >

CarCheck.co.uk page 10/11



## Car features

S0225	Air conditioning
S0295	
50482	
50501	
S0566	
S0567	
S0569	

# Safety ratings

NCAP rating	****
Video	see crash video



# Dimensions & weight

Width	1727 mm
Height	1414 mm
Length	3821 mm
Wheel base	2495 mm
Kerb weight	1090 kg
Max. allowed weight	1570 kg

# Additional information

Fuel tank capacity	40
Fuel delivery	Direct Injection
Number of doors	3
Number of seats CarCheck.co.uk	4 page 11/1