



report date: 2024-03-28

General information

Make	VOLVO
Model	S60 D5 SPORT
Colour	Silver
Year of manufacture	-
Top speed	130 mph
0 - 60 mph	9.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	161 BHP
Max. torque	340 Nm at 1.750 rpm
Cylinders	5
Fuel type	Diesel
Consumption city	32.5 mpg
Consumption extra urban	54.3 mpg
Consumption combined	43.5 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-10-22
Pictures	0
Listing price	View report

source: [autotrader.co.uk](#)

**MOT history**

MOT #18	2022-04-13 11:43
MOT test number	113764342016
Result	✓ Passed
Next expiry date	2023-04-12
Advice	Rear Coil spring corroded both (5.3.1 (b) (i))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Front Registration plate deteriorated but not likely to be misread (0.1 (b))
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))

MOT #17	2022-04-01 12:14
MOT test number	407894885629
Result	✗ Failed
Advice	Front Registration plate deteriorated but not likely to be misread (0.1 (b))
Fail	Parking brake efficiency below requirements (1.4.2 (a) (i))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Fail	Nearside Rear Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
Advice	Rear Coil spring corroded both (5.3.1 (b) (i))
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))
Fail	Offside Parking brake inoperative on one side (1.4.1 (a))

MOT #16	2021-02-06 15:47
MOT test number	937975272465
Result	✓ Passed

MOT #15	2020-02-08 12:46
MOT test number	524504718914
Result	✓ Passed
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))



MOT #14	2019-02-09 13:16
MOT test number	232021754800
Result	✓ Passed
MOT #13	2018-02-10 12:31
MOT test number	796279494009
Result	✓ Passed
MOT #12	2017-02-11 13:11
MOT test number	601032281256
Result	✓ Passed
MOT #11	2016-02-10 15:31
MOT test number	390736961215
Result	✓ Passed
MOT #10	2015-02-10 16:41
MOT test number	449601545033
Result	✓ Passed
MOT #9	2014-02-10 12:42
MOT test number	689641044048
Result	✓ Passed
MOT #8	2013-02-14 16:44
MOT test number	537265543008
Result	✓ Passed



MOT #7	2013-02-13 17:02
MOT test number	239934143026
Result	✗ Failed
Fail	Nearside Rear Registration plate lamp not working (1.1.C.1d)
Fail	Centre Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)
Notice	Orange warning triangle on dash illuminated.
Fail	Offside Rear Registration plate lamp not working (1.1.C.1d)
Fail	Offside Inner Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)

MOT #6	2012-02-06 10:23
MOT test number	848087932030
Result	✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Rear Brake pad(s) wearing thin (3.5.1g)

MOT #5	2011-02-14 13:03
MOT test number	467765541074
Result	✓ Passed
Advice	Nearside Front Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

MOT #4	2010-07-30 16:11
MOT test number	644741810229
Result	✓ Passed

MOT #3	2009-07-29 13:11
MOT test number	923680219282
Result	✓ Passed
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)



MOT #2	2008-07-24 14:36
MOT test number	453206908298
Result	✓ Passed

MOT #1	2008-07-24 14:36
MOT test number	452466908273
Result	✗ Failed
<div>Pass with rectification</div> Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)	



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	VA05TXJ
Plate since	2024-03-28
Current registration	VA05TXJ
Plate since	2024-03-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2005-08-11
Last registration	2022-04-13
Complete history	See info



Registration #1	2005-08-11	15 mi
Registration #2	2008-07-24	28.679 mi
Registration #3	2009-07-29	36.526 mi
Registration #4	2010-07-30	44.604 mi
Registration #5	2011-02-14	48.301 mi
Registration #6	2012-02-06	75.429 mi
Registration #7	2013-02-13	104.882 mi
Registration #8	2013-02-14	104.882 mi
Registration #9	2014-02-10	108.510 mi
Registration #10	2015-02-10	122.362 mi
Registration #11	2016-02-10	136.214 mi
Registration #12	2017-02-10	150.066 mi
Registration #13	2018-02-10	163.918 mi
Registration #14	2019-02-10	177.770 mi
Registration #15	2020-02-10	191.622 mi
Registration #16	2021-02-10	205.474 mi
Registration #17	2022-02-10	219.326 mi
Registration #18	2023-02-10	233.178 mi
Registration #19	2024-02-10	247.030 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1804 mm
Height	1428 mm
Length	4576 mm
Wheel base	2715 mm
Kerb weight	1515 kg
Max. allowed weight	2030 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

Number of axles	2
Engine number	289182