



HI25YCH

report date: 2024-03-28

General information

Make	FORD
Model	ESCORT XR3I
Colour	White
Year of manufacture	1991
Top speed	115 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	105 BHP
Max. torque	at 4.800 rpm
Engine capacity	1.597 cc
Cylinders	4
Fuel type	Petrol



LABEL UNKNOWN



Internet history

Entry 2

Date	2021-08-20
Pictures	25
Listing price	<a href="#">View report</a>



source: yesauto.com

Entry 1

Date	2021-07-09
Pictures	25
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



## MOT history

MOT expiry date	2024-06-22
MOT pass rate	79 %
MOT passed	11
Failed MOT tests	3
Total advice items	10
Total items failed	15

MOT #14	2023-05-26 12:34
MOT test number	221302083911
Result	✓ Passed
Next expiry date	2024-06-22

MOT #13	2022-06-23 11:55
MOT test number	749750038597
Result	✓ Passed

MOT #12	2022-05-26 13:38
MOT test number	387311927324
Result	✗ Failed

- Fail** Offside Rear Tyre not fitted in accordance with side wall instructions (5.2.3 (i))
- Fail** Nearside Headlamp insecure (4.1.1 (c))
- Fail** Rear Position lamp not working both (4.2.1 (a) (ii))
- Fail** Steering rack gaiter missing or no longer prevents the ingress of dirt both (2.1.3 (g) (ii))
- Fail** Offside Rear Road wheel fixing missing (5.2.1 (a) (i))
- Fail** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- Fail** Stop lamp(s) not working both (4.3.1 (a) (ii))
- Fail** Exhaust system insecure (6.1.2 (a))

**MOT #11**

2015-07-01 09:36

**MOT test number**

845962385116

**Result**

✓ Passed

**Advice**

Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #10**

2015-06-20 14:25

**MOT test number**

689611575183

**Result**

✗ Failed

**Fail**

Offside Body or chassis has an unsatisfactory modification, seriously affecting its strength within 30cm of the body mountings (6.1.B.2)

**Fail**

Nearside Rear Body or chassis has excessive corrosion, seriously affecting its strength within 30cm of the body mountings (6.1.B.2)

**Fail**

Offside Front Body or chassis has an unsatisfactory modification, seriously affecting its strength within 30cm of the body mountings (6.1.B.2)

**Fail**

Offside Rear Body or chassis has an unsatisfactory modification, seriously affecting its strength within 30cm of the body mountings (6.1.B.2)

**Advice**

Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #9**

2013-06-05 18:32

**MOT test number**

267696153122

**Result**

✓ Passed

**MOT #8**

2012-05-02 14:11

**MOT test number**

556973822162

**Result**

✓ Passed

**Notice**

FRONT DISC(S) SLIGHTLY CORRODED

**Advice**

Offside Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)

**Advice**

Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive (2.4.A.3)

**Advice**

Nearside Rear Suspension component mounting prescribed area is corroded but not considered excessive (2.4.A.3)

**MOT #7** 2010-11-18 10:57**MOT test number** 982372620360**Result** ✓ Passed**Advice** Front Front constant velocity joint gaiter deteriorated (2.5.C.1a)**Advice** Rear wheel bearing has slight play (2.6.2)**MOT #6** 2009-11-20 08:34**MOT test number** 471254929386**Result** ✓ Passed**MOT #5** 2009-11-13 09:02**MOT test number** 931417219395**Result** ✗ Failed**Fail** Offside Rear wheel bearing has excessive play (2.6.2)**Fail** Windscreen washer provides insufficient washer liquid (8.2.3)**Fail** Rear Registration plate lamp not fitted (1.1.C.1b)**MOT #4** 2008-09-29 11:08**MOT test number** 642443678262**Result** ✓ Passed**MOT #3** 2007-09-10 11:16**MOT test number** 782283657288**Result** ✓ Passed**MOT #2** 2006-09-14 15:32**MOT test number** 671927256238**Result** ✓ Passed



MOT #1	2005-09-24 13:38
MOT test number	342737865407
Result	✓ Passed
Advice	Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓  
**Taxed**

**Tax due:**  
1 July 2024

✓  
**MOT**

**Expires:**  
22 June 2024

Tax status		Valid until 1 July
Days left		63
MOT expiry date		22 June 2024
Full MOT history		<a href="#">See MOT history</a>



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	1991-03-18
Last registration	2023-05-26
Complete history	<a href="#">See info</a>



Registration #1	1991-03-18	11 mi
Registration #2	2005-09-24	65.558 mi
Registration #3	2006-09-14	66.745 mi
Registration #4	2007-09-10	74.327 mi
Registration #5	2008-09-29	85.185 mi
Registration #6	2009-11-13	93.831 mi
Registration #7	2009-11-20	93.831 mi
Registration #8	2010-11-18	2.946 mi
Registration #9	2012-05-02	8.597 mi
Registration #10	2012-05-02	8.597 mi
Registration #11	2012-05-02	8.597 mi
Registration #12	2012-05-02	8.597 mi
Registration #13	2012-05-02	8.597 mi
Registration #14	2012-05-02	8.597 mi
Registration #15	2012-05-02	8.597 mi
Registration #16	2012-05-02	8.597 mi
Registration #17	2012-05-02	8.597 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1641 mm
Height	1308 mm
Length	4062 mm
Kerb weight	945 kg

Additional information

Number of doors	3
Engine number	LM71321